Received by OCD: 10/21/2025 8:41:00 AM Known Volume (dropdown):				Percentage of Oil if a Mixture	(%.)		olume of Spill (bbl.)	Total Estimated Volume of Spilled Oil (bbl.)	Total Estimated Postulated St Spilled Liquid other than Oil (bbl.)	
				~	70% oil&water mix 30% Fire-				#VALUE!	#VALUE!
		Known	Area (dropdown):		Mapped Area (sq. ft.)	Average Depth (in.)	Percentage of Oil if Spilled Fluid is a Mixture (%.)	Total Estimated Volume of Spill (bbl.)	Total Estimated Volume of Spilled Oil (bbl.)	Total Estimated Volume of Spilled Liquid other than Oil (bbl.)
				~				0.0000	0.0000	0.0000
90	500	200			Spill Calcu	lation - On-Pad	Surface Pool Spill	×	V2	
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft.)	Average Depth (in.)	Estimated <u>Pool</u> Area (sq. ft.)	Estimated volume of each pool area (bbl.)		Total Estimated Volume of Spill (bbl.)	Percentage of Oil if Spilled Fluid is a Mixture (%.)	Total Estimated Volume of Spilled Oil (bbl.)	Total Estimated Volume of Spilled Liquid other than Oil (bbl.)
Rectangle A	33	9	0.8	297.00	1.32		1.32		0.00	1.32
Rectangle B	12	8	1.0	96.00	0.57		0.57		0.00	0.57
Rectangle C 0 0 0.0		0.0	0.00	0.00		0.00		0.00	0.00	
Rectangle D			0.00	0.00		0.00		0.00	0.00	
Rectangle E				0.00	0.00		0.00		0.00	0.00
Rectangle F				0.00	0.00		0.00		0.00	0.00
Rectangle G		- 3		0.00	0.00		0.00		0.00	0.00
Rectangle H		0.00	0.00		0.00		0.00	0.00		
Rectangle I				0.00	0.00		0.00		0.00	0.00
Rectangle J				0.00	0.00		0.00		0.00	0.00
Total Volume Released to Lined Secon					ed to Lined Seconda	ry Containment:	1.8913		0.0000	1.8913

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 518469

QUESTIONS

Operator:	OGRID:
COG PRODUCTION, LLC	217955
600 W. Illinois Ave	Action Number:
Midland, TX 79701	518469
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS

Prerequisites			
Incident ID (n#)	nAPP2529058701		
Incident Name	NAPP2529058701 EIDER 35 FEDERAL 501H @ 30-025-49287		
Incident Type	Oil Release		
Incident Status	Initial C-141 Received		
Incident Well	[30-025-49287] EIDER 35 FEDERAL #501H		

Location of Release Source		
Please answer all the questions in this group.		
Site Name	Eider 35 Federal 501H	
Date Release Discovered	10/17/2025	
Surface Owner	Federal	

Incident Details			
Please answer all the questions in this group.			
Incident Type	Oil Release		
Did this release result in a fire or is the result of a fire	Yes		
Did this release result in any injuries	No		
Has this release reached or does it have a reasonable probability of reaching a watercourse	No		
Has this release endangered or does it have a reasonable probability of endangering public health	No		
Has this release substantially damaged or will it substantially damage property or the environment	No		
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No		

Nature and Volume of Release				
Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.				
Crude Oil Released (bbls) Details	Cause: Other Pipeline (Any) Crude Oil Released: 2 BBL Recovered: 0 BBL Lost: 2 BBL.			
Produced Water Released (bbls) Details	Not answered.			
Is the concentration of chloride in the produced water >10,000 mg/l	No			
Condensate Released (bbls) Details	Not answered.			
Natural Gas Vented (Mcf) Details	Not answered.			
Natural Gas Flared (Mcf) Details	Not answered.			
Other Released Details	Not answered.			
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Emergency services were notified to extinguish the fire. The release was confined to the well pad. The facility has been cleared by safety personnel.			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 518469

200-20	
	IONS (continued)
Operator: COG PRODUCTION, LLC	OGRID: 217955
600 W. Illinois Ave	Action Number:
Midland, TX 79701	518469
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)
QUESTIONS	
Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	More info needed to determine if this will be treated as a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes
Reasons why this would be considered a submission for a notification of a major release	From paragraph A. "Major release" determine using: (2) an unauthorized release of a volume that: (a) results in a fire or is the result of a fire.
With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.	e. gas only) are to be submitted on the C-129 form.
Initial Response The responsible party must undertake the following actions immediately unless they could create a s	
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	Emergency services were notified to extinguish the fire. The release was confined to the well pad. The facility has been cleared by safety personnel.
	i lation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative ted or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of evaluation in the follow-up C-141 submission.
to report and/or file certain release notifications and perform corrective actions for releathe OCD does not relieve the operator of liability should their operations have failed to	knowledge and understand that pursuant to OCD rules and regulations all operators are require ases which may endanger public health or the environment. The acceptance of a C-141 report by adequately investigate and remediate contamination that pose a threat to groundwater, surface t does not relieve the operator of responsibility for compliance with any other federal, state, or
	Name: Brittany Esparza
I hereby agree and sign off to the above statement	Title: Environmental Technician
, ,	Email: brittany.Esparza@ConocoPhillips.com Date: 10/21/2025

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 3

Action 518469

QUESTIONS (continued)

Operator:		OGRID:
	COG PRODUCTION, LLC	217955
	600 W. Illinois Ave	Action Number:
	Midland, TX 79701	518469
		Action Type:
		[C-141] Initial C-141 (C-141-v-Initial)

QUESTIONS Site Characterization Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the What is the shallowest depth to groundwater beneath the area affected by the Not answered. release in feet below ground surface (ft bgs) What method was used to determine the depth to ground water Not answered. Did this release impact groundwater or surface water Not answered What is the minimum distance, between the closest lateral extents of the release and the following surface areas: A continuously flowing watercourse or any other significant watercourse Not answered Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) Not answered. An occupied permanent residence, school, hospital, institution, or church Not answered. A spring or a private domestic fresh water well used by less than five households Not answered. for domestic or stock watering purposes Any other fresh water well or spring Not answered. Incorporated municipal boundaries or a defined municipal fresh water well field Not answered. Not answered. A subsurface mine Not answered. An (non-karst) unstable area Not answered. Categorize the risk of this well / site being in a karst geology A 100-year floodplain Not answered. Did the release impact areas not on an exploration, development, production, or Not answered. storage site

Remediation Plan				
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.				
Requesting a remediation plan approval with this submission	No			
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.				

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 518469

CONDITIONS

Operator:	OGRID:
COG PRODUCTION, LLC	217955
600 W. Illinois Ave	Action Number:
Midland, TX 79701	518469
	Action Type:
	[C-141] Initial C-141 (C-141-v-Initial)

CONDITIONS

Created By	Condition	Condition Date
scott.rodgers	None	10/21/2025