

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 547254

QUESTIONS

Operator: Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	OGRID: 328947 Action Number: 547254 Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)
---	--

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2601338190
Incident Name	NAPP2601338190 SHELBY 23 TB @ A-26-19S-25E
Incident Type	Oil Release
Incident Status	Initial C-141 Approved

Location of Release Source	
Site Name	SHELBY 23 TB
Date Release Discovered	01/12/2026
Surface Owner	Private

Liner Inspection Event Information	
<i>Please answer all the questions in this group.</i>	
What is the liner inspection surface area in square feet	9,000
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	01/30/2026
Time liner inspection will commence	02:30 PM
Please provide any information necessary for observers to liner inspection	Pima Environmental Services 619-721-4813
Please provide any information necessary for navigation to liner inspection site	32.63622,-104.44844

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 547254

CONDITIONS

Operator:	OGRID: 328947
Spur Energy Partners LLC 9655 Katy Freeway Houston, TX 77024	Action Number: 547254
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
pima	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	1/27/2026