

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 547176

**QUESTIONS**

Operator:  XTO ENERGY, INC 6401 Holiday Hill Road Midland, TX 79707	OGRID:  5380
	Action Number:  547176
	Action Type:  [NOTIFY] Notification Of Sampling (C-141N)

**QUESTIONS**

<b>Prerequisites</b>	
Incident ID (n#)	nRM1932350962
Incident Name	NRM1932350962 PLU 89 @ 30-015-27787
Incident Type	Release Other
Incident Status	Initial C-141 Approved
Incident Well	[30-015-27787] POKER LAKE UNIT #089

**Location of Release Source**

Site Name	PLU 89
Date Release Discovered	10/08/2019
Surface Owner	Federal

**Sampling Event General Information**

*Please answer all the questions in this group.*

What is the sampling surface area in square feet	3,527
What is the estimated number of samples that will be gathered	18
Sampling date pursuant to Subparagraph (a) of Paragraph (1) of Subsection D of 19.15.29.12 NMAC	02/22/2021
Time sampling will commence	08:00 AM

*Warning: Notification can not be less than two business days prior to conducting final sampling.*

Please provide any information necessary for observers to contact samplers	Tacoma Morrissey - <a href="mailto:tmorrissey@ensolum.com">tmorrissey@ensolum.com</a>
Please provide any information necessary for navigation to sampling site	Additional soil sampling activities and excavation were conducted at the Site to address the October 8, 2019, produced water and oil release. Laboratory analytical results from all samples collected from the final release extent and release area, indicated that all COC concentrations were in compliance with the Reclamation and Closure Criteria. Based on laboratory analytical results, impacted soil exceeding the Site Reclamation and Closure Criteria has been excavated and no further remediation is required at this time. The excavation was backfilled with material purchased locally and the surface recontoured to match pre-existing Site conditions. Excavation of impacted soil has mitigated impacts at this Site. Depth to groundwater is confirmed to be greater than 100 feet bgs and no other sensitive receptors were identified near the release extent. XTO believes these remedial actions are protective of human health, the environment, and groundwater.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 547176

**CONDITIONS**

Operator:  XTO ENERGY, INC 6401 Holiday Hill Road Midland, TX 79707	OGRID:  5380
	Action Number:  547176
	Action Type: [NOTIFY] Notification Of Sampling (C-141N)

**CONDITIONS**

Created By	Condition	Condition Date
kthomason01	Failure to notify the OCD of sampling events including any changes in date/time per the requirements of 19.15.29.12.D.(1).(a) NMAC, may result in the remediation closure samples not being accepted.	1/27/2026
kthomason01	If confirmation sampling is going to take place over multiple days, individual C-141N applications must be submitted for each sampling date. Date ranges are not currently accepted on the C-141N application.	1/27/2026