

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 61823

QUESTIONS

Operator: Franklin Mountain Energy LLC 44 Cook Street Denver, CO 80206	OGRID: 373910
	Action Number: 61823
	Action Type: [NOTIFY] Notification Of Release (NOR)

QUESTIONS

Location of Release Source <i>Please answer all of the questions in this group.</i>	
Site Name	Carnival CTB
Date Release Discovered	11/13/2021
Surface Owner	State

Incident Details <i>Please answer all of the questions in this group.</i>	
Incident Type	Fire
Did this release result in a fire or is the result of a fire	Yes
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

Nature and Volume of Release <i>Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.</i>	
Crude Oil Released (bbls) Details	Cause: Equipment Failure Separator Crude Oil Released: 60 BBL Recovered: 60 BBL Lost: 0 BBL]
Produced Water Released (bbls) Details	<i>Not answered.</i>
Is the concentration of dissolved chloride in the produced water >10,000 mg/l	<i>Not answered.</i>
Condensate Released (bbls) Details	<i>Not answered.</i>
Natural Gas Vented (Mcf) Details	<i>Not answered.</i>
Natural Gas Flared (Mcf) Details	<i>Not answered.</i>
Other Released Details	<i>Not answered.</i>
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Date: 11/13/21. Approx. 4:00 AM Location: Carnival CTB Incident: Heater Treater Fire and Oil Spill Estimated Volume: 60 Oil Description: At approximately 4:00 AM Greg Legier, FME gate security guard, called FME Field Superintendent, Clay Treadaway, and told him there was a fire at the Carnival CTB [facility ID (#) FAPP2123468509]. Clay immediately went to the battery and found treater flame arrestor was on fire. Got 20lb fire extinguisher and attempted to extinguish fire. Was unsuccessful. Heater tube began to leak oil. Decision was made to ESD facility and call Jal Fire Department. Started recirculating water to heater; closed water dump valve. When water level got above leak in tube, fire was extinguished. Fire was out before fire department arrived. Fire department remained on location until they felt comfortable all ignition risk was eliminated. Remediation: Safety equipment, vac truck, and gang on location for clean up. Full clean up should be complete by 11/18/2021. A follow-up report will be submitted.
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by 19.15.29.7(A) NMAC	Yes, major release.
Reasons why this would be considered a submission for a notification of a major release	<ul style="list-style-type: none"> • Unauthorized release of a volume, excluding gases, of 25 barrels or more • Incident Type is reported as fire • This release resulted in a fire or was the result of a fire
If YES, was immediate notice given to the OCD, by whom	<i>Not answered.</i>
If YES, was immediate notice given to the OCD, to whom	<i>Not answered.</i>
If YES, was immediate notice given to the OCD, when	<i>Not answered.</i>
If YES, was immediate notice given to the OCD, by what means (phone, email, etc.)	<i>Not answered.</i>

With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.

The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	<i>Not answered.</i>

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 61823

ACKNOWLEDGMENTS

Operator: Franklin Mountain Energy LLC 44 Cook Street Denver, CO 80206	OGRID: 373910
	Action Number: 61823
	Action Type: [NOTIFY] Notification Of Release (NOR)

ACKNOWLEDGMENTS

<input checked="" type="checkbox"/> I acknowledge that I am authorized to submit notification of releases on behalf of my operator.
<input checked="" type="checkbox"/> I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to my operator) to track the notification(s) and corrective action(s) for a release, pursuant to NMAC 19.15.29.
<input checked="" type="checkbox"/> I acknowledge that creating a new incident file will require my operator to file subsequent submission(s) of form "C-141, Application for administrative approval of a release notification and corrective action", pursuant to NMAC 19.15.29.
<input checked="" type="checkbox"/> I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment.
<input checked="" type="checkbox"/> I acknowledge the fact that the acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment.
<input checked="" type="checkbox"/> I acknowledge the fact that, in addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 61823

CONDITIONS

Operator: Franklin Mountain Energy LLC 44 Cook Street Denver, CO 80206	OGRID: 373910
	Action Number: 61823
	Action Type: [NOTIFY] Notification Of Release (NOR)

CONDITIONS

Created By	Condition	Condition Date
roverbey	When submitting future reports regarding this release, please submit the calculations used or specific justification for the volumes reported on the initial C-141.	11/15/2021



Date: 11/13/21. Approx. 4:00 AM

Location: Carnival CTB

Incident: Heater Treater Fire and spill

Final Volume: 93 BBLS Oil

Description:

At approximately 4:00 AM Greg Legier, FME gate security guard, called FME Field Superintendent, Clay Treadaway, and told him there was a fire at the Carnival CTB [facility ID (f#) fAPP2123468509]. Clay immediately went to the battery and found treater flame arrestor was on fire. Got 20lb fire extinguisher and attempted to extinguish fire. Was unsuccessful. Heater tube began to leak oil. Decision was made to ESD facility and call Jal Fire Department. Started recirculating water to heater, closed water dump valve. When water level got above leak in tube, fire was extinguished. Fire was out before fire department arrived. Fire department remained on location until they felt comfortable all ignition risk was eliminated. Remediation: Safety equipment, vac truck, and gang were dispatched to location for cleanup. Full cleanup was complete on 11/18/2021.

Root Cause:

Fire tube manufacturing flaw.

Remediation:

Fluids were fully contained. 93 BBLS were vac'd up and the containment and equipment were power washed. All fire tubes within FME's operation have been pulled and x-rayed to ensure integrity. All fire tubes will be x-rayed prior to site installation go-forward.



Photos of spill within containment:








Photo of vessel:





Photos of cleaned and restored:





District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAPP2131947608
District RP	
Facility ID	FAPP2123468509
Application ID	

Release Notification

Responsible Party

Responsible Party: Franklin Mountain Energy, LLC	OGRID: 373910
Contact Name: Craig Walters	Contact Telephone: 720-414-7868
Contact email: cwalters@fmellc.com	Incident # (assigned by OCD) NAPP2131947608
Contact mailing address: 44 Cook St., Ste. 1000 Denver, CO 80206	

Location of Release Source

Latitude 32.166139Longitude -103.338089 NAD83

(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Carnival CTB (FAPP2123468509)	Site Type: Production Facility
Date Release Discovered: 1/13/2021	API# (if applicable)

Unit Letter	Section	Township	Range	County
C	02	25S	35E	Lea

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 93	Volume Recovered (bbls) 93
<input type="checkbox"/> Produced Water	Volume Released (bbls):	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: Fire tube failure. Manufacturing flaw. All fire tubes have been or will be x-rayed going forward to ensure integrity.

Incident ID	NAPP2131947608
District RP	
Facility ID	FAPP2123468509
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? Volume of release greater than 25 bbls
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? NOR was submitted 11/15/2021.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- The source of the release has been stopped.
- The impacted area has been secured to protect human health and the environment.
- Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- All free liquids and recoverable materials have been removed and managed appropriately.


If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Rachael Overbey

Title: Dir. Operations Planning & Regulatory

Signature: 

Date: 12/1/2021

email: roverbey@fmellc.com

Telephone: 720-414-6878

OCD Only

Received by: _____

Date: _____



VOLUME CALCULATION

Volume spilled during Carnival Heater event is ~93 bbls.

- 93 bbls = Starting Volume in Vessel (204 bbls) – Ending Volume in Vessel (111 bbls)

Starting Volume in Vessel = 204 bbls

- $204 \text{ bbls} = \text{Volume of Liquid in Vessel to Wier (221 bbls)} - \text{Volume Occupied by Firetubes (17 bbls)}$

Volume in Cylinder	210 bbl
Volume in (1) Elliptical Head	11 bbl
Total Volume in vessel to "h"	221 bbl
	TO WEIR
Volume in 1 Length of 1 Tube	4 bbl
Volume in Bend of 1 Tube	1 bbl
Total Volume	17 bbl
	TOTAL
	BURNER
	TUBE
	VOLUME

Ending Volume in Vessel = 111 bbl


- 111 bbls = Volume of Liquid in Vessel to Firetube Leak (119 bbls) – Volume Occupied by Submerged Firetubes (8 bbls)

Volume in Cylinder	114 bbl
Volume in (1) Elliptical Head	5 bbl
Total Volume in vessel to "h"	119 bbl

Volume in 1 Length of 1 Tube	4 bbl
Volume in Bend of 1 Tube	0 bbl
Total Volume	8 bbl



Drawing of Heater:



Incident ID	NAPP2131947608
District RP	
Facility ID	FAPP2123468509
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	_____ (ft bgs)
Did this release impact groundwater or surface water?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a wetland?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release overlying a subsurface mine?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release overlying an unstable area such as karst geology?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within a 100-year floodplain?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Did the release impact areas not on an exploration, development, production, or storage site?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

Characterization Report Checklist: Each of the following items must be included in the report.

N/A - Fully
Contained

- Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.
- Field data
- Data table of soil contaminant concentration data
- Depth to water determination
- Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release
- Boring or excavation logs
- Photographs including date and GIS information
- Topographic/Aerial maps
- Laboratory data including chain of custody


If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Incident ID	NAPP2131947608
District RP	
Facility ID	FAPP2123468509
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Rachael Overbey

Title: Dir. Operations Planning & Regulatory

Signature: 

Date: 12/1/2021

email: roverbey@fmelc.com

Telephone: 720-414-6878

OCD Only

Received by: _____

Date: _____



December 1, 2021

RE: Release Closure Report for Record - Incident Number NAPP2131947608

Franklin Mountain Energy, LLC (FME) had a spill, within containment, at our CARNIVAL CTB (FAPP2123468509) location on 11/13/2021. A C-141 was filed and FME was issued incident number NAPP2131947608.

The spill was completely contained, containment vac'd, containment/equipment power washed, and site cleaned up by 11/18/20. There were no leaks in the containment and there was no impact to the surface of the location. FME visually inspected the area. The site is available for NMOCD Compliance inspection.

Please consider the site cleaned/restored and close the reported incident.

Please feel free to contact me directly with any questions or concerns at 303-570-4057.
Thank you!

Rachael Overbey

Director - Operations Planning & Regulatory

Franklin Mountain Energy LLC

44 Cook St., Suite 1000

Denver, CO 80206

Main: 720.414.7868

Mobile: 303.570.4057

roverbey@fmellc.com

Incident ID	NAPP2131947608
District RP	
Facility ID	FAPP2123468509
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.


Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- A scaled site and sampling diagram as described in 19.15.29.11 NMAC N/A - Fully Contained
- Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling) N/A - Fully Contained
- Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Rachael Overbey

Title: Dir. Operations Planning & Regulatory

Signature: 

Date: 12/1/2021

email: roverbey@fmellc.com

Telephone: 720-414-6878

OCD Only

Received by: _____

Date: _____

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: _____ Date: _____

Printed Name: _____

Title: _____

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 68236

CONDITIONS

Operator: Franklin Mountain Energy LLC 44 Cook Street Denver, CO 80206	OGRID: 373910
	Action Number: 68236
	Action Type: [C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rmarcus	The submitted C-141 is accepted with the following condition(s): The lateral and longitudinal information does not match the ULSTR regarding the release location. Please correct the conflicting information and report back to OCD. The latitude and longitude information on the C-141 resulted in the following ULSTR: B-2-25S-35W. Also there is a discrepancy on the date of release: 1/13/2021 or 11/13/2021? Please clarify.	12/21/2021

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 544375

QUESTIONS

Operator: Coterra Energy Operating Co. 6001 Deauville Blvd Midland, TX 79706	OGRID: 215099
	Action Number: 544375
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2131947608
Incident Name	NAPP2131947608 CARNIVAL CTB @ FAPP2123468509
Incident Type	Fire
Incident Status	Initial C-141 Approved
Incident Facility	[fAPP2123468509] Carnival CTB

Location of Release Source

Site Name	CARNIVAL CTB
Date Release Discovered	11/13/2021
Surface Owner	State

Liner Inspection Event Information*Please answer all the questions in this group.*

What is the liner inspection surface area in square feet	25,530
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	01/23/2026
Time liner inspection will commence	09:00 AM
Please provide any information necessary for observers to liner inspection	Liner Inspection of entire tank battery facility
Please provide any information necessary for navigation to liner inspection site	32.166139,-103.338089

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 544375

CONDITIONS

Operator: Coterra Energy Operating Co. 6001 Deauville Blvd Midland, TX 79706	OGRID: 215099
	Action Number: 544375
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)

CONDITIONS

Created By	Condition	Condition Date
athielke	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	1/19/2026



Liner Integrity Certification

The following serves to verify that the affected liner has been inspected and found to be in serviceable condition in accordance with 19.15.29.11 A.(5)(a)(i-ii) of the New Mexico Administrative Code.

Facility ID: fAPP2123468509

Date: 01/26/2026

Incident ID(s): nAPP2131947608


- Responsible Party has visually inspected the liner.
- Liner remains intact and was able to contain the leak in question.
- At least two business days' notice was given to the appropriate division district office before conducting the liner inspection.
- Photographs illustrating liner integrity are included.

PHOTOGRAPHIC LOG


Coterra Energy Operating Co

Photograph No. 1**Facility:** Carnival CTB (11.13.2021)**County:** Lea County, New Mexico**Description:**


View North of lined containment during winter 2026 rain/snow storm.

**Photograph No. 2****Facility:** Carnival CTB (11.13.2021)**County:** Lea County, New Mexico**Description:**

View North of lined containment during winter 2026 rain/snow storm.

**Photograph No. 3****Facility:** Carnival CTB (11.13.2021)**County:** Lea County, New Mexico**Description:**

View Northwest of lined containment during winter 2026 rain/snow storm.




PHOTOGRAPHIC LOG


Coterra Energy Operating Co

Photograph No. 4**Facility:** Carnival CTB (11.13.2021)**County:** Lea County, New Mexico**Description:**


View West of lined containment during winter 2026 rain/snow storm.

**Photograph No. 5****Facility:** Carnival CTB (11.13.2021)**County:** Lea County, New Mexico**Description:**

View Southwest of lined containment during winter 2026 rain/snow storm.

**Photograph No. 6****Facility:** Carnival CTB (11.13.2021)**County:** Lea County, New Mexico**Description:**

View Southwest of lined containment during winter 2026 rain/snow storm.



PHOTOGRAPHIC LOG


Coterra Energy Operating Co

Photograph No. 7**Facility:** Carnival CTB (11.13.2021)**County:** Lea County, New Mexico**Description:**


View Southeast of lined containment during winter 2026 rain/snow storm.

**Photograph No. 8****Facility:** Carnival CTB (11.13.2021)**County:** Lea County, New Mexico**Description:**

View South of lined containment during winter 2026 rain/snow storm.

**Photograph No. 9****Facility:** Carnival CTB (11.13.2021)**County:** Lea County, New Mexico**Description:**

View Southeast of lined containment during winter 2026 rain/snow storm.



Site Map

Coterra Energy Operating Co.

Legend

Page 26 of 42

- Carnival CTB (11.13.2021)




Google Earth

Released to Imaging: 2/2/2026 3:28:01 PM

Image © 2025 Airbus

N

3000 ft



- Carnival CTB (11.13.2021)
- ◆ Containment Area



Nearest water well

Coterra Energy Operating Co.

Legend

- 0.06 Miles
- 0.50 Mile Radius
- Carnival CTB (11.13.2021)
- Groundwater Determination Bore



- Carnival CTB (11.13.2021)
- Low

Carnival CTB (11.13.2021)



Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)

(R=POD has been replaced, O=orphaned, C=the file is closed)

(quarters are smallest to largest)

(meters)

(In feet)

POD Number	Code	Sub basin	County	Q64	Q16	Q4	Sec	Tws	Range	X	Y	Map	Distance	Well Depth	Depth Water	Water Column
CP 02097 POD1		CP	LE	NE	NE	NW	01	25S	35E	658237.1	3560131.3		1536	105		
CP 00624		CP	LE	SE	NW	NW	11	25S	35E	656206.0	3558197.0 *		1929	510		
CP 02069 POD1		CP	LE	NE	NE	NW	34	24S	35E	654968.6	3561581.0		2305	95		
CP 01919 POD1		CP	LE	NW	SW	SW	31	24S	36E	659230.3	3560419.8		2553	101		
CP 01972 POD1		CP	LE	SW	SE	SW	10	25S	35E	654863.0	3557050.7		3527			
CP 01972 POD3		CP	LE	SW	SE	SW	10	25S	35E	654852.4	3557044.7		3538			
CP 01972 POD2		CP	LE	SW	SE	SW	10	25S	35E	654852.0	3557033.0		3548			
CP 01119 POD2		CP	LE			SE	23	24S	35E	657210.4	3564007.7		3978	1572		

Average Depth to Water: **0 feet**

Minimum Depth: **0 feet**

Maximum Depth: **0 feet**

Record Count: 8

UTM Filters (in meters):

Easting: 656702.25

Northing: 3560061.30

Radius: 4000

* UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.



WELL RECORD & LOG

OFFICE OF THE STATE ENGINEER

www.ose.state.nm.us


1. GENERAL AND WELL LOCATION	OSE POD NO. (WELL NO.) Pod-1		WELL TAG ID NO.		OSE FILE NO(S). CP-2087			
	WELL OWNER NAME(S) Civitas Permian Operating				PHONE (OPTIONAL) 512-635-0129			
	WELL OWNER MAILING ADDRESS 6301 Holiday Hill Rd. Unit #201				CITY Midland	STATE TX	ZIP 79707	
	WELL LOCATION (FROM GPS)	DEGREES LATITUDE	32	MINUTES 10	SECONDS 0.90	* ACCURACY REQUIRED: ONE TENTH OF A SECOND * DATUM REQUIRED: WGS 84		
		LONGITUDE	103	20	18.82			
	DESCRIPTION RELATING WELL LOCATION TO STREET ADDRESS AND COMMON LANDMARKS – PLSS (SECTION, TOWNSHIP, RANGE) WHERE AVAILABLE UL-N S-35 T-24S R-35E							
	LICENSE NO. WD-1862		NAME OF LICENSED DRILLER James Hawley			NAME OF WELL DRILLING COMPANY H&R Enterprises, LLC		
	DRILLING STARTED 9/23/25	DRILLING ENDED 9/23/25	DEPTH OF COMPLETED WELL (FT) 106'	BORE HOLE DEPTH (FT) 106'		DEPTH WATER FIRST ENCOUNTERED (FT) Dry hole		
	COMPLETED WELL IS: <input type="checkbox"/> ARTESIAN *add <input checked="" type="checkbox"/> DRY HOLE <input type="checkbox"/> SHALLOW (UNCONFINED) Centralizer info below				STATIC WATER LEVEL IN COMPLETED WELL (FT)	NA	DATE STATIC MEASURED 9/26/25	
	DRILLING FLUID: <input checked="" type="checkbox"/> AIR <input type="checkbox"/> MUD ADDITIVES – SPECIFY:							
DRILLING METHOD: <input checked="" type="checkbox"/> ROTARY <input type="checkbox"/> HAMMER <input type="checkbox"/> CABLE TOOL <input type="checkbox"/> OTHER – SPECIFY:						CHECK HERE IF PITLESS ADAPTER IS <input type="checkbox"/> INSTALLED		
DEPTH (feet bgl)		BORE HOLE DIAM (inches)	CASING MATERIAL AND/OR GRADE (include each casing string, and note sections of screen)		CASING CONNECTION TYPE (add coupling diameter)	CASING INSIDE DIAM. (inches)	CASING WALL THICKNESS (inches)	SLOT SIZE (inches)
FROM	TO		No Casing left in hole					
DEPTH (feet bgl)		BORE HOLE DIAM. (inches)	LIST ANNULAR SEAL MATERIAL AND GRAVEL PACK SIZE- RANGE BY INTERVAL <i>*if using Centralizers for Artesian wells- indicate the spacing below</i>			AMOUNT (cubic feet)	METHOD OF PLACEMENT	
FROM	TO		N/A					
FOR OSE INTERNAL USE								
FILE NO.			POD NO.		TRN NO.			
LOCATION					WELL TAG ID NO.			PAGE 1 OF 2

FOR OSE INTERNAL USE

WR-20 WELL RECORD & LOG (Version 09/22/2022)


FILE NO. POD NO. TRN NO.
LOCATION WELL TAG ID NO. PAGE 2 OF 2

Carnival CTB (11.13.2021)



1/26/2026

World_Hillshade



Esri, NASA, NGA, USGS, FEMA, Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, (c) OpenStreetMap contributors, and the GIS User

Carnival CTB (11.13.2021)



1/26/2026, 2:04:39 PM

1:36,112


OSE Streams

0 0.38 0.75 1.5 mi
0 0.5 1 2 km

Esri, NASA, NGA, USGS, FEMA, Sources: Esri, TomTom, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community, NM OSE



Carnival CTB (11.13.2021)



January 26, 2026

Wetlands

- █ Estuarine and Marine Deepwater
- █ Estuarine and Marine Wetland

- █ Freshwater Emergent Wetland
- █ Freshwater Forested/Shrub Wetland
- █ Freshwater Pond
- █ Lake
- █ Other
- █ Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 546315

QUESTIONS

Operator: Coterra Energy Operating Co. 6001 Deauville Blvd Midland, TX 79706	OGRID: 215099
	Action Number: 546315
	Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2131947608
Incident Name	NAPP2131947608 CARNIVAL CTB @ FAPP2123468509
Incident Type	Fire
Incident Status	Remediation Closure Report Received
Incident Facility	[fAPP2123468509] Carnival CTB

Location of Release Source	
<i>Please answer all the questions in this group.</i>	
Site Name	CARNIVAL CTB
Date Release Discovered	11/13/2021
Surface Owner	State

Incident Details	
<i>Please answer all the questions in this group.</i>	
Incident Type	Fire
Did this release result in a fire or is the result of a fire	Yes
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

Nature and Volume of Release	
<i>Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.</i>	
Crude Oil Released (bbls) Details	Cause: Equipment Failure Separator Crude Oil Released: 60 BBL Recovered: 60 BBL Lost: 0 BBL.
Produced Water Released (bbls) Details	Not answered.
Is the concentration of chloride in the produced water >10,000 mg/l	Not answered.
Condensate Released (bbls) Details	Not answered.
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Date: 11/13/21. Approx. 4:00 AM Location: Carnival CTB Incident: Heater Treater Fire and Oil Spill Estimated Volume: 60 Oil Description: At approximately 4:00 AM Greg Legier, FME gate security guard, called FME Field Superintendent, Clay Treadaway, and told him there was a fire at the Carnival CTB [facility ID (#) FAPP2123468509]. Clay immediately went to the battery and found treater flame arrestor was on fire. Got 20lb fire extinguisher and attempted to extinguish fire. Was unsuccessful. Heater tube began to leak oil. Decision was made to ESD facility and call Jal Fire Department. Started recirculating water to heater; closed water dump valve. When water level got above leak in tube, fire was extinguished. Fire was out before fire department arrived. Fire department remained on location until they felt comfortable all ignition risk was eliminated. Remediation: Safety equipment, vac truck, and gang on location for clean up. Full clean up should be complete by 11/18/2021. A follow-up report will be submitted.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 546315

QUESTIONS (continued)

Operator: Coterra Energy Operating Co. 6001 Deauville Blvd Midland, TX 79706	OGRID: 215099
	Action Number: 546315
	Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Nature and Volume of Release (continued)	
Is this a gas only submission (i.e. only significant Mcf values reported)	No, according to supplied volumes this does not appear to be a "gas only" report.
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	Yes
Reasons why this would be considered a submission for a notification of a major release	<p>From paragraph A. "Major release" determine using:</p> <p>(1) an unauthorized release of a volume, excluding gases, of 25 barrels or more;</p> <p>(2) an unauthorized release of a volume that:</p> <p>(a) results in a fire or is the result of a fire.</p>

With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.

Initial Response	
<i>The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.</i>	
The source of the release has been stopped	True
The impacted area has been secured to protect human health and the environment	True
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	True
All free liquids and recoverable materials have been removed and managed appropriately	True
If all the actions described above have not been undertaken, explain why	<i>Not answered.</i>

Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement	Name: Ashton Thielke Title: EHS Specialist Email: Ashton.Thielke@coterra.com Date: 01/26/2026
--	--

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 3

Action 546315

QUESTIONS (continued)

Operator: Coterra Energy Operating Co. 6001 Deauville Blvd Midland, TX 79706	OGRID: 215099
	Action Number: 546315
	Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Site Characterization

Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Between 100 and 500 (ft.)
What method was used to determine the depth to ground water	Direct Measurement
Did this release impact groundwater or surface water	No
What is the minimum distance, between the closest lateral extents of the release and the following surface areas:	
A continuously flowing watercourse or any other significant watercourse	Between 1/2 and 1 (mi.)
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Between 1 and 5 (mi.)
An occupied permanent residence, school, hospital, institution, or church	Between 1 and 5 (mi.)
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Between 1 and 5 (mi.)
Any other fresh water well or spring	Between 1 and 5 (mi.)
Incorporated municipal boundaries or a defined municipal fresh water well field	Greater than 5 (mi.)
A wetland	Between 1/2 and 1 (mi.)
A subsurface mine	Greater than 5 (mi.)
An (non-karst) unstable area	Greater than 5 (mi.)
Categorize the risk of this well / site being in a karst geology	Low
A 100-year floodplain	Between 1/2 and 1 (mi.)
Did the release impact areas not on an exploration, development, production, or storage site	No

Remediation Plan

Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

Requesting a remediation plan approval with this submission	Yes
<i>Attach a comprehensive report demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined, pursuant to 19.15.29.11 NMAC and 19.15.29.13 NMAC.</i>	
Have the lateral and vertical extents of contamination been fully delineated	Yes
Was this release entirely contained within a lined containment area	Yes
<i>Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC, which includes the anticipated timelines for beginning and completing the remediation.</i>	
On what estimated date will the remediation commence	11/14/2021
On what date will (or did) the final sampling or liner inspection occur	11/23/2026
On what date will (or was) the remediation complete(d)	11/23/2026
What is the estimated surface area (in square feet) that will be remediated	25530
What is the estimated volume (in cubic yards) that will be remediated	0

These estimated dates and measurements are recognized to be the best guess or calculation at the time of submission and may (be) change(d) over time as more remediation efforts are completed.

The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 4

Action 546315

QUESTIONS (continued)

Operator: Coterra Energy Operating Co. 6001 Deauville Blvd Midland, TX 79706	OGRID: 215099
	Action Number: 546315
	Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Remediation Plan (continued)

Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

This remediation will (or is expected to) utilize the following processes to remediate / reduce contaminants:

(Select all answers below that apply.)

Is (or was) there affected material present needing to be removed	Yes
Is (or was) there a power wash of the lined containment area (to be) performed	Yes
OTHER (Non-listed remedial process)	Not answered.

Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC, which includes the anticipated timelines for beginning and completing the remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement	Name: Ashton Thielke Title: EHS Specialist Email: Ashton.Thielke@coterra.com Date: 01/26/2026
--	--

The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

QUESTIONS, Page 6

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Action 546315

QUESTIONS (continued)

Operator: Coterra Energy Operating Co. 6001 Deauville Blvd Midland, TX 79706	OGRID: 215099
	Action Number: 546315
	Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure)

QUESTIONS

Liner Inspection Information	
Last liner inspection notification (C-141L) recorded	544375
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	01/23/2026
Was all the impacted materials removed from the liner	Yes
What was the liner inspection surface area in square feet	25530

Remediation Closure Request	
<i>Only answer the questions in this group if seeking remediation closure for this release because all remediation steps have been completed.</i>	
Requesting a remediation closure approval with this submission	Yes
Have the lateral and vertical extents of contamination been fully delineated	Yes
Was this release entirely contained within a lined containment area	Yes
What was the total surface area (in square feet) remediated	25530
What was the total volume (cubic yards) remediated	0
Summarize any additional remediation activities not included by answers (above)	The area was previously cleaned immediately after the release. A second inspection was conducted on 01.23.2026 to verify the integrity of the liner. While onsite, rain and snow began to fall but the slight water in the containment demonstrated the liner integrity. Additionally, you could still see the bottom of the liner, which did not show any holes in the containment.

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (in .pdf format) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.	
I hereby agree and sign off to the above statement	Name: Ashton Thielke Title: EHS Specialist Email: Ashton.Thielke@coterra.com Date: 01/26/2026

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 546315

CONDITIONS

Operator: Coterra Energy Operating Co. 6001 Deauville Blvd Midland, TX 79706	OGRID: 215099
	Action Number: 546315
	Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure)

CONDITIONS

Created By	Condition	Condition Date
rhamlet	We have received your Remediation Closure Report for Incident #nAPP2131947608 CARNIVAL CTB, thank you. This Remediation Closure Report is approved.	2/2/2026