



FAX To: Regional Environmental Department 111-111-1111

## SERC/LEPC Notification Form

Facility Name:	Burton Flats Booster	Date:	2/2/2026 8:34 AM	County:	EDDY
Location:	Event GPS Coordinates: 32.5195, -104.1507 Driving Directions: (Lat: 32.5195, Long: -104.1507); From Canal St (CR-206) & Pierce St located on the northeast side of Carlsbad NM, drive 3.2 miles N on CR-206, continue N onto Illinois Camp Rd for another 0.6 mile, turn E and drive 2.2 miles on Rains Rd to an intersection with Angle Ranch Rd, continue NE on Rains Rd for another 1.2 miles to a fork, bear right (E) and drive 1.7 miles on an Access Rd to the Booster Station on the right.				<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Updated Report <input type="checkbox"/> Final Report
Type of Incident:	Upset	Release Occurred To:	Air	Release Type:	Vented
Started On:	1/31/2026 12:58 AM	Ended On:	1/31/2026 1:22 AM	Discovered On:	1/31/2026 12:58 AM

## Event Duration:

24 Minutes

## Material Released:

## Material Composition:

Carbon Dioxide 0.874%, Methane 81.3662%, Hydrogen Sulfide 0.1292%, Hexane 0.2394%, Butane 1.1513%, Pentane 0.3031%, Heptane 0.2147%, n-Nonane 0.049%, n-Octane 0.1417%, Nitrogen 1.4473%, Propane 3.8546%, Ethane 9.3919%, Isobutane 0.5242%, Isopentane 0.3134%, Hydrogen Sulfide 0.1292%,

## Calculations:

Compound Calculation Used to Obtain Released Amount (Id: 144454)

Hexane: 87000 {scf/event} \* 0.002394 {mole fraction} \* 86.1754 {lb/lb-mole} / 379.3 {scf/lb-mole}

Butane: 87000 {scf/event} \* 0.011513 {mole fraction} \* 58.1222 {lb/lb-mole} / 379.3 {scf/lb-mole}

Pentane: 87000 {scf/event} \* 0.003031 {mole fraction} \* 72.1488 {lb/lb-mole} / 379.3 {scf/lb-mole}

Heptane: 87000 {scf/event} \* 0.002147 {mole fraction} \* 100.2019 {lb/lb-mole} / 379.3 {scf/lb-mole}

n-Nonane: 87000 {scf/event} \* 0.00049 {mole fraction} \* 128.2551 {lb/lb-mole} / 379.3 {scf/lb-mole}

n-Octane: 87000 {scf/event} \* 0.001417 {mole fraction} \* 114.2285 {lb/lb-mole} / 379.3 {scf/lb-mole}

Propane: 87000 {scf/event} \* 0.038546 {mole fraction} \* 44.0956 {lb/lb-mole} / 379.3 {scf/lb-mole}

Isobutane: 87000 {scf/event} \* 0.005242 {mole fraction} \* 58.1222 {lb/lb-mole} / 379.3 {scf/lb-mole}

Isopentane: 87000 {scf/event} \* 0.003134 {mole fraction} \* 72.1488 {lb/lb-mole} / 379.3 {scf/lb-mole}

Carbon Dioxide: 87000 {scf/event} \* 0.00874 {mole fraction} \* 44.0095 {lb/lb-mole} / 379.3 {scf/lb-mole}

Hydrogen Sulfide: 87000 {scf/event} \* 0.001292 {mole fraction} \* 34.08088 {lb/lb-mole} / 379.3 {scf/lb-mole}

Nitrogen: 87000 {scf/event} \* 0.014473 {mole fraction} \* 28.0134 {lb/lb-mole} / 379.3 {scf/lb-mole}

Ethane: 87000 {scf/event} \* 0.093919 {mole fraction} \* 30.069 {lb/lb-mole} / 379.3 {scf/lb-mole}

## Violations:

## Known or anticipated acute or chronic health risks associated with the emergency:

## Medical attention advised for exposed individuals:

## Cause of the upset:

multiple units down due to high discharge pressures

## Actions taken to correct the upset and minimize emissions:

restarted compression when pressures came down

## Precautions taken as a result of the release:

A. AI Number	N. Failure Pt No: O. Failure Pt. Description:				
251	Vent (Emergency Blowdown Vent )				
A. NOx: 0 lb	B. SO2: 0 lb	C. CO: 0 lb	D. PM: 	E. VOC: 863.46 lb	F. H2S: 10.1 lb

Vol=87 mscf/event

SERC Email Notification: henry.jolly@state.nm.us

LEPC Email Notification: jarmendariz@eddyoem.com

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

DEFINITIONS

Action 548961

**DEFINITIONS**

Operator: DCP OPERATING COMPANY, LP 2331 Citywest Blvd Houston, TX 77042	OGRID: 36785
	Action Number: 548961
	Action Type: [C-129] Venting and/or Flaring (C-129)

**DEFINITIONS**

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 548961

## QUESTIONS

Operator: DCP OPERATING COMPANY, LP 2331 Citywest Blvd Houston, TX 77042	OGRID: 36785
	Action Number: 548961
	Action Type: [C-129] Venting and/or Flaring (C-129)

## QUESTIONS

## Prerequisites

*Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.*

Incident Well	Unavailable.
Incident Facility	[FWJF0431356160] BURTON FLATS BOOSTER STATION

## Determination of Reporting Requirements

*Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.*

Was this vent or flare caused by an emergency or malfunction	No
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.

*An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.*

Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or within 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

## Equipment Involved

Primary Equipment Involved	Not answered.
Additional details for Equipment Involved. Please specify	Not answered.

## Representative Compositional Analysis of Vented or Flared Natural Gas

*Please provide the mole percent for the percentage questions in this group.*

Methane (CH4) percentage	81
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	1
Oxygen (O2) percentage, if greater than one percent	0

*If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.*

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 548961

**QUESTIONS (continued)**

Operator:  DCP OPERATING COMPANY, LP 2331 Citywest Blvd Houston, TX 77042	OGRID:  36785
	Action Number:  548961
	Action Type:  [C-129] Venting and/or Flaring (C-129)

**QUESTIONS**

<b>Date(s) and Time(s)</b>	
Date vent or flare was discovered or commenced	01/31/2026
Time vent or flare was discovered or commenced	12:58 AM
Time vent or flare was terminated	01:22 AM
Cumulative hours during this event	1

<b>Measured or Estimated Volume of Vented or Flared Natural Gas</b>	
Natural Gas Vented (Mcf) Details	Cause: Other   Gas Compressor Station   Natural Gas Vented   Released: 87 Mcf   Recovered: 0 Mcf   Lost: 87 Mcf.
Natural Gas Flared (Mcf) Details	<i>Not answered.</i>
Other Released Details	<i>Not answered.</i>
Additional details for Measured or Estimated Volume(s). Please specify	<i>Not answered.</i>
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

<b>Venting or Flaring Resulting from Downstream Activity</b>	
Was this vent or flare a result of downstream activity	<b>No</b>
Was notification of downstream activity received by this operator	<i>Not answered.</i>
Downstream OGRID that should have notified this operator	<i>Not answered.</i>
Date notified of downstream activity requiring this vent or flare	<i>Not answered.</i>
Time notified of downstream activity requiring this vent or flare	<i>Not answered.</i>

<b>Steps and Actions to Prevent Waste</b>	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	<b>True</b>
Please explain reason for why this event was beyond this operator's control	Multiple units down due to high discharge pressure from Artesia Gas Plant.
Steps taken to limit the duration and magnitude of vent or flare	Once pressure dropped from Artesia, units were restarted and venting stopped.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Once pressure dropped from Artesia, units were restarted and venting stopped.



Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 548961

**ACKNOWLEDGMENTS**

Operator: DCP OPERATING COMPANY, LP 2331 Citywest Blvd Houston, TX 77042	OGRID: 36785
	Action Number: 548961
	Action Type: [C-129] Venting and/or Flaring (C-129)

**ACKNOWLEDGMENTS**

<input checked="" type="checkbox"/>	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a <b>complete C-129</b> submission per 19.15.27.8 and 19.15.28.8 NMAC.
<input checked="" type="checkbox"/>	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
<input checked="" type="checkbox"/>	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
<input checked="" type="checkbox"/>	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<input checked="" type="checkbox"/>	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 548961

**CONDITIONS**

Operator:  DCP OPERATING COMPANY, LP 2331 Citywest Blvd Houston, TX 77042	OGRID: 36785
	Action Number: 548961
	Action Type: [C-129] Venting and/or Flaring (C-129)

**CONDITIONS**

Created By	Condition	Condition Date
rasmalts	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	2/2/2026