

**From:** [Terhune, Chuck](#)  
**To:** [Wells, Shelly, EMNRD](#)  
**Subject:** RE: [EXTERNAL] RE: nAPP2614944462 State F Battery  
**Date:** Monday, June 1, 2026 9:13:39 AM  
**Attachments:** [image001.png](#)  
[image002.png](#)  
[image003.png](#)  
[image004.png](#)  
[image005.png](#)

---

Yes, the attachment is correct

Best Regards,

**Chuck Terhune, P.G. | Program Manager**

Mobile +1 (281) 755-8965 | Business +1 (832) 252-2093

[chuck.terhune@tetrattech.com](mailto:chuck.terhune@tetrattech.com)

**Tetra Tech** | *Leading with Science*® | OGA

1500 CityWest Blvd., Ste. 1000 | Houston, TX 77042 | [tetrattech.com/oilandgas](https://tetrattech.com/oilandgas)

*This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.*



Please consider the environment before printing. [Read more](#)



---

**From:** Wells, Shelly, EMNRD <[Shelly.Wells@emnrd.nm.gov](mailto:Shelly.Wells@emnrd.nm.gov)>  
**Sent:** Monday, June 1, 2026 10:08 AM  
**To:** Terhune, Chuck <[chuck.terhune@tetrattech.com](mailto:chuck.terhune@tetrattech.com)>  
**Subject:** RE: [EXTERNAL] RE: nAPP2614944462 State F Battery

**⚠ CAUTION:** This email originated from an external sender. Verify the source before opening links or attachments. ⚠

Hi Chuck,

So the Total Spill Liquid and the Recovered Volumes are correct on the volume calculation attachment?

Shelly

---

**From:** Terhune, Chuck <[chuck.terhune@tetrattech.com](mailto:chuck.terhune@tetrattech.com)>

**Sent:** Monday, June 1, 2026 9:03 AM  
**To:** Wells, Shelly, EMNRD <[Shelly.Wells@emnrd.nm.gov](mailto:Shelly.Wells@emnrd.nm.gov)>  
**Subject:** [EXTERNAL] RE: nAPP2614944462 State F Battery

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

ACH, sorry, this is the correct:

1.5 bbls oil recovered  
8.5 bbls Produced Water recovered

Best Regards,

**Chuck Terhune, P.G. | Program Manager**  
Mobile +1 (281) 755-8965 | Business +1 (832) 252-2093  
[chuck.terhune@tetrattech.com](mailto:chuck.terhune@tetrattech.com)

**Tetra Tech** | *Leading with Science*® | OGA  
1500 CityWest Blvd., Ste. 1000 | Houston, TX 77042 | [tetrattech.com/oilandgas](http://tetrattech.com/oilandgas)

*This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.*



Please consider the environment before printing. [Read more](#)



---

**From:** Wells, Shelly, EMNRD <[Shelly.Wells@emnrd.nm.gov](mailto:Shelly.Wells@emnrd.nm.gov)>  
**Sent:** Monday, June 1, 2026 9:59 AM  
**To:** Terhune, Chuck <[chuck.terhune@tetrattech.com](mailto:chuck.terhune@tetrattech.com)>  
**Subject:** nAPP2614944462 State F Battery

⚠ CAUTION: This email originated from an external sender. Verify the source before opening links or attachments. ⚠

Good morning Chuck,

I am reviewing the submitted initial C-141 for nAPP2614944462 State F Battery and have a few questions for you regarding the volume calculations. I see that under the Nature and Volume of Release, in the C-141 application, it says that 5 BBL Oil was released and

2 BBL recovered; in addition, it says that 10 BBL PW was released and 3 BBL recovered. The volumes on the submitted volume calculation sheet do not match this. Which volumes are correct? If the volume calculation sheet needs updating please do so and email the corrected copy to me.

Kind regards,

Shelly

Shelly Wells \* Senior Environmental Scientist  
Environmental Bureau  
EMNRD-Oil Conservation Division  
1220 S. St. Francis Drive|Santa Fe, NM 87505  
(505)469-7520 [Shelly.Wells@emnrd.nm.gov](mailto:Shelly.Wells@emnrd.nm.gov)  
<http://www.emnrd.state.nm.us/OCD/>

**\*\*\*\*\* LIQUID SPILLS - VOLUME CALCULATIONS \*\*\*\*\***

Location of Spill: State F Battery

Date of Spill: 5/28/2026

If the leak/spill is associated with production equipment, i.e. - wellhead, stuffing box, flowline, tank battery, production vessel, transfer pump, or storage tank place an "X" here:

**Input Data:**

If spill volumes from measurement, i.e. metering, tank volumes, etc. are known enter the volumes here:                      OIL:                      BBL      WATER:                      BBL

If "known" spill volumes are given, input data for the following "Area Calculations" is optional. The above will override the calculated volumes.

Total Area Calculations					Standing Liquid Calculations				
Total Surface Area	width	length	wet soil depth	oil (%)	Standing Liquid Area	width	length	liquid depth	oil (%)
Rectangle Area #1	9.00 ft X	55.00 ft X	2.00 in	15.00%	Rectangle Area #1	8.00 ft X	55.00 ft X	1.00 in	15.00%
Rectangle Area #2	5.00 ft X	40.00 ft X	2.00 in	15.00%	Rectangle Area #2	5.00 ft X	40.00 ft X	2.00 in	15.00%
Rectangle Area #3	6.00 ft X	12.00 ft X	2.00 in	15.00%	Rectangle Area #3	5.00 ft X	10.00 ft X	1.50 in	15.00%
Rectangle Area #4	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #4	0.00 ft X	0.00 ft X	0.00 in	0.00%
Rectangle Area #5	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #5	0.00 ft X	0.00 ft X	0.00 in	0.00%
Rectangle Area #6	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #6	0.00 ft X	0.00 ft X	0.00 in	0.00%
Rectangle Area #7	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #7	0.00 ft X	0.00 ft X	0.00 in	0.00%
Rectangle Area #8	0.00 ft X	0.00 ft X	0.00 in	0.00%	Rectangle Area #8	0.00 ft X	0.00 ft X	0.00 in	0.00%

**production system leak - DAILY PRODUCTION DATA REQUIRED**

Average Daily Production: Oil                      BBL      Water                      BBL

Did leak occur before the separator?:  YES       N/A (place an "X")

Amount of Free Liquid Recovered: 10 BBL      **okay**

Percentage of Oil in Free Liquid Recovered: 15.00% (percentage)

Liquid holding factor \*: 0.08 gal per gal  
Maljamar Sands

Use the following when the spill wets the grains of the soil.

- \* sand = .08 gallon liquid per gallon volume of soil.
- \* gravelly (caliche) loam = .14 gallon liquid per gallon volume of soil.
- \* sandy clay loam soil = .14 gallon liquid per gallon volume of soil.
- \* clay loam = .16 gallon liquid per gallon volume of soil.

Use the following when the liquid completely fills the pore space of the soil:

- Occurs when the spill soaked soil is contained by barriers, natural (or not).
- \* gravelly (caliche) loam = .25 gallon liquid per gallon volume of soil.
- \* sandy loam = .5 gallon liquid per gallon volume of soil.

Saturated Soil Volume Calculations:			Free Liquid Volume Calculations:		
Total Solid/Liquid Volume:	H2O	OIL	Total Free Liquid Volume:	H2O	OIL
<b>767 sq. ft.</b>	<b>109 cu. ft.</b>	<b>19 cu. ft.</b>	<b>690 sq. ft.</b>	<b>65 cu. ft.</b>	<b>11 cu. ft.</b>
<b>Estimated Volumes Spilled</b>			<b>Estimated Production Volumes Lost</b>		
Liquid in Soil:	H2O <u>1.5</u> BBL	OIL <u>0.3</u> BBL	Estimated Production Spilled:	H2O <u>0.0</u> BBL	OIL <u>0.0</u> BBL
Free Liquid:	<u>11.5</u> BBL	<u>2.0</u> BBL	<b>Estimated Surface Damage</b>		
Totals:	<u>13.1</u> BBL	<u>2.3</u> BBL	Surface Area: <u>767</u> sq. ft.		
Total Spill Liquid:	<b>13.1 BBL</b>	<b>2.3 BBL</b>	Surface Area: <u>.0176</u> acre		
<b>Recovered Volumes</b>			<b>Estimated Weights, and Volumes</b>		
Estimated oil recovered:	<u>1.5</u> BBL	<b>check - okay</b>	Saturated Soil =	<u>14,317</u> lbs	<u>128</u> cu.ft.
Estimated water recovered:	<u>8.5</u> BBL	<b>Oil recovered as released as operator was on site as leak</b>	Total Liquid =	<u>15</u> BBL	<u>647</u> gallon
					<u>5</u> cu.yds.
					<u>5,382</u> lbs

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS

Action 590265

**QUESTIONS**

Operator: Maverick Permian LLC 500 Dallas Street, Suite 2300 Houston, TX 77002	OGRID: 331199
	Action Number: 590265
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

**QUESTIONS**

<b>Prerequisites</b>	
Incident ID (n#)	nAPP2614944462
Incident Name	NAPP2614944462 STATE F BATTERY @ M-01-21S-36E
Incident Type	Release Other
Incident Status	Initial C-141 Received

<b>Location of Release Source</b>	
<i>Please answer all the questions in this group.</i>	
Site Name	State F Battery
Date Release Discovered	05/28/2026
Surface Owner	State

<b>Incident Details</b>	
<i>Please answer all the questions in this group.</i>	
Incident Type	Produced Water Release
Did this release result in a fire or is the result of a fire	No
Did this release result in any injuries	No
Has this release reached or does it have a reasonable probability of reaching a watercourse	No
Has this release endangered or does it have a reasonable probability of endangering public health	No
Has this release substantially damaged or will it substantially damage property or the environment	No
Is this release of a volume that is or may with reasonable probability be detrimental to fresh water	No

<b>Nature and Volume of Release</b>	
<i>Material(s) released, please answer all that apply below. Any calculations or specific justifications for the volumes provided should be attached to the follow-up C-141 submission.</i>	
Crude Oil Released (bbls) Details	Cause: Equipment Failure   Production Tank   Crude Oil   Released: 5 BBL   Recovered: 2 BBL   Lost: 3 BBL.
Produced Water Released (bbls) Details	Cause: Equipment Failure   Production Tank   Produced Water   Released: 10 BBL   Recovered: 3 BBL   Lost: 7 BBL.
Is the concentration of chloride in the produced water >10,000 mg/l	Yes
Condensate Released (bbls) Details	Not answered.
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Not answered.
Other Released Details	Not answered.
Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts)	Not answered.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 590265

**QUESTIONS (continued)**

Operator: Maverick Permian LLC 500 Dallas Street, Suite 2300 Houston, TX 77002	OGRID: 331199
	Action Number: 590265
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

**QUESTIONS**

<b>Nature and Volume of Release (continued)</b>	
Is this a gas only submission (i.e. only significant Mcf values reported)	<b>No, according to supplied volumes this does not appear to be a "gas only" report.</b>
Was this a major release as defined by Subsection A of 19.15.29.7 NMAC	<b>No</b>
Reasons why this would be considered a submission for a notification of a major release	<i>Unavailable.</i>

*With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. gas only) are to be submitted on the C-129 form.*

**Initial Response**

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury.*

The source of the release has been stopped	<b>True</b>
The impacted area has been secured to protect human health and the environment	<b>True</b>
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices	<b>True</b>
All free liquids and recoverable materials have been removed and managed appropriately	<b>True</b>
If all the actions described above have not been undertaken, explain why	<i>Not answered.</i>

*Per Paragraph (4) of Subsection B of 19.15.29.8 NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative of actions to date in the follow-up C-141 submission. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC), please prepare and attach all information needed for closure evaluation in the follow-up C-141 submission.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement	Name: Chuck Terhune Title: Program Manager Email: <a href="mailto:chuck.terhune@tetrattech.com">chuck.terhune@tetrattech.com</a> Date: 06/01/2026
--	--

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

QUESTIONS, Page 3

Action 590265

**QUESTIONS (continued)**

Operator: Maverick Permian LLC 500 Dallas Street, Suite 2300 Houston, TX 77002	OGRID: 331199
	Action Number: 590265
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

**QUESTIONS**

**Site Characterization**  
Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs)	Not answered.
What method was used to determine the depth to ground water	Not answered.
Did this release impact groundwater or surface water	Not answered.
<b>What is the minimum distance, between the closest lateral extents of the release and the following surface areas:</b>	
A continuously flowing watercourse or any other significant watercourse	Not answered.
Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)	Not answered.
An occupied permanent residence, school, hospital, institution, or church	Not answered.
A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes	Not answered.
Any other fresh water well or spring	Not answered.
Incorporated municipal boundaries or a defined municipal fresh water well field	Not answered.
A wetland	Not answered.
A subsurface mine	Not answered.
An (non-karst) unstable area	Not answered.
Categorize the risk of this well / site being in a karst geology	Not answered.
A 100-year floodplain	Not answered.
Did the release impact areas not on an exploration, development, production, or storage site	Not answered.

**Remediation Plan**  
Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

Requesting a remediation plan approval with this submission	No
The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.	

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oecd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 590265

**CONDITIONS**

Operator: Maverick Permian LLC 500 Dallas Street, Suite 2300 Houston, TX 77002	OGRID: 331199
	Action Number: 590265
	Action Type: [C-141] Initial C-141 (C-141-v-Initial)

**CONDITIONS**

Created By	Condition	Condition Date
scwells	Initial C-141 approved. Pursuant to 19.15.29.12.B(1) NMAC, a remediation plan or a remediation closure report is due to the OCD by 8/26/26.	6/1/2026