

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720
District II
1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-103
Permit 39759

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NUMBER 30-015-34954
1. Type of Well:G		5. Indicate Type of Lease P
2. Name of Operator YATES PETROLEUM CORPORATION		6. State Oil & Gas Lease No.
3. Address of Operator 105 S 4TH ST , ARTESIA , NM 88210		7. Lease Name or Unit Agreement Name IVEY BFV
4. Well Location Unit Letter P : 660 feet from the S line and 850 feet from the E line Section 4 Township 19S Range 26E NMPM Eddy County		8. Well Number 001
11. Elevation (Show whether DR, KB, BT, GR, etc.) 3345 GR.		9. OGRID Number 25575
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING/CEMENT JOB ☐
Other: **Drilling/Cement** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/25/06 Resumed drilling.

9/29/06 Set 13-3/8" 48# H-40 casing at 1024'. Cemented with 180 sx Class "H" + 10% A-10 + 0.25#/sx CF + 10#/sx LCM-1 (yld 1.52, wt 14.6) and 600 sx 15:61:11 "H" + 0.25#/sx CF + 5#/sx LCM-1 + 2% CaCl2 (yld 1.98, wt 12.5). Tailed in with 200 sx Class "C" + 1% CaCl2 (yld 1.32, wt 14.8). Cement did not circulate. Ran temperature survey and found TOC at 300'. Ran 1" cement to surface with 250 sx Class "C". Tested casing to 600 psi for 30 min. WOC 49 hrs 30 min. Reduced hole and resumed drilling 9/11/2006 Spudded well.

Casing and Cement Program

Date	String	Fluid Type	Hole Size	Csg Size	Weight lb/ft	Grade	Est TOC	Dpth Set	Sacks	Yield	Class	1" Dpth	Pres Held	Pres Drop	Open Hole
09/29/06	Surf		17.5	13.375	48		0	1024	1230						

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed

TITLE

DATE 10/16/2006

Type or print name Shirley Pruitt

E-mail address shirleyp@ypcnm.com

Telephone No. 505-748-4356

For State Use Only:

APPROVED BY: Bryan Arrant

TITLE Geologist

DATE 10/17/2006 7:44:41 AM

Drilling Comments

OGRID: [25575] YATES PETROLEUM CORPORATION
Permit Number: 39759
Permit Type: Drilling

Created By	Comment	Comment Date
TINAH	Submitted by Tina Huerta, Regulatory Compliance Supervisor	10/16/2006
BArrant	Operator to submit temperature survey.	10/17/2006