

District II

1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

WELL API NUMBER

30-015-35098

5. Indicate Type of Lease

S

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

MOSLEY CANYON BIA
STATE COM

8. Well Number

001

9. OGRID Number

25575

10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:G

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 S 4TH ST , ARTESIA , NM 88210

4. Well Location

Unit Letter 1 : 660 feet from the N line and 660 feet from the E line
Section 5 Township 24S Range 25E NMPM Eddy County

11. Elevation (Show whether DR, KB, BT, GR, etc.)

3814 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐CASING/CEMENT JOB ☐Other: **Spud** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/1/2006 Spudded well.

10/1/06 Spudded 26" conductor hole. Set 57' of 20" conductor NOTE: Had to redi-mix cellar before resuming drilling conductor hole. Mike Bratcher (NMOCD) was notified of operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.SIGNATURE Electronically Signed TITLE _____ DATE 10/16/2006Type or print name Shirley Pruitt E-mail address shirleyp@ypcnm.com Telephone No. 505-748-4356

For State Use Only:

APPROVED BY: Bryan Arrant TITLE Geologist DATE 10/17/2006

NoticeSpud Comments

OGRID: [25575] YATES PETROLEUM CORPORATION
Permit Number: 39786
Permit Type: NoticeSpud

Created By	Comment	Comment Date
TINAH	Submitted by Tina Huerta, Regulatory Compliance Supervisor	10/16/2006