



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 1-8-15 Operator Hess Corp. API # 30-021-20546

Property Name WBDGU Well No. 1 Location: Unit J Section 23 Township 19 Range 29

Well Status (Shut-In or Producing) Tubing 550 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING			
5 minutes	0	N/A	0	Steady Flow		N/A
10 minutes	0	N/A	0	Surges		N/A
15 minutes	0	N/A	0	Down to Nothing		N/A
20 minutes	0	N/A	0	Nothing	X	N/A
25 minutes	0	N/A	0	Gas		N/A
30 minutes	0	N/A	0	Gas & Water		N/A
				Water		N/A

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

West Bravo Dome Gas Unit 1929 - 231J

Elaine Hunter

By Elaine Hunter Witness James Reece

Regulatory Technician
(Position)

E-mail address ehunter@hess.com

RECEIVED

FEB 06 2015

NMOCD
DISTRICT III

WBDGU 1929-231J
Annual Bradenhead Test (SI Well)

Year	Date	Tbg PSI	Csg PSI	Bleed Down Time
2013	2/13	510	0	
2014	2/19	540	0	
2015	01/08/2015	550	0	
2016				
2017				
2018				
2019				
2020				
2021				
2022				
2023				

Note: Well drilled in 2012 and SI as uneconomic producer



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 1-8-15 Operator Hess Corp. API # 30-021-20546

Property Name WBDGU Well No. 1 Location: Unit J Section 23 Township 19 Range 29

Well Status (Shut-In or Producing) Tubing 550 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING			
5 minutes	0	N/A	0	Steady Flow		N/A
10 minutes	0	N/A	0	Surges		N/A
15 minutes	0	N/A	0	Down to Nothing		N/A
20 minutes	0	N/A	0	Nothing	X	N/A
25 minutes	0	N/A	0	Gas		N/A
30 minutes	0	N/A	0	Gas & Water		N/A
				Water		N/A

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

West Bravo Dome Gas Unit 1929 - 231J

Elaine Hunter

By Elaine Hunter Witness James Reece

Regulatory Technician
(Position)

E-mail address ehunter@hess.com

WBDGU 1929-231J
Annual Bradenhead Test (SI Well)

Year	Date	Tbg PSI	Csg PSI	Bleed Down Time
2013	2/13	510	0	
2014	2/19	540	0	
2015	01/08/2015	550	0	
2016				
2017				
2018				
2019				
2020				
2021				
2022				
2023				

Note: Well drilled in 2012 and SI as uneconomic producer