



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 1-8-2015 Operator Hess Corporation API # 30-021-20534

Property Name WBDGU Well No. 1 Location: Unit J Section 14 Township 19 Range 29

Well Status (Shut-In or Producing) Tubing 570 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING			
5 minutes	0	N/A	0	Steady Flow		N/A
10 minutes	0	N/A	0	Surges		N/A
15 minutes	0	N/A	0	Down to Nothing		N/A
20 minutes	0	N/A	0	Nothing	X	N/A
25 minutes	0	N/A	0	Gas		N/A
30 minutes	0	N/A	0	Gas & Water		N/A
				Water		N/A


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

West Bravo Dome Gas Unit 1929 - 141J



Elaine Hunter

By Elaine Hunter

Witness James Reece

Regulatory Technician
(Position)

E-mail address ehunter@hess.com

WBDGU 1929-141J
Annual Bradenhead Test (SI Well)

Year	Date	Tbg PSI	Csg PSI	Bleed Down Time
2013	2/13	590	0	
2014	2/19	590	0	
2015	01/08/2015	570		
2016				
2017				
2018				
2019				
2020				
2021				
2022				
2023				

Note: Well drilled in 2012 and SI as non-producer



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 1-8-2015 Operator Hess Corporation API # 30-021-20534

Property Name WBDGU Well No. 1 Location: Unit J Section 14 Township 19 Range 29

Well Status (Shut-In or Producing) Tubing 570 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING			
5 minutes	0	N/A	0	Steady Flow		N/A
10 minutes	0	N/A	0	Surges		N/A
15 minutes	0	N/A	0	Down to Nothing		N/A
20 minutes	0	N/A	0	Nothing	X	N/A
25 minutes	0	N/A	0	Gas		N/A
30 minutes	0	N/A	0	Gas & Water		N/A
				Water		N/A

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

West Bravo Dome Gas Unit 1929 - 141J

By Elaine Hunter Witness James Reece

Regulatory Technician
(Position)

E-mail address ehunter@hess.com

WBDGU 1929-141J
Annual Bradenhead Test (SI Well)

Year	Date	Tbg PSI	Csg PSI	Bleed Down Time
2013	2/13	590	0	
2014	2/19	590	0	
2015	01/08/2015	570		
2016				
2017				
2018				
2019				
2020				
2021				
2022				
2023				

Note: Well drilled in 2012 and SI as non-producer