Submit One Copy To Appropriate District	State of New Me	exico	Form C-103
Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu	ıral Resources	Revised November 3, 2011 WELL API NO.
<u>District II</u> 811 S. First St., Artesia, NM 88210			30-21-20061
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	rict III 1220 South St. Francis Dr.		5. Indicate Type of Lease  STATE ☐ FEE ☒
District IV Santa Fe, NM 8/505 1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Hayoz
1. Type of Well: Soil Well Gas Well Other			8. Well Number 001
2. Name of Operator			9. OGRID Number
Breitburn Operating LP  3. Address of Operator			370080 10. Pool name or Wildcat
1111 Bagby Street, Suite 1600 Houston, Texas 77002			Bravo Dome
4. Well Location			
Unit Letter: F 1980 feet from the North line and 1980 feet from the West line			
Section 12 Township 19N Range 30E NMPM County Harding  11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
4,600' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTEN			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ARANDON ALTERING CASING COMMENCE PRILLING ORDER OF RANDA			
			<del>_</del>
_			_
OTHER: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
<ul> <li>✓ All other environmental concerns have been addressed as per OCD rules.</li> <li>✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-</li> </ul>			
retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
Shelle Oresaken			
SIGNATURE Stelly Course	TITLE: <u>Age</u>	ent DATE	E: <u>12/23/2017</u>
TYPE OR PRINT NAME Shelly Doescher E-MAIL: shelly_doescher@yahoo.com PHONE: 505-320-5682			
For State Use Only			
APPROVED BY:	<u> </u>	Erginar	DATE
Conditions of Approval (if any):		S	• / (   • -