## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Te	st	2/11/2021		Operator Hilcorp Energy Company					API # 3004532689			
Property Name VALANCE 33			Well No.	2	Location: Unit	В	Section	33	Townshi	p <u>031N</u> Range	013W	
Well Status	s Flow	ing	Initial	PSI: Tubing <sub>_</sub>	81	Intermediate		Casing	) <u></u>	58 Bra	denhead 0	
OPE Testing TIME 5 min 10 min 15 min 20 min 25 min 30 min	BH 0 0	BRADENHE	PRESSUR			Steady F Surges Down to Nothing Gas Gas & W Water	Not	FI BRADE	LOW	CHARA	MINUTES EAC	_
CL	EAR_	FRE	SH	SALTY		hat apply below:	_	BLACK				
		·		•		hat apply below SULFUR		BI ACK				
	<del></del>	-IN PRESSU		denhead								
REMARKS BH had no		rom start to fir	nish all good	Well was s	shut in v	vhile test all good	•					
Tested By	Dani	el Rios-Tapia		W	itness							

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 18109

## **CONDITIONS OF APPROVAL**

Operator:			OGRID:	Action Number:	Action Type:
HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	372171	18109	BRADENHEAD TEST (3)

OCD Reviewer	Condition
mkuehling	None