

Office	State of New Mexico	Form C-103 ¹ of 5 Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	Minerals and Natural Resources	WELL API NO.
611 S. Filst St., Altesia, Nivi 66210	ONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd Aztec NM 87410	20 South St. Francis Dr.	STATE FEE X
1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REF		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL O DIFFERENT RESERVOIR. USE "APPLICATION FOR PER PROPOSALS.)	Northern Lights	
1. Type of Well: Oil Well 🗓 Gas Well 🗌	8. Well Number #1	
2. Name of Operator Armstrong Energy Corporation		9. OGRID Number 1092
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 1973 Roswell, NM 88202-19	773	
4. Well Location		
	from the South line and	2183 feet from the East line
	vnship 8S Range 29E (Show whether DR, RKB, RT, GR, etc.)	NMPM County Chaves
11. Elevation	(Show whether DK, KKB, KI, OK, etc.)
NOTICE OF INTENTION TO PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PLUG OF ALTER CASING MULTIPLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	REMEDIAL WORLD COMMENCE DE CASING/CEMEN OTHER: s. (Clearly state all pertinent details, as	BSEQUENT REPORT OF: RK
	ods, send pump to be shopped and visust tubing coming out of the well for he	
2. TOOH with pump and ros 3. RU tubing testers and tes 4. Replace any bad joints 5. TIH w/tbg 6. TIH w/pump and rods 7. Return well to production Spud Date: 5/3/1995	st tubing coming out of the well for ho	ole T
 TOOH with pump and ro RU tubing testers and testers Replace any bad joints TIH w/tbg TIH w/pump and rods Return well to production 	st tubing coming out of the well for ho	ole T
2. TOOH with pump and ros 3. RU tubing testers and tes 4. Replace any bad joints 5. TIH w/tbg 6. TIH w/pump and rods 7. Return well to production Spud Date: 5/3/1995 I hereby certify that the information above is true and	st tubing coming out of the well for ho	ole T
2. TOOH with pump and ros 3. RU tubing testers and tes 4. Replace any bad joints 5. TIH w/tbg 6. TIH w/pump and rods 7. Return well to production Spud Date: 5/3/1995	Rig Release Date:	ge and belief. DATE 5/20/2021

- 1. RUPU
- 2. TOOH with pump and rods, send pump to be shopped and visually inspect rods
- 3. RU tubing testers and test tubing coming out of the well for hole
- 4. Replace any bad joints
- 5. TIH w/tbg
- 6. TIH w/pump and rods
- 7. Return well to production









District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 29019

CONDITIONS

Ope	erator:	OGRID:
	ARMSTRONG ENERGY CORP	1092
	P.O. Box 1973	Action Number:
	Roswell, NM 88202	29019
		Action Type:
		[C-103] NOI Workover (C-103G)

CONDITIONS

Created By	Condition	Condition Date
jagarcia	None	8/4/2021