

**District II – Artesia**811 S. 1<sup>st</sup> Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575)-748-9720

**State of New Mexico**  
**Energy, Minerals and Natural Resources Department**  
**Oil Conservation Division Artesia District Office**

**BRADENHEAD TEST REPORT**

Operator Name BXP Operating, LLC	API Number 30-015-37025
Property Name WLH G4S UNIT	Well No. 45

**7. Surface Location**

UL - Lot N	Section 12	Township 18S	Range 29E	Feet from 660	N/S Line S	Feet From 1980	E/W Line W	County EDDY
---------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	----------------

**Well Status**

TA'D Well YES <input checked="" type="radio"/> NO	SHUT-IN YES <input checked="" type="radio"/> NO	INJECTOR <input checked="" type="radio"/> INJ SWD	PRODUCER OIL GAS	DATE 6-23-2021
--	--	--	---------------------	-------------------

**OBSERVED DATA**

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	1100
<b>Flow Characteristics</b>					
Puff	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	CO2 _____
Steady Flow	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	GAS _____
Down to nothing	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	If applicable type
Gas or Oil	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	fluid injected for
Water	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Butler Gadi</i>	<b>OIL CONSERVATION DIVISION</b>
Printed name: M. Y. Merchant	Entered RBDMS
Title: Production Manager	Re-test
E-mail Address: mymerch@Penrocoil.com	
Date: 6-23-2021	
Phone: 575-492-1236	
Witness:	

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 33889

CONDITIONS

Operator: BXP Operating, LLC P.O. Box 7227 Dallas, TX 75209	OGRID:
	329487
	Action Number:
	33889
Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)	

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	11/18/2021