



# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emrdd.state.nm.us/oed/District/III3district.htm>

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-2-21 Operator OXY USA API #30-0 21-20481  
Property Name Bravo Dome Unit Well No. 221 Location: Unit G Section 22 Township 19 Range 30  
Well Status(Shut-In or Producing) Initial PSI: Tubing\_\_\_ Intermediate\_\_\_ Casing 532 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| Testing | PRESSURE |                |            | INTERM |     |
|---------|----------|----------------|------------|--------|-----|
|         | BH       | Bradenhead Int | Csg        | Int    | Csg |
| TIME    |          |                |            |        |     |
| 5 min   | <u>0</u> | <u>N/A</u>     | <u>532</u> |        |     |
| 10 min  | <u>0</u> | <u>N/A</u>     | <u>532</u> |        |     |
| 15 min  | <u>0</u> | <u>N/A</u>     | <u>532</u> |        |     |
| 20 min  |          |                |            |        |     |
| 25 min  |          |                |            |        |     |
| 30 min  |          |                |            |        |     |

|                 | FLOW CHARACTERISTICS                |              |
|-----------------|-------------------------------------|--------------|
|                 | BRADENHEAD                          | INTERMEDIATE |
| Steady Flow     |                                     |              |
| Surges          |                                     |              |
| Down to Nothing |                                     |              |
| Nothing         | <input checked="" type="checkbox"/> |              |
| Gas             |                                     |              |
| Gas & Water     |                                     |              |
| Water           |                                     |              |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR\_\_\_ FRESH\_\_\_ SALTY\_\_\_ SULFUR\_\_\_ BLACK\_\_\_

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE\_\_\_

REMARKS: Braden head had OPSE & Production casing stayed at 532

By Scott Stephenson

Witness\_\_\_

(Position)

E-mail address Scott.Stephenson@oxy.com

**District I**

1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**

811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**

1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 68933

**CONDITIONS**

|                                                                    |                                                            |
|--------------------------------------------------------------------|------------------------------------------------------------|
| Operator:<br>OXY USA INC<br>P.O. Box 4294<br>Houston, TX 772104294 | OGRID:<br>16696                                            |
|                                                                    | Action Number:<br>68933                                    |
|                                                                    | Action Type:<br>[UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

**CONDITIONS**

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| mkuehling  | None      | 2/3/2022       |