

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Chevron USA Inc.</i>		API Number
Property Name <i>Vacuum Gravelburg San Andres Unit</i>		Well No. <i># 148</i>

1. Surface Location

UL - Lot <i>D</i>	Section <i>1</i>	Township <i>18S</i>	Range <i>34E</i>	Feet from <i>1330</i>	N/S Line <i>N</i>	Feet From <i>660</i>	E/W Line <i>W</i>	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	---------------

Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS ☐	DATE <i>6-30-21</i>
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>0</i>			<i>0</i>	<i>1700</i>
Flow Characteristics					
Puff	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	CO2 _____
Steady Flow	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	WTR _____
Surges	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	GAS _____
Down to nothing	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	If applicable type
Gas or Oil	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	fluid injected for
Water	Y ☒ N ☐	Y ☐ N ☐	Y ☐ N ☐	Y ☒ N ☐	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION
Printed name: <i>Eby Carmore</i>		Entered into RBDMS
Title: <i>FSA</i>		Re-test
E-mail Address: <i>ECarmore@Chevron.com</i>		<i>K 7</i>
Date: <i>6-30-21</i>	Phone: <i>575-200-6265</i>	
Witness:		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Chevron USA Inc.</i>		API Number <i>30-025-30917</i>
Property Name <i>Vacuum Hrayburg San Andres Unit</i>		Well No. <i>#150</i>

Surface Location									
UL Lot <i>2</i>	Section <i>1</i>	Township <i>18S</i>	Range <i>39E</i>		Feet from <i>1390</i>	N/S Line <i>N</i>	Feet From <i>1980</i>	E/W Line <i>E</i>	County <i>LEA</i>

Well Status					DATE
TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ INJ ☐ SWD	PRODUCER OIL ☐ GAS ☐		<i>6-29-21</i>

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>0</i>	<i>0</i>		<i>0</i>	<i>1800</i>
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	CO2 _____
Steady Flow	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	WTR _____
Surges	Y / ☒ N	Y / ☒ N	Y / ☒ N	Y / ☒ N	GAS _____
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	If applicable type
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	fluid injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION
Printed name: <i>Eloy Carmona</i>		Entered into RBDMS
Title: <i>FSA</i>		Re-test
E-mail Address: <i>Ecarmona@Chevron.com</i>		
Date: <i>6-29-21</i>	Phone: <i>575-200-6265</i>	
Witness:		

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Vacuum San Andres Unit Chevron USA INC	API Number 30-025- 20823
Property Name Chevron Concho Estate	Well No. 2

7. Surface Location

UL - Lot 1	Section 31	Township 17S	Range 35E	Feet from 660	N/S Line FSL	Feet From 1700	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING ☒	DATE 7-1-2021
-------------	---------	--	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0 psi	0 psi	N/A	25 psi	300 psi
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / N	
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / N	
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / N	
Down to nothing	☒ Y / N	☒ Y / N	Y / N	Y / N	
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR ☒	FRESH	SALTY	SULFUR	BLACK
--	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ____ WTR, ____ GAS, ____ CO2

Signature: Eric Abston	OIL CONSERVATION DIVISION
Printed name: Tanner DeHaan Eric Abston	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: TZVR@Chevron.com EAIW@Chevron.com	
Date: 7-1-2021	Phone: 575-390-4449 575-552-2517
Witness:	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>Chevron USA Inc.</i>		API Number <i>30-025-38140</i>	
Property Name <i>New Mexico "O" State Net - 1</i>		Well No. <i>#40</i>	

1. Surface Location								
UL - Lot <i>I</i>	Section <i>36</i>	Township <i>17S</i>	Range <i>34E</i>	Feet from <i>1885</i>	N/S Line <i>S</i>	Feet From <i>1978</i>	E/W Line <i>E</i>	County LEA

Well Status				
TA'D Well YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR INJ ☒ SWD	PRODUCER OIL ☒ GAS	DATE <i>7-7-21</i>

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>0</i>	<i>0</i>		<i>0</i>	<i>45</i>
Flow Characteristics					
Puff	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	CO2 _____
Steady Flow	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	WTR _____
Surges	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	GAS _____
Down to nothing	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	If applicable type
Gas or Oil	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	fluid injected for
Water	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Eloy Carmone</i>		Entered into RBDMS	
Title: <i>FSA</i>		Re-test	
E-mail Address: <i>ECarmone@Chevron.com</i>			
Date: <i>7-7-21</i>	Phone: <i>575-200-6265</i>		
Witness:			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 41726

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 41726
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	5/13/2022