

SAT 3

JAN

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENTHEAD TEST REPORT

Operator Name

API Number

Chevron USA Inc.

302-025-27967

Property Name
CENTRAL VACUUM UNITWell No.
159

Surface Location

U-Tube	Section	Location	Range	Feet In	Sec Line	Feet From	E-W Line	County
D	36	175	34E	1310	N	100	W	D.P.

Well Status

TAP WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☒	YES ☒	INJ ☒	OH ☐ GAS ☐	20 Jun 21

OBSERVED DATA

	Tapwell-Inject	Inject-Prod	Prod-Inject	Inject-Gas	Inject-Prod
Pressure	0	N/A	N/A	0	1500
Flow Characteristics					
Pull	☒ Y	☐ Y	☐ Y	☒ Y	UD
Steady Flow	☐ Y	☐ Y	☐ Y	☒ Y	WTR X
Surges	☐ Y	☐ Y	☐ Y	☒ Y	GAS
Down to nothing	☒ Y	☐ Y	☐ Y	☒ Y	Applicable if p
Gas or Oil	☐ Y	☐ Y	☐ Y	☒ Y	Prod Interval for
Water	☐ Y	☐ Y	☐ Y	☒ Y	Water level

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature

Van Bep

Printed name

Van Bep Tyrore

HANN

Title

FSA

E-mail Address

HANN@chevron.com

Date 20 June 21

Phone

Witness

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 39127

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 39127
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	6/13/2022