

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA, Inc.		API Number 30-025-31816	
Property Name Vacuum Blanks West Unit		Well No. 54	

Surface Location									
UL Lot B	Section 36	Township 17S	Range 34E	Feet from 51	N/S Line FNL	Feet from 1588	E/W Line FEL	LEA	County

TA'D Well		SHUT-IN		Well Status		PRODUCER		DATE	
YES	☒ NO	YES	☒ NO	☒ INJ	☐ SWD	OIL	GAS	6-14-21	

OBSERVED DATA

	(A) Surface	(B) Inj	(C) Inj	(D) Prod	(E) Type
Pressure	0	N/A	N/A	0	500
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name: Jesus Romero		Entered into RBDMS	
Title: Field Specialist		Re-test	
E-mail Address: jr@chevron.com			
Date: 6-14-21	Phone: 575-988-1256		
Witness:			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 39196

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 39196
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	6/13/2022