

Well Name: CANYON LARGO UNIT	Well Location: T25N / R6W / SEC 9 / NENW / 36.419784 / -107.475632	County or Parish/State: RIO ARRIBA / NM
Well Number: 480	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM019400	Unit or CA Name: DAKOTA	Unit or CA Number: NMNM120967
US Well Number: 3003930218	Well Status: Producing Gas Well	Operator: HILCORP ENERGY COMPANY

Notice of Intent

Sundry ID: 2691435

Type of Submission: Notice of Intent

Type of Action: Workover Operations

Date Sundry Submitted: 09/08/2022

Time Sundry Submitted: 01:52

Date proposed operation will begin: 10/03/2022

Procedure Description: Hilcorp Energy is requesting approval to repair the bradenhead for the subject well per the attached procedure.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Canyon_Largo__480_Bradenhead_NOI_20220908135114.pdf

Well Name: CANYON LARGO UNIT

Well Location: T25N / R6W / SEC 9 / NENW / 36.419784 / -107.475632

County or Parish/State: RIO ARRIBA / NM

Well Number: 480

Type of Well: CONVENTIONAL GAS WELL

Allottee or Tribe Name:

Lease Number: NMNM019400

Unit or CA Name: DAKOTA

Unit or CA Number: NMNM120967

US Well Number: 3003930218

Well Status: Producing Gas Well

Operator: HILCORP ENERGY COMPANY

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TAMMY JONES

Signed on: SEP 08, 2022 01:51 PM

Name: HILCORP ENERGY COMPANY

Title: Regulatory Compliance Specialist

Street Address: 382 ROAD 3100

City: AZTEC

State: NM

Phone: (505) 324-5185

Email address: tajones@hilcorp.com

Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK

BLM POC Title: Petroleum Engineer

BLM POC Phone: 5055647742

BLM POC Email Address: krennick@blm.gov

Disposition: Approved

Disposition Date: 09/08/2022

Signature: Kenneth Rennick

Bradenhead Repair - NOI

Canyon Largo Unit #480

API # - 3003930218

Procedure:

Hold PJSM prior to beginning any and all operations. Properly document all operations via the JSA process. Ensure that all personnel onsite abide by HEC safety protocol, including PPE, housekeeping, and standard guidelines.

Verify cathodic protection is off and wellhead instrumentation is properly disconnected from the wellhead. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.


Verify there is no H₂S present prior to beginning operations. If any H₂S is present, take the necessary actions to ensure that the location is safe prior to beginning operations.

Observe and record pressures across all string daily, prior to beginning operations.

Remember to notify NMOCD 24 hours prior to starting operations on location.

NOTE: This procedure is contingent upon sundry approval by NMOCD. All cement volumes use 100% excess outside pipe and 50' excess inside (unless otherwise stated). All cement will be Class G, mixed at 15.8 ppg w/ a 1.15 cf/sx yield. The stabilizing wellbore fluid will be an 8.3 ppg fluid, sufficient to balance all exposed formation pressures.

1. This project will use a steel tank to handle waste fluids circulated from the well and cement wash up.
2. Test anchors if not using a base beam. Comply with all NMOCD, BLM, and HEC safety regulations. MIRU and conduct safety meeting for all personnel on location.
3. Record casing, tubing, and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary. Ensure well is dead or on a vacuum.
4. ND wellhead and NU BOP, unseat tubing hanger and POOH laying down pipe.
5. PU & RIH with RBP and packer. Set RBP at $\pm 2,000'$, avoiding casing collars.
6. Roll and fill hole, PT to 500 PSI to check for casing or wellhead issue. Proceed to isolate casing leak if found. Hole suspected above 1,500' based on CBL.
7. Report findings to Houston and develop plan forward for remediation.
8. Contact NMOCD prior to proceeding with remediation.



District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 141841

CONDITIONS

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 141841
	Action Type: [C-103] NOI Workover (C-103G)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	None	10/7/2022