

OPERATOR'S COPY

Well Name: PURE GOLD D	Well Location: T23S / R31E / SEC 28 / SWSE /	County or Parish/State: EDDY / NM
Well Number: 12	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM40659	Unit or CA Name:	Unit or CA Number:
US Well Number: 3001527347	Well Status: Abandoned	Operator: OXY USA INCORPORATED

Accepted for record – NMOCD gc2/3/2023

Subsequent Report**Sundry ID:** 2709831**Type of Submission:** Subsequent Report**Type of Action:** Plug and Abandonment**Date Sundry Submitted:** 01/06/2023**Time Sundry Submitted:** 09:04**Date Operation Actually Began:** 01/09/2023**Actual Procedure:** Please see the attached final plugging report, and final plugged wellbore diagram. The well is now plugged.**SR Attachments****Actual Procedure**

Pure_Gold_D_Federal_012___Final_PA_Wellbore_Diagram_20230106090414.pdf

Pure_Gold_D_Federal_012___Final_PA_Report_20230106090355.pdf

**RECLAMATION
DUE 5-15-23**

Well Name: PURE GOLD D	Well Location: T23S / R31E / SEC 28 / SWSE /	County or Parish/State: EDDY / NM
Well Number: 12	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM40659	Unit or CA Name:	Unit or CA Number:
US Well Number: 3001527347	Well Status: Abandoned	Operator: OXY USA INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: SARAH MCKINNEY

Signed on: JAN 06, 2023 09:04 AM

Name: OXY USA INCORPORATED

Title: Regulatory Analyst Sr

Street Address: 5 GREENWAY PLAZA SUITE 110

City: HOUSTON

State: TX

Phone: (713) 215-7295

Email address: SARAH_MCKINNEY@OXY.COM

Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: JAMES A AMOS

BLM POC Title: Acting Assistant Field Manager

BLM POC Phone: 5752345927

BLM POC Email Address: jamos@blm.gov


Disposition: Accepted

Disposition Date: 01/10/2023

Signature: James A. Amos

Final Wellbore Diagram 1/6/2023

PURE GOLD D FEDERAL 012
30-015-27347-0000
Eddy



Pure Gold D Federal 012 - Final P&A Report

Start Date	Remarks
11/9/2022	DROVE RIG AND P&A ASSOCIATED EQUIP TO PURE GOLD D FED 12, SPOT IN EQUIP /
11/9/2022	RU KEY 6003, CMT PUMP, FLOWBACK LINES, FRAC TANKS, SPOT IN WIRELINE /
11/9/2022	DIG OUT CELLAR , REPLACED SURFACE VALVE /
11/9/2022	TBG 20 PSI /
11/9/2022	CSG 500 PSI /
11/9/2022	BLEED OFF PRESSURE TO FLOWBACK TANK /
11/9/2022	CHANGED TBG SIZE EQUIPMENT /
11/9/2022	ATTEMPTED TO ND 7 1/16 B1 ADAPTER, NOTICED 8RD PIN WAS BENT , DECIDED NOT TO PULL ON IT , CALLED IN FOR TBG SPEAR /
11/9/2022	UNLOAD AND SPOT IN TBG RACKS , 2 3/8 TBG WORKSTRING/
11/9/2022	SECURED WELL / SION
11/9/2022	DROVE CREW BACK TO YARD .
11/10/2022	DROVE CREW TO LOCATION
11/10/2022	TGSM W CREW MEMBERS
11/10/2022	TBG 0 PSI /
11/10/2022	CSG 50 PSI /
11/10/2022	BLEED OFF PRESSURE TO FLOWBACK TANK /
11/10/2022	PUMPED 20 BBLS 10# DOWN CSG , VACUUM, WELL STATIC /
11/10/2022	FUNCTION TEST 7 1/16 5K HYD BOP /
11/10/2022	ATTEMPTED TO RUN 2 7/8 - 2 3/8 TBG SPEAR , DID NOT WENT THROUGH , B-1 ADAPTER PIN WERE BENT , PERFORMED HOT PERMIT
11/10/2022	PRIOR TO CUT FLANGE PIN AND ND 7 1/16 FLANGE /
11/10/2022	NU 7 1/16 5K HYD BOP /
11/10/2022	RU RIG WORK FLOOR, SAFETY AUX EQUIP /
11/10/2022	RELEASE 5.5 45K TAC
11/10/2022	DROPPED TBG SV CUP TYPE, PUMPED 4 BBLS 10# DOWN TBG , PRESSURED UP TO 1500 PSI, HELD GOOD /
11/10/2022	RU WL ATTEMPTING TO SHOOT DRAIN HOLES , TAGGED UP @ 28' , RD WL /
11/10/2022	LD 1 JT 2 3/8 L-80 TBG AND HAD STEEL RODS INSIDE TBG /
11/10/2022	CHANGED TBG EQUIP FOR ROD EQUIP /
11/10/2022	UNSEAT ROD PUMP /
11/10/2022	SECURED WELL / SION .
11/10/2022	DROVE CREW BACK TO YARD
11/11/2022	DROVE CREW TO LOCATION
11/11/2022	TGSM W CREW MEMBERS /
11/11/2022	TBG 0 PSI
11/11/2022	CSG 50 PSI
11/11/2022	BLEED OFF PRESSURE / PUMPED 20 BBLS 10#, WELL STATIC/
11/11/2022	LD 54-1" SR KD , 81- 7/8 SR KD , 132- 3/4 SR KD , 8- 1.5 SINKER BARS, 7/8 RHR, 7/8 GUIDED SUB, 1.5 X 24 RHBC ROD PUMP /
11/11/2022	LUNCH /
11/11/2022	CHANGED ROD EQUIP X TBG EQUIP /
11/11/2022	TOH W 1 JT CERAMKOTE 2 7/8 , 218 JTS 2 7/8 L80 TBG, 4 FT TBG SUB, 2 JTS 2 7/8 L80, 5.5 TAC, 1 JT 2 7/8, 2 JTS 2 7/8 CERAMKOTE, 2 7/8
11/11/2022	SN CUP TYPE, 1" DIP TUBE INSIDE 2 7/8 12 SLOT SAND SCREEN 2 JTS MUD ANCHOR, 2 7/8 BULL PLUG /
11/11/2022	RU WL , RIH W 5.5 CIBP , SET @ 7010' RD WL /
11/11/2022	SECURED WELL / SION.
11/11/2022	DROVE CREW BACK TO YARD
11/12/2022	DROVE CREW TO LOCATION
11/12/2022	TGSM W CREW MEMBERS
11/12/2022	RIH TO VERIFY CIBP @ 7010' W 225 JTS 2 7/8 TBG , 8 FT TBG SUB /
11/12/2022	CIRC CLEAN WELL BORE W 160 BBLS 10#, SALT GEL
11/12/2022	POSITIVE CSG PRESSURE TEST @ 500 PSI /
11/12/2022	SPOT 75 SX CLASS 'C' CMT @ 7010' TOP OF CIBP, 14.8#, 1.32 YIELD, 11.25 MIX, 17.67 SLURRY
11/12/2022	LD 25 JTS 2 7/8 TBG , STOOD BACK 50 JTS 2 7/8 /
11/12/2022	SECURED WELL / SION
11/12/2022	DROVE CREW BACK TO YARD
11/14/2022	DROVE CREW TO LOCATION
11/14/2022	TGSM W CREW MEMBERS
11/14/2022	TBG 0 PSI
11/14/2022	CSG 0 PSI
11/14/2022	RIH TO TAG TOC @ 6290'
11/14/2022	LD 62 JTS 2 7/8 TBG
11/14/2022	SPOT 160 SX CLASS 'C' CMT @ 4299' 14.8#, 1.32 YIELD, 24 MIX, 37.71 SLURRY, 15.7 DISPLACEMENT
11/14/2022	LD 53 JTS 2 7/8 , STOOD BACK 50 JTS
11/14/2022	WOC

11/14/2022 RIH TO TAG TOC @ 2700'
11/14/2022 SPOT 135 SX CLASS 'C' CMT @ 2700', 14.8#, 1.32 YIELD, 20.25 MIX, 31.82 SLURRY
11/14/2022 LD 43 JTS 2 7/8 TBG , STOOD BACK 22 JTS
11/14/2022 SECURED WELL / SION
11/14/2022 DROVE CREW BACK TO YARD

11/15/2022 DROVE CREW TO LOCATION
11/15/2022 TGSM W CREW MEMBERS
11/15/2022 TBG 0 PSI /
11/15/2022 CSG 0 PSI /
11/15/2022 RIH TO TAG TOC @ 1291' /
11/15/2022 SPOT 120 SX CLASS 'C' @ 1291', 14.8#, 1.32 YIELD, 18 MIX, 28.28 SLURRY , DISP TO 106' W .6 BBLS /
11/15/2022 LD 41 JTS 2 7/8 TBG /
11/15/2022 WOC /
11/15/2022 RIH TO TAG TOC @ 130' /
11/15/2022 RU WL , PERF @ 125' /
11/15/2022 UNABLE TO GET INJECTION RATE , HOLDING 1800 PSI FOR 15 MIN NO LEAK OFF , BLM ON SITE DROP DOWN TO 130' / SPOT 15 SX CLASS
11/15/2022 'C' CMT , 14.8#, 1.32 YIELD, 2.25 MIX, 3.53 SLURRY, FILLED UP TO SURFACE /
11/15/2022 ND BOP / RD KEY 6003, P&A ASSOCIATED EQUIP /
X 11/15/2022 DROVE CREW BACK TO YARD

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 181957

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 181957
	Action Type: [C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	2/3/2023