

Surface Reclamation Complete Report

Well Name: ARCHIMEDES SWD #001

API: 30-015-10414

Well Location: J-18-21S-24E

Surface Owner: STATE OF NEW MEXICO

Reclamation Complete Date: 6/10/22

Total Acres reclaimed: 4.25 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
NMSLO - Loamy (L)	Plains Bristlegrass (Setaria vulpiseta)	1.0	2.0
п	Blue Grama	2.0	4.0
п	Sideoats Grama	2.0	4.0
п	Sand Dropseed	1.0	2.0
п	Alkali Sacaton	2.5	5.0
п	Little Bluestem	2.5	5.0
п	Firewheel (Gaillardia)	1.0	2.0
п	Fourwing Saltbush	1.0	2.0
п	Common Winterfat	0.5	1.0
Weights should be as pounds of pure live s	seed.	_	

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

Corrective actions complete-2/16/23





On-Site Regulat	ory Reclamat	ion Inspection			Date:	2 /16 / 20	023		
Site Name:	Archimedes	SWD #001							
						□ Init	ial Monitoring		
API Number: Facility Site-	30-0 15 - No associated well on		Date:	/ 21 / 2022	_ In	spection: Act	ive Corrective	YES	NO
Was this the last remain	ing or only well on t	the location?				182	-	V	110
	•	going to remian on the lo	cation?						
Is there any production	equipment or struct	ture (not including steel m	arker, poured onsite co	oncrete bases, or p	ipelines) that an	e going to remain	on location?	V	
If any production equipm	nent or structure (in	ncluding 3rd party) is to re	main on location, pleas	se specify.				_	
Site Evaluation									
Recontoured back to								YES	NO
Have the rat hole and ce Have the cathodic prote		ieveled? operly abandoned & redai	med?					- ×	
Rock or Caliche Surfacing									
Section Comments:	•							,	
All Facilities Removed	for Final Reclam	ation							
Have all of the pipelines	& production equip	ment been cleared? (othe	r than the listed above)				✓	
		cleared from the location?							
		tie downs and risers have er materials have been rer		wo feet below grou	ind level?			V	
Have all the required po			novear					V	
Section Comments:	THE PERSON NAMED IN COLUMN	anorea.						V	
Dry Hole Marker								YES	NO
					Dec 4 Dec 1	Buried	✓ Above Ground		
Has a steel marker been	installed per COA re	equirements:			Check One:	Burned	M Above Ground	V	
Required DHM Inform	ation:	Operator Name	UL or Qtr/Qtr	API Number	County	Feder	ral Lease # (Fed Only)		
		Lease Name & Number	Sec-Twn-Rng	Footage	DYP&A Date				
Free of Oil or Salt Con	taminated Soil							YES	NO
Have all the required pit	s been remediated i	in compliance with OCD ru	iles and the terms of th	ne Operator's pit p	ermit and closur	e plan?		✓	
Have all other environm	ental concerns beer	n addressed as per OCD rul	e!					✓	
If any environmental cor	ncerns remain on th	e location, please specify.						_	
								_	
Abandoned Pipelines		if any pipelines have been a	ahandanad (in accorda	ncowith 19 15 25	TONMAC			YES	NO
Have all fluids have been			accorde (in accorde		. 20 1111040			123	1
Have all abandoned pipe	lines been confirme	ed to <u>NOT</u> contain addition	nal regulated NORM , o	ther than that whi	ch accumulated	under normal op	eration?		
Have all accessible point	s of abandoned pip	elines been permanently o	apped?						/
Section Comments:									
Last Remaining or On						en in transfer		WEE.	
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.				YES	NO				
Have all electrical service poles and lines been removed from the location? Is there any electrical utility distribution infrastructure that is remaining on the location?				- ×					
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?									
Have all the retrievable pipelines, production equipment been removed from the location?									
Has all the junk and trash been removed from the location?			✓						
Section Comments:									
iEnvironmental Only-									
		he Reclamation Inspection pecies or treatment in rem		al but not related t	o NMOCD forms			Met	Not Met
Site Stability? Erosion co								- V	
Signs of seeding complet									
Revegetation Success as	compared to backg		Circle	e One: Of	25%	50%	75% 100%		✓
Adequate Reclamation F	ence installed?							V	
Section Comments:									
Additional Findings or	Comments:	Inspection sweep	p completed; all	trash/junk rer	noved. Trac	ks removed.			
Inspector: B. Madi	id							R FAN SUBMITTAL RTHER REVIEW	
							Insp	ection Result	
Picture Checklist:	☑ DHM	Background	☐ 3rd Party Equipment				PASS	○ F/	AIL
	M Site Corners	Access Road	☐ EOG Equipment	☐ Trash/Jun	·				

On-Site_Inspection_Form v1.xlsx 2/13/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 190043

DEFINITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	190043
Γ.	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 190043

Q	UESTIONS	
Operator: EOG RESOURCES INC	OGRID: 7377	
P.O. Box 2267 Midland, TX 79702	Action Number: 190043	
	Action Type: [C-103] Sub. Release After P&A (C-103Q)	
QUESTIONS		
Subsequent Report of: Location Ready For OCD Inspection After P&A		
Was this the last remaining or only well on the location	Yes	
Are there any abandoned pipelines that are going to remain on the location	No	
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	Yes	
If any production equipment or structure is to remain on the location, please specify	Not answered.	
Site Evaluation Please answer all the questions in this group.		
Have all the required pits been remediated in compliance with OCD rules and the		
terms of the Operator's pit permit and closure plan	Yes	
Have the rat hole and cellar been filled and leveled	Yes	
Have the cathodic protection holes been properly abandoned	Yes	
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes	
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.	
Has the location been leveled as nearly as possible to original ground contour	Yes	
Have all the required pipelines and other production equipment been cleared	Yes	
Has all the required junk and trash been cleared from the location	Yes	
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes	
Have all the required metal bolts and other materials have been removed	Yes	
Poured onsite concrete bases do not have to be removed.		
Have all the the required portable bases been removed	Yes	
Have all other environmental concerns have been addressed as per OCD rules	Yes	
If any environmental concerns remain on the location, please specify	Not answered.	

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

Released to Imaging: 3/2/2023 8:47:36 AM

* Proof of the site marker (photograph) is required.

QUESTIONS

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 190043

QUESTIONS (continued)			
Operator:	OGRID:		
EOG RESOURCES INC	7377		
P.O. Box 2267	Action Number:		
Midland, TX 79702	190043		
	Action Type:		
	[C-103] Sub. Release After P&A (C-103Q)		

Abandoned Pipelines Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC). Have all fluids have been removed from any abandoned pipelines Not answered. Have all abandoned pipelines been confirmed to **NOT** contain additional regulated Not answered. NORM, other than that which accumulated under normal operation Have all accessible points of abandoned pipelines been permanently capped Not answered.

Last Remaining or Only Well on the Location			
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.			
Have all electrical service poles and lines been removed from the location	Yes		
Is there any electrical utility distribution infrastructure that is remaining on the location	Yes		
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes		
Have all the retrievable pipelines, production equipment been removed from the location	Yes		
Has all the junk and trash been removed from the location	Yes		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 190043

ACKNOWLEDGMENTS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	190043
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 190043

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	190043
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	3/1/2023