

Surface Reclamation Complete Report

Well Name: NEW MEXICO ES STATE COM #001

API: 30-015-25272

Well Location: O-07-19S-24E

Surface Owner: STATE OF NEW MEXICO

Reclamation Complete Date: 11/2/22

Total Acres reclaimed: 2.5

Seed Mix:

Mix	Species	lb/acre (Drilled)	Ib/acre (Broadcast)
NMSLO - Loamy (L)	Black Grama	2.0	4.0
u u	Blue Grama	2.0	4.0
"	Sideoats Grama	2.0	4.0
"	Sand Dropseed	1.0	2.0
"	Alkali Sacaton	2.5	5.0
11	Little Bluestem	2.5	5.0
Weights should be as pounds of pure li	ve seed.		

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

3rd party riser and valve box on the west side of pad by road.







On-Site Regulate	orv Reclama	tion Inspect	ion			Date:	11 / 0	2,2022			
	-										
Site Name: New Mexico ES State Com #001											
API Number:	30-0 15 . 2	5272	Plug Date:	02 / 14	/ 2022		Program:	Initial	Monitoring		
			-					Final	Corrective	YES	NO
Was this the last remaini	ng or only well on	the location?									
Are there any abandones	-		on the location?								_
is there any production e	equipment or struc	ture (not includir	ng steel marker, pour	ed onsite concrete	bases, or pi	pelines) that a	ire going to	remain on lo	cation?		
If any production equipm	nent or structure (i	ncluding 3rd part	ty) is to remain on loc	ation, please spec	ify.	3rd pa	rty riser	and valve	box on the		
west side of pad	by road.										
Site Evaluation											
Recontoured back to	original State/To	osoil Replaced								YES	NO
Have the rat hole and ce										1	
Have the cathodic protect	tion holes been pr	operly abandone	ed & reclaimed?							1	
Rock or Caliche Surfacing	materials have be	en removed?									
Section Comments:											
All Facilities Removed	for Final Redam	nation									
Have all of the pipelines	& production equip	pment been dear	red? (other than the li	isted above)						_	
Has all of the required ju											
Have all of the required a				ff at least two feet	t below grour	nd level?					
Have all of the required re Have all the required por			e been removed?							·/	
	table bases been i	emoveur									
Section Comments:											
Dry Hole Marker										YES	NO
Has a steel marker been	installed per COA r	requirements?				Check One:	☐ Burk	rd 💆	Above Ground	✓	
		Lease Na	me & Number						Federal Lease #		
DHM Info	Operator Nar		_	UL-S-T-R	Otr Section	(footage)	A	P1#	(Federal Only)		
Met Not Met			/	· ·		V		<u> </u>			
Free of Oil or Salt Con	taminated Soil									YES	NO
Have all the required pits	been remediated	in compliance w	ith OCD rules and the	terms of the Ope	rator's pit pe	rmit and close	ure plan?				
Have all other environme											
If any environmental con	cerns remain on th	ne location, pleas	e specify.								
Abandoned Pipelines											
Only need to provide ans				(in accordance wi	th 19. 15. 35.	10 NMAC).				YES	NO
Have all fluids have been											
Have all abandoned pipe				d NORM , other ti	nan that whic	th accumulate	ed under no	rmai operatio	one	\rightarrow	<u> </u>
Have all accessible points	s of abandoned pip	elines been pern	nanently capped?							-	-
Section Comments: Last Remaining or Onl	w Well on the Lo	ation									
Mease answer all question			offy if there is no longs	er aging to be any	well or facilit	tu nemainina a	of this locat	line		YES	NO
Have all electrical service				a going to be any	west or judge	y remaining a	a tritarioca.	, one		7	110
				cation?							$\overline{}$
is there any electrical utility distribution infrastructure that is remaining on the location? Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?					/						
Have all the retrievable pipelines, production equipment been removed from the location?											
Has all the junk and trash been removed from the location?											
Section Comments:											
iEnvironmental Only-	Do not have to be	met to pass inspe	ection								
This section corresponds				nvironmental but i	not related to	NMOCD form	15.			Met	Not Met
Free of Noxious or Invasi											
Site Stability? Erosion co			ung.								
Signs of seeding complet Revegetation Success as			%.	Circle One:	0%	25%	509	6 75%	100%		_
Adequate Reclamation F		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				,	-			N	A
Section Comments:											
Additional Findings or	Comments:										
Inspector: Igor Rio	5								READY FOR FA		
Inspector: Igor Kio	_			_					Income di la constanti	on Result	
Picture Checklist:	T DHM	M Background	NO and Park	ty Equipment	Contamina	tion П_					
	Site Comers	Access Road			Trush/Junk				PASS	O FA	AIL .
										_	

On-Site_Inspection_Form v1.xlsx 10/20/2022

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 158571

DEFINITIONS

Operator		OGRID:
	EOG RESOURCES INC	7377
	P.O. Box 2267	Action Number:
	Midland, TX 79702	158571
		Action Type:
		[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 158571

Q	UESTIONS	
Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702		OGRID: 7377 Action Number: 158571
		Action Type: [C-103] Sub. Release After P&A (C-103Q)
QUESTIONS		
Subsequent Report of: Location Ready For OCD Inspection After P&A		
Was this the last remaining or only well on the location	Yes	
Are there any abandoned pipelines that are going to remain on the location	No	
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	Yes	
If any production equipment or structure is to remain on the location, please specify	3rd party riser and valve	box on the West side of the pad by the road.
Site Evaluation		
Please answer all the questions in this group.	1	
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes	
Have the rat hole and cellar been filled and leveled	Yes	
Have the cathodic protection holes been properly abandoned	Yes	
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes	
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	LETTER, SECTION, TOW	LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT NSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE /ED INTO THE MARKER'S METAL.
Has the location been leveled as nearly as possible to original ground contour	Yes	
Have all the required pipelines and other production equipment been cleared	Yes	
Has all the required junk and trash been cleared from the location	Yes	
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes	
Have all the required metal helts and other metarials have been removed	Vac	

Yes

Yes

Not answered.

* Proof of the site marker (photograph) is required.

Poured onsite concrete bases do not have to be removed. Have all the the required portable bases been removed

Have all other environmental concerns have been addressed as per OCD rules

If any environmental concerns remain on the location, please specify

Please submit any other site photographs that would assist in documenting the above answers, site features, addtional concerns, or other nearby / remaing structures and equipment.

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 158571

QUESTIONS (continued)			
Operator:	OGRID:		
EOG RESOURCES INC	7377		
P.O. Box 2267	Action Number:		
Midland, TX 79702	158571		
	Action Type:		
	[C-103] Sub. Release After P&A (C-103Q)		

QUESTIONS

Abandoned Pipelines			
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).			
Have all fluids have been removed from any abandoned pipelines	Not answered.		
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.		
Have all accessible points of abandoned pipelines been permanently capped	Not answered.		

Last Remaining or Only Well on the Location				
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.				
Have all electrical service poles and lines been removed from the location	Yes			
Is there any electrical utility distribution infrastructure that is remaining on the location	No			
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes			
Have all the retrievable pipelines, production equipment been removed from the location	Yes			
Has all the junk and trash been removed from the location	Yes			

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 158571

ACKNOWLEDGMENTS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	158571
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 158571

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	158571
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	12/19/2022