



Surface Reclamation Complete Report

Well Name: SHERELL SR COM #001

API: 30-015-24073

Well Location: L-32-17S-26E

Surface Owner: HERRY SHERRELL

Reclamation Complete Date: Will be conducted by LO

Total Acres reclaimed: 1.10

Seed Mix:

Do not bring in topsoil or reseed the area, per rec plan.


Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.

Buried DHM



Jerry & Angel Sherrell has agreed to leave tubing, casing and will reclaim well pad per attached signed letter therefor EOG will not be responsible for anything after reclamation is completed by landowner.


Surface Owner Approval of Reclamation completed with Well P&A

Well Name: Sherrell SR Com #001
API: 30-015-24073
Location: NW/4SW/4 being approximately 1.10 acres in total area.
Section: 32
Township: 17 South
Range: 26 East
County: Eddy

Surface owner: Jerry & Angel Sherrell
24 Crystal Dr. R 370 South 13th
Artesia, NM 88210

I hereby agree that EOG Resources, Inc. has agreed to leave the tubing from the well bore that is on location and landowner will remove the casing as well as reclaiming the well pad, therefore EOG will not be responsible for anything after reclamation is completed by such landowner.

Surface Owner Name: Jerry & Angel Sherrell
Surface Owner Signature: C. Jerry Sherrell

EOG Representative Name: Keith Kistner
EOG Representative Signature: Keith Kistner
Date: 3/1/2023

On-Site Regulatory Reclamation Inspection		Date:	3 / 07 / 2023	
Site Name: Sherrell SR Com #1				
API Number: 30-015-24073		Plug Date: 06 / 28 / 2022		Inspection: <input checked="" type="checkbox"/> Initial <input type="checkbox"/> Monitoring <input type="checkbox"/> Active <input type="checkbox"/> Corrective <input type="checkbox"/> Final
<input type="checkbox"/> Facility Site-No associated well on location				
Was this the last remaining or only well on the location?		YES NO		
Are there any abandoned pipelines that are going to remain on the location?		YES NO		
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?		YES NO		
If any production equipment or structure (including 3rd party) is to remain on location, please specify.				
Site Evaluation				
Recontoured back to original State/Topsoil Replaced		YES NO		
Have the rat hole and cellar been filled and leveled?		YES NO		
Have the cathodic protection holes been properly abandoned & reclaimed?		YES NO		
Rock or Caliche Surfacing materials have been removed?		YES NO		
Section Comments:				
All Facilities Removed for Final Reclamation		YES NO		
Have all of the pipelines & production equipment been cleared? (other than the listed above)		YES NO		
Has all of the required junk and trash been cleared from the location?		YES NO		
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?		YES NO		
Have all of the required metal bolts and other materials have been removed?		YES NO		
Have all the required portable bases been removed?		YES NO		
Section Comments:				
Dry Hole Marker		YES NO		
Has a steel marker been installed per COA requirements?		YES NO		
Check One: <input checked="" type="checkbox"/> Buried <input type="checkbox"/> Above Ground				
Required DHM Information:		<input checked="" type="checkbox"/> Operator Name <input checked="" type="checkbox"/> UL or Qtr/Qtr <input checked="" type="checkbox"/> API Number <input checked="" type="checkbox"/> County <input type="checkbox"/> Federal Lease # (Fed Only) <input checked="" type="checkbox"/> Lease Name & Number <input checked="" type="checkbox"/> Sec-Twn-Rng <input checked="" type="checkbox"/> Footage <input checked="" type="checkbox"/> P&A Date		
Free of Oil or Salt Contaminated Soil		YES NO		
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?		YES NO		
Have all other environmental concerns been addressed as per OCD rules?		YES NO		
If any environmental concerns remain on the location, please specify.				
Abandoned Pipelines				
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).		YES NO		
Have all fluids have been removed from any abandoned pipelines?		YES NO		
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?		YES NO		
Have all accessible points of abandoned pipelines been permanently capped?		YES NO		
Section Comments:				
Last Remaining or Only Well on the Location		YES NO		
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.		YES NO		
Have all electrical service poles and lines been removed from the location?		YES NO		
Is there any electrical utility distribution infrastructure that is remaining on the location?		YES NO		
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?		YES NO		
Have all the retrievable pipelines, production equipment been removed from the location?		YES NO		
Has all the junk and trash been removed from the location?		YES NO		
Section Comments:				
Environmental Only- Do not have to be met to pass inspection				
This section corresponds with questions on the Reclamation Inspection Form in iEnvironmental but not related to NMOCD forms.		Met Not Met		
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)		Met Not Met		
Site Stability? Erosion controls in place (if necessary) & working.		Met Not Met		
Signs of seeding completion? (Broadcast/Drilled)		Met Not Met		
Revegetation Success as compared to background? Met >75%.		Met Not Met		
Adequate Reclamation Fence Installed?		Met Not Met		
Section Comments:				
Additional Findings or Comments: land owner will reclaim location				
Inspector: Igor Rios				
Picture Checklist:		<input type="checkbox"/> DHM <input type="checkbox"/> Background <input type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/> <input checked="" type="checkbox"/> Site Corners <input type="checkbox"/> Access Road <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/>		
		<input type="checkbox"/> READY FOR FAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW		
		Inspection Result		
		<input checked="" type="radio"/> PASS <input type="radio"/> FAIL		

On-Site_Inspection_Form v1.xlsx

2/13/2023

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 201871

DEFINITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 201871
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 201871

QUESTIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 201871
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

QUESTIONS

Subsequent Report of: Location Ready For OCD Inspection After P&A	
Was this the last remaining or only well on the location	Yes
Are there any abandoned pipelines that are going to remain on the location	No
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	Yes
If any production equipment or structure is to remain on the location, please specify	Reclamation will be conducted by Land owner. Dry hole marker is buried.

Site Evaluation

Please answer all the questions in this group.

Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have the rat hole and cellar been filled and leveled	Yes
Have the cathodic protection holes been properly abandoned	Yes
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Not answered.
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.
Has the location been leveled as nearly as possible to original ground contour	Yes
Have all the required pipelines and other production equipment been cleared	Yes
Has all the required junk and trash been cleared from the location	No
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes
Have all the required metal bolts and other materials have been removed	No

Poured onsite concrete bases do not have to be removed.

Have all the the required portable bases been removed	Yes
Have all other environmental concerns have been addressed as per OCD rules	Yes
If any environmental concerns remain on the location, please specify	Not answered.

* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 201871

QUESTIONS (continued)

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 201871
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

QUESTIONS**Abandoned Pipelines**

Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).

Have all fluids have been removed from any abandoned pipelines	Not answered.
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.
Have all accessible points of abandoned pipelines been permanently capped	Not answered.

Last Remaining or Only Well on the Location

Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.

Have all electrical service poles and lines been removed from the location	Yes
Is there any electrical utility distribution infrastructure that is remaining on the location	No
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have all the retrievable pipelines, production equipment been removed from the location	Yes
Has all the junk and trash been removed from the location	Yes

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 201871

ACKNOWLEDGMENTS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 201871
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

<input checked="" type="checkbox"/>	I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.
-------------------------------------	--

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 201871

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 201871
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	4/4/2023