

Surface Reclamation Complete Report

Well Name: BOZARTH UC #001

API: 30-005-61537

Well Location: P-22-07S-25E

Surface Owner: BUCKEYE WATER LLC (BEN PEARCE)

Reclamation Complete: 7/24/17





On-Site Regulatory Reclamation Inspection	Date: 3 /29/ 25		
Site Name: BOZARTH UC #001			
API Number: 30.0 05 . 41537 Plug Date:		onitoring arrective YES	NO.
Was this the last remaining or only well on the location?		X	NO
Are there any abandoned pipelines that are going to remian on the location?		3	×,
Is there any production equipment or structure (not including steel marker, pour)	X
If any production equipment or structure (including 3rd party) is to remain on lo	ation, please specify.	E	
ally a state of			
Site Evaluation			
Recontoured back to original State/Topsoil Replaced Have the rat hole and cellar been filled and leveled?		YES	NO
Have the cathodic protection holes been properly abendoned & reclaimed?		2	
Rock or Caliche Surfacing materials have been removed?		Ŷ	
Section Comments:			
All Facilities Removed for Final Reclamation			
Hove all of the pipelines & production equipment been cleared? (other than the	Isted above)	, ,	<u> X</u>
Has all of the required junk and trash been cleared from the location? Have all of the required anchors, dead men, tie downs and risers have been out of	ff of least two foot below accord book?	- X	
Have all of the required metal bolts and other materials have been removed?	and the seed record Records leaves	- X	
Have all the required portable bases been removed?		Ŷ	
Section Comments: AGAVE RISER PIPELIN€	ON PAD	1000	(3)
Dry Hole Marker		YES	NO
Has a steel marker been installed per COA requirements?	Check One: ☐ Burled	Ground X	
.,		No. 24 (1998)	755 V
	or Qts/Qtr	101M	
* * * * * * * * * * * * * * * * * * * *	-Twe-Ring ☐ Footage		
Free of Oil or Salt Contaminated Soil		YES	NO
Have all the required pits been remediated in compliance with OCD rules and the	terms of the Operator's pit permit and closure plan?	- X	
Have all other environmental concerns been addressed as per OCD rules?		X	
If any environmental concerns remain on the location, please specify.			
Abandoned Pipelines		100 Marie	
Only need to provide answers in this group, if any pipelines have been abandoned	(in accordance with 19. 15. 35. 10 NMAC).	YES 1	NO
Have all fluids have been removed from any abandoned pipelines?			
Have all abandoned pipelines been confirmed to NOT contain additional regulate	d NORM, other than that which accumulated under normal operation?		
Have all accessible points of abandoned pipelines been permanently capped?			-
Section Comments: Last Remaining or Only Well on the Location		20177.50	
Please answer all questions that apply in this group, specifically if there is no long	or gaing to be any well or facility remaining at this location.	YES	NO
Have all electrical service poles and lines been removed from the location?		X	
is there any electrical utility distribution infrastructure that is remaining on the lo		2	х
Have all the battery and pit location(s) have been remediated in compliance with		X	
Have all the retrievable pipelines, production equipment been removed from the Has all the Junk and trash been removed from the location?	location?	X .	
		K	No.
Section Comments: VEnvironmental Only: Do not have to be met to pass inspection			
This section corresponds with questions on the Reclamation Inspection Form in IE	wironmental but not related to NMOCD forms.	Met Not	ot Met
Free of Navious or Invasive Weeds? (Note species or treatment in remarks)		X.	
Site Stability? Erosion controls in place (if necessary) & working.		X.	
Signs of seeding completion? (Broadcast/Drilled) Revegetation Success as compared to background? Met >75%.	Circle One: 0% 25% 50% 75%	100%	
Adequate Reclamation Fence Installed?	Citationic: USS 25% 50% 75%	W V	-
		- A	1
Section Comments:	I	in terms of the contract	
Additional Findings or Comments: AGAVE PISED THE ROAD TO INSPECT THEIR	PIPELINE ON PAD, AGAVE	13 STILL ACCESSIO	Ne
THE WORD TO INSPECT THEIR	EQUIPMENT.		
		READY FOR FAN SUBMITTAL	
Inspector: C. PETERSON		☐ NEEDS FURTHER REVIEW	
v		Inspection Result	
	y Equipment Contamination C	PASS FAIL	
Site Corners	śprnem □Trash/tunk □		
On-Site_Inspection_Form v1.xlsx		2/13	3/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 207794

DEFINITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	207794
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 207794

Q	UESTIONS	
Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702		OGRID: 7377 Action Number: 207794 Action Type:
		[C-103] Sub. Release After P&A (C-103Q)
QUESTIONS		•
Subsequent Report of: Location Ready For OCD Inspection After P&A		
Was this the last remaining or only well on the location	Yes	
Are there any abandoned pipelines that are going to remain on the location	No	
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	No	
If any production equipment or structure is to remain on the location, please specify	Agave Riser/pipeline on	pad
Site Evaluation		
Please answer all the questions in this group.		
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes	
Have the rat hole and cellar been filled and leveled	Yes	
Have the cathodic protection holes been properly abandoned	Yes	
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes	
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	LETTER, SECTION, TOW	LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT NSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE /ED INTO THE MARKER'S METAL.
Has the location been leveled as nearly as possible to original ground contour	Yes	
Have all the required pipelines and other production equipment been cleared	No	
Has all the required junk and trash been cleared from the location	Yes	
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes	
Have all the required metal bolts and other materials have been removed	Yes	
Poured onsite concrete bases do not have to be removed.		
Have all the the required portable bases been removed	Yes	
Have all other environmental concerns have been addressed as per OCD rules	Yes	
If any environmental concerns remain on the location, please specify	Not answered.	

Please submit any other site photographs that would assist in documenting the above answers, site features, addtional concerns, or other nearby / remaing structures and equipment.

* Proof of the site marker (photograph) is required.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 207794

QUESTIONS	(continued)
QUESTIONS:	COHUHUCU <i>i</i>

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	207794
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

QUESTIONS

Abandoned Pipelines		
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).		
Have all fluids have been removed from any abandoned pipelines	Not answered.	
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.	
Have all accessible points of abandoned pipelines been permanently capped	Not answered.	

Last Remaining or Only Well on the Location	
Please answer all questions that apply in this group, specifically if there is no longer going to be an	ny well or facility remaining at this location.
Have all electrical service poles and lines been removed from the location	Yes
Is there any electrical utility distribution infrastructure that is remaining on the location	No
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have all the retrievable pipelines, production equipment been removed from the location	Yes
Has all the junk and trash been removed from the location	Yes

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 207794

ACKNOWLEDGMENTS

Operator: C	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267 Midland, TX 79702	Action Number: 207794
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 207794

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	207794
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	4/25/2023