

Surface Reclamation Complete Report

Well Name: CROW ASM STATE COM #002H

API: 30-015-37061

Well Location: A-32-16S-28E

Surface Owner: STATE OF NM

Reclamation Complete Date:


Total Acres reclaimed: 2.75 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
NMSLO - Loamy (L)	Plains Bristlegrass (Setaria vulpiseta)	1.0	2.0
"	Blue Grama	2.0	4.0
п	Sideoats Grama	2.0	4.0
п	Sand Dropseed	1.0	2.0
"	Alkali Sacaton	2.5	5.0
п	Little Bluestem	2.5	5.0
п	Firewheel (Gaillardia)	1.0	2.0
"	Fourwing Saltbush	1.0	2.0
п	Common Winterfat	0.5	1.0
Weights should be as pounds of pure liv	e seed. Revised 10/20/2022 per NMSLO & EOG Regulatory/	Artesia.	

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2024 to determine if successful vegetation regrowth is established.





On-Site Regulate	ory Reclamat	ion Inspection			Date:	4/17/20	023		
Site Name:	CROW ASM	STATE COM #002	2H						
Site Name:						□ Initi	ial Monitoring		
API Number:	30-015	37061 Plug l	Date:11	1 / 23/ 2022	In	spection: Act			
☐ Facility Site-I	No associated well on	location				√fine		YES	NO
Was this the last remaini								V	
		going to remian on the loc							✓
Is there any production e	equipment or struct	ure (not including steel m	arker, poured onsite o	oncrete bases, or pi			on location? ocher on south side	/	
If any production equipm	nent or structure (in	iduding 3rd party) is to re	main on location, pleas	se specify.	oru party	riser ox iduit	icher on south side	_	
Site Evaluation									
Recontoured back to								YES	NO
Have the rat hole and cel		leveled? operly abandoned & reciai						V	
Rock or Caliche Surfacing			medr					· /	
								,	
Section Comments: All Facilities Removed	for Final Reclams	ation						_	
		ment been deared? (othe	r than the listed above	e)				_	
Has all of the required ju	nk and trash been o	leared from the location?						V	
		tie downs and risers have		wo feet below grou	nd level?			_/	
		er materials have been rer	noved?						
Have all the required por	rtable bases been re	moved?							
Section Comments:									
Dry Hole Marker								YES	NO
Has a steel marker been	installed per COA re	equirements?			Check One:	☐ Burled	M Above Ground	✓	
Required DHM Inform	ation:	Operator Name	Ø u. or ge/ge	API Number	M County	☐ feder	ral Lease # (Fed Only)		
nequires or invitation in	20011	☑ Lease Name & Number	Sec-Twn-Rng	Footage					
		M resie wane or written	Mi sec-ren-ing	Mr roctage	☑ PSA Date				
Free of Oil or Salt Con		in compliance with OCD or	les and the terms of th	ha Consented alternation	make and decreased	nino?		YES	NO
		in compliance with OCD ru addressed as per OCD rul		ne Operator's pit pe	mit and dosure	peanr		V	
								,	
If any environmental con	icems remain on th	e location, please specify.							
Abandoned Pipelines									
Only need to provide ans	wers in this group, i	f any pipelines have been a	abandoned (in accordo	once with 19. 15. 35	10 NMAC).			YES	NO
Have all fluids have been									/
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation?									
	s of abandoned pipe	elines been permanently o	apped?						•
Section Comments: Last Remaining or Onl	w Well on the Loc	-ti						_	
			e is no longer going to	he any well or facili	ty remaining at t	this Investion		YES	NO
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location. Have all electrical service poles and lines been removed from the location?					V				
		astructure that is remaining							
Have all the battery and	pit location(s) have	been remediated in comp	liance with OCD rules	and the terms of th	e Operator's pit	permit and closu	re plan?		
Have all the retrievable pipelines, production equipment been removed from the location?									
Has all the junk and trash been removed from the location?			V						
Section Comments:				_					
iEnvironmental Only-									
		he Redamation Inspection		al but not related to	NMOCD forms.			Met	Not Met
Site Stability? Erosion co		pecies or treatment in rem pressary! & working.	ericaj					V	
Signs of seeding complet								· /	
Revegetation Success as			Circl	le One: 0%	25%	50%	75% 100%		
Adequate Reclamation Fo	ence installed?							V	
Section Comments:									
	Comments	Inspection sweep	o completed: all	trash/junk ren	oved				
Additional Findings or	comments:			,					
□ READY FOR FAN SUBMITTAL									
Inspector: B. Madrid					CER REVIEW				
	_						Inspec	tion Result	
	☑ DHM ☑ Site Comers	☑ Background ☑ Access Road	3rd Party Equipment				PASS	O F/	AIL
	E) are comes	IN PROCESS NORTH	COG Equipment	√ Trash/Juni					

On-Site_Inspection_Form v1.xlsx 2/13/2023

Marie Florez

From: Jennifer Palma

Sent: Monday, December 19, 2022 2:32 PM

To: Nick Felix; Bob Asher; Ashley Bravo; Artesia Regulatory; Kim Harris; Joshua Edwards

Subject: RE: Crow ASM State Com #2H

Attachments: Resized_20221219_115054.JPEG; Resized_20221219_115049.JPEG;

Resized_20221219_115236.JPEG; Resized_20221219_115241.JPEG

Thank you Nick \[\begin{aligned} \ld \text{D} \\ \dagger \text{ add to that....CVE confirmed the poles are theirs and they will remove as they \]

can. Forwarded email to Regulatory.

Durango has kind of given me a response: they've confirmed there is "pipe" belonging to them and that

they will

remove. They were not specific in identifying a riser and pig launcher. Will "pipe" cover everything

Regulatory group?

Jennifer Palma

Lead Operations Assistant

EOG Resources, Inc

Artesia Division

104 South 4th Street

Artesia, NM 88210

Office Phone: (575) 748-4149 Cell Phone: (575) 513-8394

Email: Jennifer_Palma@eogresources.com

From: Nick Felix <Nick_Felix@eogresources.com>
Sent: Monday, December 19, 2022 2:24 PM

To: Bob Asher <Bob_Asher@eogresources.com>; Ashley Bravo <Ashley_Bravo@eogresources.com>;

Artesia Regulatory

<artesia_Regulatory@eogresources.com>; Kim Harris <Kim_Harris@eogresources.com>; Joshua Edwards

<Joshua_Edwards@eogresources.com>; Jennifer Palma <Jennifer_Palma@eogresources.com>

Subject: Crow ASM State Com #2H

The decommissioning on the Crow ASM State Com #2H is complete. There is a Durango Midstream riser and nig

launcher on side of pad, there is also CVE electrical poles on pad.

Get Outlook for iOS

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 210014

DEFINITIONS

Operator:		OGRID:
	EOG RESOURCES INC	7377
	P.O. Box 2267	Action Number:
	Midland, TX 79702	210014
		Action Type:
		[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 210014

QUESTIONS				
Operator: EOG RESOURCES INC		OGRID: 7377		
P.O. Box 2267 Midland, TX 79702		Action Number: 210014		
·		Action Type: [C-103] Sub. Release After P&A (C-103Q)		
QUESTIONS				
Subsequent Report of: Location Ready For OCD Inspection After P&A				
Was this the last remaining or only well on the location	Yes			
Are there any abandoned pipelines that are going to remain on the location	No			
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	Yes			
If any production equipment or structure is to remain on the location, please specify	3rd party riser and launc	her on South side		
Pite Fredricker				
Site Evaluation				
Please answer all the questions in this group. Have all the required pits been remediated in compliance with OCD rules and the				
terms of the Operator's pit permit and closure plan	Yes			
Have the rat hole and cellar been filled and leveled	Yes			
Have the cathodic protection holes been properly abandoned	Yes			
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes			
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.			
Has the location been leveled as nearly as possible to original ground contour	Yes			
Have all the required pipelines and other production equipment been cleared	Yes			
Has all the required junk and trash been cleared from the location	Yes			
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes			
Have all the required metal bolts and other materials have been removed	Yes			
Poured onsite concrete bases do not have to be removed.				
Have all the the required portable bases been removed	Yes			
Have all other environmental concerns have been addressed as per OCD rules	Yes			
If any environmental concerns remain on the location, please specify	Not answered.			

* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 210014

QUESTIONS ((continued)

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	210014
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

QUESTIONS

Abandoned Pipelines		
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).		
Have all fluids have been removed from any abandoned pipelines	Not answered.	
Have all abandoned pipelines been confirmed to <u>NOT</u> contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.	
Have all accessible points of abandoned pipelines been permanently capped	Not answered.	

Last Remaining or Only Well on the Location				
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.				
Have all electrical service poles and lines been removed from the location	Yes			
Is there any electrical utility distribution infrastructure that is remaining on the location	No			
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes			
Have all the retrievable pipelines, production equipment been removed from the location	Yes			
Has all the junk and trash been removed from the location	Yes			

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 210014

ACKNOWLEDGMENTS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	210014
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 210014

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	210014
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Cre	ated By	Condition	Condition Date
go	ordero	None	4/27/2023