

Surface Reclamation Complete Report

Well Name: ARMSTRONG CT COM #001

API: 30-015-20863

Well Location: L-5-18S-26E

Surface Owner: KENNON PHYLLIS REVOCABLE TRUST

Reclamation Complete Date: 2/7/23

Total Acres reclaimed: 2.30 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)		
NMSLO - Loamy (L)	Plains Bristlegrass (Setaria vulpiseta)	1.0	2.0		
п	Blue Grama	2.0	4.0		
п	Sideoats Grama	2.0	4.0		
II .	Sand Dropseed	1.0	2.0		
"	Alkali Sacaton	2.5	5.0		
п	Little Bluestem	2.5	5.0		
II .	Firewheel (Gaillardia)	1.0	2.0		
"	Fourwing Saltbush	1.0	2.0		
п	Common Winterfat	0.5	1.0		
Weights should be as pounds of pure live seed. Revised 10/20/2022 per NMSLO & EOG Regulatory/Artesia.					

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2024 to determine if successful vegetation regrowth is established.





On-Site Regulate	ory Reclamation	Inspection			Date:	2 / 7 / 2023	3		
Site Name: Armstrong CT Com #001									
API Number:	30-0 15 . 208	63 Plug I	ate: 7 /	27 / 2022		Program: Initial	Monitoring		
						Final	Corrective	YES	NO
Was this the last remaini	ng or only well on the lo	cation?							
Are there any abandone									V
Is there any production of		-			ipelines) that i	are going to remain on	locations		
If any production equipn	ent or structure (includi	ng 3rd party) is to ren	ain on location, please:	specify.					
Site Evaluation									
Recontoured back to	original State/Topsoil	Replaced						YES	NO
Have the rat hole and ce	llar been filled and levele	d?						$\overline{}$	
Have the cathodic protein			ned?					- /	
Rock or Caliche Surfacing	materials have been rer	novedr							
All Facilities Removed	for Final Reclamation								
Have all of the pipelines			than the listed above)					$\overline{}$	
Has all of the required ju								$\overline{}$	
Have all of the required a				feet below grou	nd level?			<u> </u>	
Have all of the required in Have all the required por			oveur					Ť	
Section Comments:									
Dry Hole Marker								YES	NO
Has a steel marker been	installed per COA require	ements?			Check One:	Buried	Above Ground	$\overline{}$	
		Lease Name & Num	her				Federal Lease #		
DHM Info	Operator Name		UL-S-T-R	Qtr Sectio	n (Footage)	API#	(Federal Only)		
Met Not Met					V				
Free of Oil or Salt Con	taminated Soil							YES	NO
Have all the required pit				Operator's pit pe	ermit and clos	ure plan?		$\overline{}$	
Have all other environme			s?						
If any environmental cor	cerns remain on the loca	ition, please specify.							
Abandoned Pipelines									
Only need to provide ans			bandoned (in accordance	e with 19. 15. 35	. 10 NMAC).			YES	NO
Have all fluids have been Have all abandoned pipe			I regulated NORM . oth	er than that whi	ch accumulate	ed under normal operat	tion?	\rightarrow	
Have all accessible point						and the second		-	
Section Comments:									
Last Remaining or Onl	y Well on the Location	1							
Please answer all question				any well or facil	ty remaining o	at this location.		YES	NO
Have all electrical service is there any electrical uti									
Have all the battery and				d the terms of th	e Operator's p	pit permit and closure p	lan?	$\overline{}$	·
Have all the retrievable	ipelines, production equ	ipment been remove	from the location?					$\overline{}$	
Has all the junk and trasl	been removed from the	location?							
Section Comments:	No not have to be met to	narr Incoartion							
This section corresponds	with questions on the Re	clamation inspection	Form in iEnvironmental L	but not related t	o NMOCD form	ns.		Met	Not Met
Free of Noxious or Invasi					, , , , , , , , , , , , , , , , , , , ,				
Site Stability? Erosion co		ry) & working.						$\overline{}$	
Signs of seeding complet		0.44-4-750	Contra		-	FAN 25			. /
Revegetation Success as Adequate Reclamation F		2r Met >/5%.	Grde 0	one: 0%	25%	50% 759	6 100%		
								v	
Section Comments:	In	enaction swear	completed: all tra	sch/iunk ron	nowed				
Additional Findings or Comments: Inspection sweep completed; all trash/junk removed.									
T READY FOR FAN					N SUBMITTAL				
Inspector: B.MADRID TINEEDS FURTHER									
Picture Checklist:	Øрни Ø	Background	3rd Party Equipment	Contamin	ation II_			on Result	
		Access Road	T EOG Equipment	∏ Trash/Juni			PASS	U #	AIL

On-Site_Inspection_Form v1.xlsx 10/20/2022



Surface Owner Approval of Reclamation completed with Well P&A

Well Name: Armstrong CT Com #001

API: 30-015-20863

Location: NW/4SW/4 being approximately 2.30 acres in total area.

Section: 05

Township: 18 South Range: 26 East County: Eddy

Surface owner: Kennon Phyllis Revocable Trust

C/O Fred Kennon 23560 Stateline Rd. Louisburg, KS 66053

I hereby agree that EOG Resources, Inc. has completed all surface reclamation activities to meet our requirements as surface landowner for the above noted well.

Surface Owner Name: Fred Kennon signing for Kennon Phyllis Revocable Trust

Surface Owner Signature:

Dated:

EOG Representative Name: Keith Kistner

EOG Representative Signature:

Dated: 4/19/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

DEFINITIONS

Action 215859

DEFINITIONS

Operator:		OGRID:
	EOG RESOURCES INC	7377
F	P.O. Box 2267	Action Number:
1	Midland, TX 79702	215859
		Action Type:
		[C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS

Action 215859

Q	UESTIONS
Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377 Action Number: 215859 Action Type: (C. 1031 Sub. Polocos After P&A (C. 1030))
QUESTIONS	[C-103] Sub. Release After P&A (C-103Q)
Subsequent Report of: Location Ready For OCD Inspection After P&A	
Was this the last remaining or only well on the location	Yes
Are there any abandoned pipelines that are going to remain on the location	No.
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	No
If any production equipment or structure is to remain on the location, please specify	Not answered.
Site Evaluation	
Please answer all the questions in this group.	
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have the rat hole and cellar been filled and leveled	Yes
Have the cathodic protection holes been properly abandoned	Yes
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.
Has the location been leveled as nearly as possible to original ground contour	Yes
Have all the required pipelines and other production equipment been cleared	Yes
Has all the required junk and trash been cleared from the location	Yes
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes
Have all the required metal bolts and other materials have been removed	Yes
Poured onsite concrete bases do not have to be removed.	
Have all the the required portable bases been removed	Yes
Have all other environmental concerns have been addressed as per OCD rules	Yes
If any environmental concerns remain on the location, please specify	Not answered.

* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, addtional concerns, or other nearby / remaing structures and equipment.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 2

Action 215859

QUESTIONS	(continued)
QUESTIONS!	(COHUHUCU)

Op	perator:	OGRID:	
	EOG RESOURCES INC	7377	ESOURCES INC
	P.O. Box 2267	Action Number:	x 2267
	Midland, TX 79702	215859	I, TX 79702
		Action Type:	
		[C-103] Sub. Release After P&A (C-103Q)	
		•	

QUESTIONS

Abandoned Pipelines		
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).		
Have all fluids have been removed from any abandoned pipelines	Not answered.	
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation	Not answered.	
Have all accessible points of abandoned pipelines been permanently capped	Not answered.	

Last Remaining or Only Well on the Location			
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.			
Have all electrical service poles and lines been removed from the location Yes			
Is there any electrical utility distribution infrastructure that is remaining on the location	No		
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes		
Have all the retrievable pipelines, production equipment been removed from the location	Yes		
Has all the junk and trash been removed from the location	Yes		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 215859

ACK	IWOI	.EDGN	IFNTS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	215859
	Action Type:
	[C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 215859

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267 Midland, TX 79702	Action Number: 215859
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By		Condition Date
gcordero	None	5/16/2023