

Leak Det. 11-22-24 10/1/2023
(505) 395-4151 Fax (505) 395-4723

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office


BRADENHEAD TEST REPORT

Operator Name OKV		API Number 30-015-35738	
Property Name Solomon State # 11		Well No. 1	
1 Surface Location			
U.S. - Lat H	Section 10	Township 19S	Range 29E
Feet from 1429		N.S. Line N	Feet from 840
E/W Line E		County Eddy	
Well Status			
☒ YES	☐ NO	☒ YES	☐ NO
INJ		INJECTOR	SWD
☒ OIL		PRODUCER	GAS
DATE 5-29-23			

OBSERVED DATA

	(A) Surface	(B) Intermit	(C) Intermit	(D) Prod Cons	(E) Tubing
Pressure	0 PSI	0 PSI	N/A		0 PSI
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Indicates for
Water	Y/N	Y/N	Y/N	Y/N	Workload &

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Berdo Olivera		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone: 806-200-0895		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 221470

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 221470
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
john.harrison	None	6/7/2023