ceived by UCD: 0/5/2023 1:06:17 PM U.S. Department of the Interior BUREAU OF LAND MANAGEMENT		Sundry Print Repo. 06/05/2023
Well Name: DOME NAVAJO 21-27-13	Well Location: T27N / R13W / SEC 21 / SWSW / 36.556519 / -108.229034	County or Parish/State: SAN JUAN / NM
Well Number: 3	<b>Type of Well:</b> CONVENTIONAL GAS WELL	Allottee or Tribe Name: EASTERN NAVAJO
Lease Number: N00C14207481	Unit or CA Name:	Unit or CA Number:
US Well Number: 300452384700S1	Well Status: Abandoned	<b>Operator:</b> DUGAN PRODUCTION CORPORATION

#### **Subsequent Report**

Sundry ID: 2734276

Type of Submission: Subsequent Report

Date Sundry Submitted: 06/05/2023

Date Operation Actually Began: 04/21/2023

Type of Action: Plug and Abandonment

Time Sundry Submitted: 11:09

Actual Procedure: Dugan Production Corp. P&A'd the well from 04/21/2023 to 04/24/2023 per the following procedure: 1) MI&RU Aztec Well Services Rig 481 and cement equipment. Check pressures. Casing 0 psi, Tubing 0 psi, BH 0 psi. ND WH & NU BOP. RU Work floor. 2) TOOH w/1¼" tubing. RU WL services. Set 2-7/8" bridge plug @ 1272'. Perforations @ 1322'-1338'. Load & circulate hole. Pressure test casing to 650 psi for 30 minutes. Casing held good. Test passed. 3) Spot and circulate cement to surface from 1272' w/45 sks (51.75 cu ft) Class G cement (1.15 cu ft/sk, 15.8 #/gal). Circulate 1 bbl cement to surface. WOC 4 hrs. Cut wellhead off. Tag 13' inside 5½" annulus and @ surface inside 2-7/8". Plug I, inside 2-7/8", 45 sks, 51.75 cu ft, Pictured Cliffs-Fruitland-Kirtland-Ojo Alamo-Surface, 0-1272'. 4) Install below ground plate for dry hole marker as it is NAPI surface. Fill up cellar w/15 sks (17.3 cu ft) to level with the plate. BLM Farmington FO witnessed job. 5) Clean location. RD & move. Well P&A'd 04/24/2023.

## SR Attachments

#### **Actual Procedure**

Dome\_Navajo\_21\_27\_13\_3\_Post\_PA\_wellbore\_schematic\_20230605110753.pdf

Dome\_Navajo\_21\_27\_13\_3\_Post\_PA\_work\_20230605110743.pdf

R	eceived by OCD: 6/5/2023 1:06:17 PM Well Name: DOME NAVAJO 21-27-13	Well Location: T27N / R13W / SEC 21 / SWSW / 36.556519 / -108.229034	County or Parish/State: SAN
	Well Number: 3	<b>Type of Well:</b> CONVENTIONAL GAS WELL	Allottee or Tribe Name: EASTERN NAVAJO
	Lease Number: N00C14207481	Unit or CA Name:	Unit or CA Number:
	US Well Number: 300452384700S1	Well Status: Abandoned	<b>Operator:</b> DUGAN PRODUCTION CORPORATION

## Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TYRA FEIL

Name: DUGAN PRODUCTION CORPORATION

Title: Authorized Representative

Street Address: PO Box 420

City: Farmington

State: NM

Phone: (505) 325-1821

Email address: tyrafeil@duganproduction.com

### **Field**

Representative Name: ALIPH REENAStreet Address: PO BOX 420City: FARMINGTONState: NMPhone: (505)325-1821Email address: Aliph.Reena@duganproduction.com

Zip: 87499-0420

Signed on: JUN 05, 2023 11:07 AM

### **BLM Point of Contact**

BLM POC Name: MATTHEW H KADE BLM POC Phone: 5055647736

Disposition: Accepted

Signature: Matthew Kade

BLM POC Title: Petroleum Engineer BLM POC Email Address: MKADE@BLM.GOV Disposition Date: 06/05/2023 Dugan Production Corp. P&A'd the well from 04/21/2023 to 04/24/2023 per the following procedure:

- MI&RU Aztec Well Services Rig 481 and cement equipment. Check pressures. Casing 0 psi, Tubing 0 psi, BH 0 psi. ND WH & NU BOP. RU Work floor.
- TOOH w/1¼" tubing. RU WL services. Set 2-7/8" bridge plug @ 1272'. Perforations @ 1322'-1338'. Load & circulate hole. Pressure test casing to 650 psi for 30 minutes. Casing held good. Test passed.
- Spot and circulate cement to surface from 1272' w/45 sks (51.75 cu ft) Class G cement (1.15 cuft/sk, 15.8 #/gal). Circulate 1 bbl cement to surface. WOC 4 hrs. Cut wellhead off. Tag 13' inside 5½" annulus and @ surface inside 2-7/8". Plug I, inside 2-7/8", 45 sks, 51.75 cu ft, Pictured Cliffs-Fruitland-Kirtland-Ojo Alamo-Surface, 0-1272'.
- Install below ground plate for dry hole marker as it is NAPI surface. Fill up cellar w/15 sks (17.3 cu ft) to level with the plate. BLM Farmington FO witnessed job.
- Clean location. RD & move. Well P&A'd 04/24/2023.

#### Completed P & A Schematic

Dome Navajo 21-27-13 #3 API: 30-045-23847 1120' FSL & 1120' FWL Sec 21, T27N R13W San Juan County, NM Lat: 36.5565987, Long: -108.2296829



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
DUGAN PRODUCTION CORP	6515
PO Box 420	Action Number:
Farmington, NM 87499	223937
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

CONDITIONS			
Created By	Condition	Condition Date	
john.harrison	Accepted for record - NMOCD JRH 6/9/23. Well P&A'd 4/24/23	6/9/2023	

CONDITIONS

Page 5 of 5

Action 223937