



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-16-2023 Operator San Juan Resources API # 30-045-32185
9:30 AM
 Property Name US Grant #1 Location: Unit G Section 19 Township 30N Range 11W
 (Well Name and Number)
 Pressure (Shut-in or Producing) 165 Intermediate 172 Casing 172 Bradenhead 172

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>Ø</u>	<u>172</u>	<u>Ø</u>	<u>Ø</u>	<u>176</u>	Steady Flow	
10 minutes	<u>Ø</u>	<u>172</u>	<u>Ø</u>	<u>Ø</u>	<u>176</u>	Surges	
15 minutes	<u>Ø</u>	<u>173</u>	<u>Ø</u>	<u>Ø</u>	<u>177</u>	Down to Nothing	<u>Ø 5 sec 5 seconds</u>
20 minutes	<u>Ø</u>	<u>173</u>	<u>Ø</u>	<u>Ø</u>	<u>177</u>	No Flow	<u>✓</u>
25 minutes	<u>Ø</u>	<u>174</u>	<u>Ø</u>	<u>Ø</u>	<u>178</u>	Gas	<u>✓</u>
30 minutes	<u>Ø</u>	<u>174</u>	<u>Ø</u>	<u>Ø</u>	<u>178</u>	Gas and Water	<u>✓</u>
5 minute SI	<u>Ø</u>	<u>176</u>	<u>Ø</u>	<u>Ø</u>	<u>179</u>	Water	<u>✓</u>

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead Ø Intermediate 1.0

REMARKS:

9:30 AM 5-15-23 Intermediate had 6 pound of pressure when
Plunger well was shut in for test.

By

[Signature]

Witness

Lease operator

(Position)

NMOCD Test Area:

1

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 218027

CONDITIONS

Operator: SAN JUAN RESOURCES, INC. 1499 Blake St, #10C Denver, CO 80202	OGRID: 20208
	Action Number: 218027
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
Idmoore	None	6/14/2023