



Surface Reclamation Complete Report

Well Name: STRAIT BLN STATE COM #005

API: 30-025-38169

Well Location: L-20-10S-34E

Surface Owner: DIAMOND & HALF INC

Reclamation Complete Date: 4/12/23

Total Acres reclaimed: 1.25 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
NMSLO - Loamy (L)	Plains Bristlegrass (Setaria vulpiseta)	1.0	2.0
"	Blue Grama	2.0	4.0
"	Sideoats Grama	2.0	4.0
"	Sand Dropseed	1.0	2.0
"	Alkali Sacaton	2.5	5.0
"	Little Bluestem	2.5	5.0
"	Firewheel (Gaillardia)	1.0	2.0
"	Fourwing Saltbush	1.0	2.0
"	Common Winterfat	0.5	1.0

Weights should be as pounds of pure live seed. Revised 10/20/2022 per NMSLO & EOG Regulatory/Artesia.

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2024 to determine if successful vegetation regrowth is established.

BG DHM

Date & Time: Wed Apr 12 12:35:02 MDT 2023
 Position: 033.43036 N / 103.49942 W
 Altitude: 4232ft
 Datum: NORTH AMERICAN 1983 CONUS
 Azimuth Bearing: 167.5135 2969mils (True)
 Zoom: 1X
 B.Madrid



On-Site Regulatory Reclamation Inspection		Date:	4 / 12 / 2023	
Site Name: STRAIT BLN STATE COM #005				
API Number:	30-0, 25, 38169	Plug Date:	4 / 25 / 2022	
<input type="checkbox"/> Facility Site-No associated well on location		Inspection:	<input type="checkbox"/> Initial <input type="checkbox"/> Monitoring <input type="checkbox"/> Active <input type="checkbox"/> Corrective <input checked="" type="checkbox"/> Final	
Was this the last remaining or only well on the location?			YES	NO
Are there any abandoned pipelines that are going to remain on the location?			✓	✓
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?			✓	
If any production equipment or structure (including 3rd party) is to remain on location, please specify.			3rd party riser on SW corner	
Site Evaluation				
Recontoured back to original State/Topsoil Replaced			YES	NO
Have the rat hole and cellar been filled and leveled?			✓	
Have the cathodic protection holes been properly abandoned & reclaimed?			✓	
Rock or Caliche Surfacing materials have been removed?			✓	
Section Comments:				
All Facilities Removed for Final Reclamation				
Have all of the pipelines & production equipment been cleared? (other than the listed above)			✓	
Has all of the required junk and trash been cleared from the location?			✓	
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?			✓	
Have all of the required metal bolts and other materials have been removed?			✓	
Have all the required portable bases been removed?			✓	
Section Comments:				
Dry Hole Marker			YES	NO
Has a steel marker been installed per COA requirements?			✓	
Check One: <input checked="" type="checkbox"/> Buried <input type="checkbox"/> Above Ground				
Required DHM Information:				
<input type="checkbox"/> Operator Name <input type="checkbox"/> UL or Qty/Qtr <input type="checkbox"/> API Number <input type="checkbox"/> County <input type="checkbox"/> Federal Lease # (Fed Only) <input type="checkbox"/> Lease Name & Number <input type="checkbox"/> Sec-Ten-Rng <input type="checkbox"/> Footage <input type="checkbox"/> PSA Date				
Free of Oil or Salt Contaminated Soil			YES	NO
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?			✓	
Have all other environmental concerns been addressed as per OCD rules?			✓	
If any environmental concerns remain on the location, please specify.				
Abandoned Pipelines			YES	NO
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19, 15, 35, 10 NMAC).				
Have all fluids have been removed from any abandoned pipelines?			✗	
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?			✗	
Have all accessible points of abandoned pipelines been permanently capped?			✗	
Section Comments:				
Last Remaining or Only Well on the Location			YES	NO
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.				
Have all electrical service poles and lines been removed from the location?			✓	
Is there any electrical utility distribution infrastructure that is remaining on the location?				✓
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?			✓	
Have all the retrievable pipelines, production equipment been removed from the location?			✓	
Has all the junk and trash been removed from the location?			✓	
Section Comments:				
Environmental Only: Do not have to be met to pass inspection			Met	Not Met
This section corresponds with questions on the Reclamation Inspection Form in Environmental but not related to NIMOC forms.				
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)			✓	
Site Stability? Erosion controls in place (if necessary) & working.			✓	
Signs of seeding completion? (Broadcast/Drilled)			✓	
Revegetation Success as compared to background? Met >75%.				✓
Grade One: 0% 25% 50% 75% 100%				
Adequate Reclamation Fence installed?			✓	
Section Comments:				
Additional Findings or Comments:			Inspection sweep completed; all oil & gas trash/junk removed.	
Inspector: B. Madrid				
Picture Checklist:			<input type="checkbox"/> READY FOR FAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW Inspection Result <input checked="" type="radio"/> PASS <input type="radio"/> FAIL	
<input checked="" type="checkbox"/> DHM <input checked="" type="checkbox"/> Background <input checked="" type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/> _____ <input checked="" type="checkbox"/> Site Corners <input checked="" type="checkbox"/> Access Road <input checked="" type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/> _____				

On-Site_Inspection_Form v1.xlsx

2/13/2023

From: Bruelhart, Alex J.
To: Jennifer Palma; Terry, Diane J.; Brown, Nikki N.; Maitlen, K'Lee D.
Cc: Gibson, Raul; Espino, Cesar M.; Corral, Alfredo V.; Ziegler, Rick L.
Subject: RE: [EXTERNAL] Measurement Equipment Removal - additional locations
Date: Friday, July 22, 2022 8:55:46 AM
Attachments: image002.png

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you

recognize the sender and know the content is safe.

Thank you Jennifer! If there are any questions please let me know.

Nikki/Diane please see Jennifer's email below. If these meters are active please move forward with TA. I can have Alfredo pull the meters if need be.

K'Lee, please add these locations below to our list of meter run removals.

Alex Bruelhart

Versado Area

abruelhart@targaresources.com

Cell: 918-894-1360

From: Jennifer Palma <Jennifer_Palma@eogresources.com>

Sent: Friday, July 22, 2022 9:49 AM

To: Bruelhart, Alex J. <abruelhart@targaresources.com>

Subject: [EXTERNAL] Measurement Equipment Removal - additional locations

CAUTION: This email originated from outside of Targa. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Good Morning Alex,

I've 4 additional locations that have been or are being P&A that need to have Targa meters removed.

They are as follows:

Rokesmith BDI State Com #1: 33.3923569,-103.475029

Mattea BFA State #1: 33.398571,-103.4379272

Hummingbird ADM State #1: 32.9381714,-103.2655716, quick note on this one: EOG sold this well effective 5/2021 but took it back over effective 6/2022.

Kemnitz South AFL State #1: 32.8730278,-103.5981293, quick note on this one: EOG sold this well effective 5/2021 but took it back over effective 6/2022. Also, my field production technician that has

been working on decommissioning this location indicated that the meter # is unreadable but the line

on the downstream side of the meter run has been marked so he was able to tell it's a Targa meter.

Please let me know if you have any questions.

Have a great weekend!!!

Jen

Jennifer Palma

Lead Operations Assistant

EOG Resources, Inc

Artesia Division

104 South 4th Street

Artesia, NM 88210

Office Phone: (575) 748-4149

Cell Phone: (575) 513-8394

Email: Jennifer_Palma@eogresources.com

From: Bruelhart, Alex J. <abruelhart@targaresources.com>

Sent: Monday, July 18, 2022 10:50 AM

To: Jennifer Palma <Jennifer_Palma@eogresources.com>; George Flores <George_Flores@eogresources.com>

Cc: Gibson, Raul <rgibson@targaresources.com>; Rainey, Colton D. <crainey@targaresources.com>

Subject: RE: [EXTERNAL] Measurement Equipment Removal

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you

recognize the sender and know the content is safe.

Morning Jennifer, we have removed and ATD' d each of the actual meters on location. We have not removed any of the physical meter runs. Our tracking list for removal has been updated and our crew(s) will get to each of them as they come up on the list.

Alex Bruelhart

Versado Area

abruelhart@targaresources.com

Cell: 918-894-1360

From: Jennifer Palma <Jennifer_Palma@eogresources.com>

Sent: Monday, July 18, 2022 9:36 AM

To: Bruelhart, Alex J. <abruelhart@targaresources.com>; George Flores <George_Flores@eogresources.com>

Cc: Gibson, Raul <rgibson@targaresources.com>; Rainey, Colton D. <crainey@targaresources.com>

Subject: RE: [EXTERNAL] Measurement Equipment Removal

Good Morning Alex,

Could I get an update on any progress that has been made on the removal of measurement equipment please?

If you require anything further from me please let me know.

Sincerely,

Jennifer

Jennifer Palma

Lead Operations Assistant

EOG Resources, Inc

Artesia Division

104 South 4th Street

Artesia, NM 88210

Office Phone: (575) 748-4149

Cell Phone: (575) 513-8394

Email: Jennifer_Palma@eogresources.com

From: Christopher Gurule <Christopher_Gurule@eogresources.com>

Sent: Monday, May 23, 2022 1:20 PM

To: Bruelhart, Alex J. <abruelhart@targaresources.com>; George Flores <George_Flores@eogresources.com>

Cc: Gibson, Raul <rgibson@targaresources.com>; Jennifer Palma

<Jennifer_Palma@eogresources.com>; Rainey, Colton D. <crainey@targaresources.com>

Subject: RE: [EXTERNAL] Measurement Equipment Removal

Alex,

below would be the priority that these are needing to be removed in. The sooner the better to prevent any reclamation issues. Thanks for your assistance in this, please let me know if you have any questions Thanks.

Strait BLN State Com #4

Strait BLN State Com #5

Judith AIJ Federal #1

Merle BOJ State Com #11

Elvis BOV State Com #1

Gato Loco BFT Com #1

Jerry Jeff BED State Com #1

Judson AUU State Com #2

Abby BLF State Com #1

McBride BEH State Com #1

Christopher Gurule

Measurement & Automation Foreman

EOG Resources, INC

Artesia Division

O: 575-748-4224

C: 575-703-4243

Christopher_Gurule@eogresources.com

From: Bruelhart, Alex J. <abruelhart@targaresources.com>

Sent: Monday, May 16, 2022 9:51 AM

To: Christopher Gurule <Christopher_Gurule@eogresources.com>; George Flores

<George_Flores@eogresources.com>

Cc: Gibson, Raul <rgibson@targaresources.com>; Jennifer Palma

<Jennifer_Palma@eogresources.com>; Rainey, Colton D. <crainey@targaresources.com>

Subject: RE: [EXTERNAL] Measurement Equipment Removal

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you

recognize the sender and know the content is safe.

George, according to ROW we don't need to remove out down leg at any of these sites but we can remove the measurement equipment. I can not at this time give you any kind of time frame of when

this will happen. If you could send me a list of the higher priority leases for you. Then I can possibly squeeze in our crew between other maintenance projects. Just let me know. Thanks

Alex Bruelhart

Versado Area

abruelhart@targaresources.com

Cell: 918-894-1360

From: Rainey, Colton D. <crainey@targaresources.com>

Sent: Monday, May 16, 2022 10:25 AM

To: Christopher Gurule <Christopher_Gurule@eogresources.com>; Bruelhart, Alex J.

<abruelhart@targaresources.com>; George Flores <George_Flores@eogresources.com>

Cc: Gibson, Raul <rgibson@targaresources.com>; Jennifer Palma <Jennifer_Palma@eogresources.com>

Subject: RE: [EXTERNAL] Measurement Equipment Removal

All,

Please see my below notes as to the removal obligations per each of these easements.

Gato Loco BFT Com#1 33.57508,-103.49868- No removal obligations referenced.

Strait BLN St Com #5 33.4305763,-103.4916382- No removal obligations referenced.

Judson AUU St Com#2 33.4127235,-103.4325104- No removal obligations referenced.

Abby BLF St #1 33.5426,-103.55593- No removal obligations referenced.

Mcbride BEH ST #1 33.4775696,-103.4753876- No removal obligations referenced.

Jerry Jeff BED St Com #1 33.4587364,-103.5072021- No removal obligations referenced.

Merle BOJ ST COM#11 33.467083,-103.4281311- No removal obligations referenced.

Thanks,

Colton Rainey

ROW Agent

Targa Resources

(432) 248-9519

crainey@targaresources.com

From: Christopher Gurule <Christopher_Gurule@eogresources.com>

Sent: Wednesday, May 11, 2022 1:48 PM

To: Bruelhart, Alex J. <abruelhart@targaresources.com>; George Flores

<George_Flores@eogresources.com>

Cc: Rainey, Colton D. <crainey@targaresources.com>; Gibson, Raul <rgibson@targaresources.com>;

Jennifer Palma <Jennifer_Palma@eogresources.com>

Subject: RE: [EXTERNAL] Measurement Equipment Removal

Not sure if you already got this info but if not please see below. Let us know if you need anymore info.

From: Bruelhart, Alex J. <abruelhart@targaresources.com>

Sent: Thursday, April 28, 2022 4:21 PM

To: George Flores <George_Flores@eogresources.com>

Cc: Christopher Gurule <Christopher_Gurule@eogresources.com>; Rainey, Colton D.

<crainey@targaresources.com>; Gibson, Raul <rgibson@targaresources.com>

Subject: RE: [EXTERNAL] Measurement Equipment Removal

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you

recognize the sender and know the content is safe.

George, can you send me some GPS points? We have a couple thousand meter runs and its just easier to locate them with a GPS. I've also CC'd our ROW department to check any removal requirements listed in our easements. Thanks

Alex Bruelhart

Versado Area

abruelhart@targaresources.com

Cell: 918-894-1360

From: George Flores <George_Flores@eogresources.com>

Sent: Thursday, April 28, 2022 8:49 AM

To: Bruelhart, Alex J. <abruelhart@targaresources.com>; Gibson, Raul

<rgibson@targaresources.com>

Cc: Christopher Gurule <Christopher_Gurule@eogresources.com>

Subject: [EXTERNAL] Measurement Equipment Removal

CAUTION: This email originated from outside of Targa. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Good morning gentlemen, I wanted to see if we could get the following locations measurement equipment removed as soon as possible. The wells have been plugged and are scheduled for reclamation. So it's imperative that we remove the equipment in a timely manner. Thanks for your help any questions please reach out to me. 575-703-0497

Gato Loco BFT Com#1 33.57508,-103.49868

Strait BLN St Com #5 33.4305763,-103.4916382

Judson AUU St Com#2 33.4127235,-103.4325104

Abby BLF St #1 33.5426,-103.55593

Mcbride BEH ST #1 33.4775696,-103.4753876

Jerry Jeff BED St Com #1 33.4587364,-103.5072021

Merle BOJ ST COM#11 33.467083,-103.4281311

EOG RESOURCES ARTESIA DIVISION

George_Flores@eogresources.com

Cell 575 703-0497

This email (including any attachments and accompanying emails) may contain proprietary and confidential information. If you are not the intended recipient, please telephone the sender and immediately delete this e-mail (including any attachments and accompanying emails). Please do not replicate, disclose, distribute, forward, or retain this e-mail or any part of this email. Thank you.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 208918

DEFINITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 208918
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- lease and well location, hereinafter "location";
- flowlines or pipelines, hereinafter "pipelines";
- and non-retrieved or abandoned, hereinafter "abandoned".

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 208918

QUESTIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 208918
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

QUESTIONS

Subsequent Report of: Location Ready For OCD Inspection After P&A	
Was this the last remaining or only well on the location	Yes
Are there any abandoned pipelines that are going to remain on the location	No
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that is going to remain on the location	Yes
If any production equipment or structure is to remain on the location, please specify	3rd party riser on SW corner. Below ground dry hole marker.

Site Evaluation

Please answer all the questions in this group.

Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have the rat hole and cellar been filled and leveled	Yes
Have the cathodic protection holes been properly abandoned	Yes
Has a steel marker, at least 4 inches in diameter and at least 4 feet above ground level, been set in concrete	Yes
The (concrete-set) steel marker shows: Must attach marker photograph(s). *	THE OPERATOR NAME, LEASE NAME AND WELL NUMBER AND LOCATION, INCLUDING UNIT LETTER, SECTION, TOWNSHIP AND RANGE, SHALL BE WELDED, STAMPED OR OTHERWISE PERMANENTLY ENGRAVED INTO THE MARKER'S METAL.
Has the location been leveled as nearly as possible to original ground contour	Yes
Have all the required pipelines and other production equipment been cleared	Yes
Has all the required junk and trash been cleared from the location	Yes
Have all the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level	Yes
Have all the required metal bolts and other materials have been removed	Yes

Poured onsite concrete bases do not have to be removed.

Have all the the required portable bases been removed	Yes
Have all other environmental concerns have been addressed as per OCD rules	Yes
If any environmental concerns remain on the location, please specify	Not answered.

* Proof of the site marker (photograph) is required.

Please submit any other site photographs that would assist in documenting the above answers, site features, additional concerns, or other nearby / remaing structures and equipment.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 208918

QUESTIONS (continued)

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 208918
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

QUESTIONS

Abandoned Pipelines	
<i>Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 19.15.35.10 NMAC).</i>	
Have all fluids have been removed from any abandoned pipelines	<i>Not answered.</i>
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation	<i>Not answered.</i>
Have all accessible points of abandoned pipelines been permanently capped	<i>Not answered.</i>

Last Remaining or Only Well on the Location	
<i>Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.</i>	
Have all electrical service poles and lines been removed from the location	Yes
Is there any electrical utility distribution infrastructure that is remaining on the location	No
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan	Yes
Have all the retrievable pipelines, production equipment been removed from the location	Yes
Has all the junk and trash been removed from the location	Yes

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 208918

ACKNOWLEDGMENTS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 208918
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

ACKNOWLEDGMENTS

<input checked="" type="checkbox"/>	I hereby certify that all the work has been completed for this location and the site is ready for an OCD scheduled inspection.
-------------------------------------	--

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

COMMENTS

Action 208918

COMMENTS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 208918
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM.	6/15/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 208918

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 208918
	Action Type: [C-103] Sub. Release After P&A (C-103Q)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	6/15/2023