

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6151 Fax: (575) 393-9729

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Morning Star CVU				Operator Name		API Number 30-025-25706				
Property Name						Well No. # 43				
UL - Lot A	Section 36	Township 17S	Range 34E	Surface Location		Feet from 35	NS Line N	Feet From 127	E/W Line E	County LEA
Well Status										
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 4-12-23

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	5		1800	1900
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Exposed for
Water	Y/N	Y/N	Y/N	Y/N	Waterhead if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

MIT/BHT

4-11-23 - Need vac truck to blow down prod. csg.

4-11-23 - come back - blow to vac truck - 1800#, opened to truck, dropped to 1600#
for 15 min. - shut valve + press. went right back to 1800#

Failed BHT - Well is to be shut in ASAP

No Chart was
seen

Signature: <i>B. D. [Signature]</i>		OIL CONSERVATION DIVISION	
Printed name: Brandon Korym		Entered into RBDMS	
Title: Production Foreman		Re-test	
E-mail Address: <i>Bkorym@lt&fieldsvcs.com</i>			
Date: 4-12-23	Phone: 682-346-5911		
Witness: <i>Greg Kolenson</i>			

INSTRUCTIONS ON BACK OF THIS FORM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 209341

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 209341
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Failed BHT repair well	6/23/2023