

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

|                                                |  |                                   |  |
|------------------------------------------------|--|-----------------------------------|--|
| Operator Name<br><b>DKR Field Services LLC</b> |  | API Number<br><b>30-025-44144</b> |  |
| Property Name<br><b>Boodlesky</b>              |  | Well No.<br><b>1</b>              |  |

|                     |                      |                        |                     |                          |                     |                          |                      |                      |
|---------------------|----------------------|------------------------|---------------------|--------------------------|---------------------|--------------------------|----------------------|----------------------|
| 1. Surface Location |                      |                        |                     |                          |                     |                          |                      |                      |
| U. Loc<br><b>C</b>  | Section<br><b>16</b> | Township<br><b>22S</b> | Range<br><b>33E</b> | Feet from<br><b>1480</b> | NS Line<br><b>N</b> | Feet from<br><b>2390</b> | E/W Line<br><b>E</b> | County<br><b>Lea</b> |

Well Status

|                 |    |     |               |           |                  |                 |     |                        |
|-----------------|----|-----|---------------|-----------|------------------|-----------------|-----|------------------------|
| TAB WELL<br>YES | NO | YES | SHUT-IN<br>NO | INJ<br>NO | INSPECTOR<br>SWD | OIL<br>PRODUCER | GAS | DATE<br><b>6-13-23</b> |
|-----------------|----|-----|---------------|-----------|------------------|-----------------|-----|------------------------|

OBSERVED DATA

|                      | (A)Surface | (B)Interm(1) | (C)Interm(2) | (D)Prod Comp | (E)Tubing                                              |
|----------------------|------------|--------------|--------------|--------------|--------------------------------------------------------|
| Pressure             | 0          | 0            | N/A          | 50           | 1524                                                   |
| Flow Characteristics |            |              |              |              |                                                        |
| Puff                 | Y / N      | Y / N        | Y / N        | Y / N        | CO2                                                    |
| Steady Flow          | Y / N      | Y / N        | Y / N        | Y / N        | WTR                                                    |
| Surges               | Y / N      | Y / N        | Y / N        | Y / N        | GAS                                                    |
| Down to nothing      | Y / N      | Y / N        | Y / N        | Y / N        | Type of fluid<br>logged for<br>viscosity &<br>specific |
| Gas or Oil           | Y / N      | Y / N        | Y / N        | Y / N        |                                                        |
| Water                | Y / N      | Y / N        | Y / N        | Y / N        |                                                        |

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

|                                                         |                               |
|---------------------------------------------------------|-------------------------------|
| Signature:<br><i>Kerry Mackey</i>                       | OIL CONSERVATION DIVISION     |
| Printed name:<br><b>Kerry Mackey</b>                    | Entered into RBDMS            |
| Title                                                   | Re-test                       |
| E-mail Address:<br><b>Kerry.Mackey@dnr.hobbs.nm.gov</b> |                               |
| Date:<br><b>6-13-23</b>                                 | Phone:<br><b>575-631-8198</b> |
| Witness:                                                |                               |

INSTRUCTIONS ON BACK OF THIS FORM

GR

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 228734

CONDITIONS

|                                                                                      |                                                            |
|--------------------------------------------------------------------------------------|------------------------------------------------------------|
| Operator:<br>DKL Field Services, LLC<br>310 Seven Springs Way<br>Brentwood, TN 37027 | OGRID:<br>372603                                           |
|                                                                                      | Action Number:<br>228734                                   |
|                                                                                      | Action Type:<br>[UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

|            |           |                |
|------------|-----------|----------------|
| Created By | Condition | Condition Date |
| kfortner   | None      | 7/10/2023      |