Received by OCD: 7/19/2023 1:13:13 PM Office District I – (575) 393-6161	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 <sup>1</sup> of Revised July 18, 2013
District IV         (5/5) 5/50 6101           1625 N. French Dr., Hobbs, NM 88240 <u>District III</u> - (575) 748-1283           811 S. First St., Artesia, NM 88210 <u>District III</u> - (505) 334-6178           1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460           1220 S. St. Francis Dr., Santa Fe, NM           87505	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-05423 5. Indicate Type of Lease STATE STATE FEE 6. State Oil & Gas Lease No.
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)	S AND REPORTS ON WELLS S TO DRILL OR TO DEEPEN OR PLUG BACK TO A ION FOR PERMIT" (FORM C-101) FOR SUCH S Well Other Injector	<ul> <li>7. Lease Name or Unit Agreement Name</li> <li>Lovington San Andres Unit</li> <li>8. Well Number 38</li> </ul>
2. Name of Operator Chevron Midcontinent, L.P.		9. OGRID Number 241333
<ol> <li>Address of Operator</li> <li>6301 Deauville Blvd Midland, Te</li> </ol>	xas 79706	10. Pool name or Wildcat San Andrew
4. Well Location Unit Letter F : 165	60 feet from the North line and 19	980feet from theline
Section 6	Township 17 S Range 37E	NMPM County Lea
1	1. Elevation (Show whether DR, RKB, RT, GR, et	<i>c.</i> )

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OI	= IN	TENTION TO:	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING		MULTIPLE COMPL	CASING/CEMENT JOB	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER:			OTHER:	

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See attached plugging report and as plugged wellbore diagram.

Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and co	omplete to the best of my knowledge and belief.	
SIGNATURE Mark Torres	_ <sub>TITLE</sub> Engineer	
Type or print name Mark Torres For State Use Only	E-mail address:marktorres@chevron.com	PHONE: 989-264-2525
APPROVED BY: Conditions of Approval (if any):	TITLE Petroleum Specialist	_DATE7/25/23

Chevron

## **P&A Operations Summary - External**

Well Name		Field Name	Lease	Area		
LOVINGTON SAN ANDRES UNIT 038		Lovington	Lovington San Andres Unit	Central Permian		
Business Unit EMC		County/ Parish Lea	Global Metrics Region EMC US East	Surface UWI 3002505423		
Basic Well Data		Lea	EMC 03 East	3002303423		
Current RKB Elevation		Original RKB Elevation (ft)	Latitude (°)	Longitude (°)		
			()			
Daily Operations						
Start Date	Summary					
8/5/2022		Reviewed JSa, checked well for pressure, realized the intermedaite casing had a vavle that was non-functioning, so crew dug down to casing and never found a second valve, crew backfilled and moved wells.				
8/10/2022		Review JSA, ahdn dig and expose risers, use backhoe to slough off soil, new risers in stalled on production, intermediate was T'ed due to plug, and surface will need to be tapped by Cudd. Crew started breaking out concrete pad and shut down.				
8/11/2022	Review JSA, cor	Review JSA, continue breaking cocnrete, back fill hole, grade location and move to next well.				
8/25/2022	Review JSA, hav	e CUdd hot tap risers, bleed pro	essure, dig and install new riser, grade loc	ation.		
12/12/2022	Review JSA // R	eview Road rig requirements // I	Road WSU & P&A Equipment From LSAU	I 39 to LSAU 38// RU WSU.		
12/13/2022		Held safety meeting with crew. Pumped 165 bbls of 10 ppg brine water to kill the well. R/U TBG equip. Release on/off tool. TOH laying down 139 jts 2-3/8" EUE TBG. RIH with GR and tag packer at 4530'. Shut in well and secure location. SDFN.				
12/14/2022	Review JSA // R	U WireLine Unit // Set CIBP @ 4	45+- // RD WL // Load CSG // Test // RD W	/SU // Move To LSAU 23		
1/20/2023		Held safety meeting with crew. R/U CT. PT. TH and tagged CIBP @ 4484'. Spotted 58 bbls MLF. Spotted 47 sks. TOH Spotted 27 sks. TOH. Spotted 27 sks. TOH to surface. WOC over night.				
1/21/2023		Held safety meeting with crew. R/U CT, PT, Bubble tested, Failed Bubble test on Intermediate and Surface Casing. RIH with 1.50" CT to 2120'. Spot 37 sacks Class C cement from 2120' to 1884, POOH to Surface. Flush Eq RDMO				
2/16/2023		Review JSA, Spot In Wireline Crane, Spot In Wireline Loggin Unit, Check PSI, RU, RIH tag TOC @ 1815, CBL OOH to Surface, RD Loggin Unit and Equipment, Prep Surface with Serfice Crew				
7/1/2023	Move rig and equ	uipment. MIRU.				
7/6/2023	N/D wellhead. N/ N/U wellhead.	N/D wellhead. N/U BOPE and pressure test. RIH with tubing. Spot MLF from TOC 1,815'-800'. POOH. Cut 7" casing @ 800'. N/D BOP. N/U wellhead.				
7/7/2023	Spear casing, unland and lay down. RIH to 850'. Spot 50 sxs 14.8 ppg class C cement 1.32 yield from 850'-764'. POOH. Set 9-5/8" packer @ 30'. Shut in well.					
7/9/2023	HSM. Pressure test well. Release packer. Tag TOC @ 689'. Set CIBP @ 688'. Perform CBL from 688' to surface. Perf casing at 680'. RIH with packer to 280'. Cement squeeze 53 sxs class C cement 14.8 ppg 1.32 yield. Displace 17 bbls. Release packer pull up to 30' and set. SNFN.					
7/10/2023		HSM. Check pressures. Tag TOC at 469'. TOH. Cut at 400'. N/D 13" wellhead.				
7/11/2023		Lay down casing. Spot cement inside stub 65 sxs class c cement 14.8 ppg 1.32 yield from 450'-298'. WOC. Tag plug @ 350'. Bubble test failed. Upgrade Cement plug from 350'-247' w/ 60 sx Class C. TOH.				
7/12/2023	SM, TOC @ 250	', circulate well clean. POOH, B	ubble test failed, attempt to run scraper. u	nable to get in the Well-head.		
7/13/2023	No activity at we	I site				
7/14/2023	MIRU Nu-Wave,	Cut and remove WH, RIH casir	ng w/ Casing Scraper to ensure it will go.			
7/17/2023	Hydrovac down o	Hydrovac down cellar to cement base of cellar . RIH w/ scraper to 240', circulate well bore clean. TOH, RIH w/ CIBP Set @ 237' . Spot 25 sks Class C cmt plug on top of CIBP f/ 237'-199', TOH & SDFN.				
7/18/2023	Perform Successful bubble test, RIH Tag TOC @ 195, Spot 125 sks Class C cmt plug no displacement f/ 195'-16' (top of 13" casing), TOH, RDMO.					

## As Plugged Wellbore Diagram



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
CHEVRON U S A INC	4323
6301 Deauville Blvd	Action Number:
Midland, TX 79706	242155
	Action Type:
	[C-103] Sub. Plugging (C-103P)
CONDITIONS	

## Created By Condition None - Well P&A'd 7/18/23 john.harrison

Page 4 of 4

Action 242155

Condition Date

7/25/2023