

District 2-Artesia

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Artesia District Office

**BRADENHEAD TEST REPORT**

Operator Name <b>Delek Logistics</b>	API Number <b>30-D15-45033</b>
Property Name <b>Dark Canyon Fee SWD</b>	Well No. <b>#1</b>

**2. Surface Location**

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
	<b>23</b>	<b>23S</b>	<b>26E</b>	<b>100 S</b>	<b>S</b>	<b>958</b>	<b>E</b>	<b>EDDY</b>

**Well Status**

TA'D WELL YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input checked="" type="radio"/> NO <input type="radio"/>	INJECTOR INJ <input type="radio"/> SWD <input checked="" type="radio"/>	PRODUCER OIL <input type="radio"/> GAS <input type="radio"/>	DATE <b>8-18-2023</b>
--	--	--	---	--------------------------

**OBSERVED DATA**

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	/	0	0
<b>Flow Characteristics</b>					
Puff	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	CO2 <input type="checkbox"/>
Steady Flow	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y / N	<input checked="" type="radio"/> Y / N	Y / N	<input checked="" type="radio"/> Y / N	Type of Fluid
Gas or Oil	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	Injected for
Water	<input checked="" type="radio"/> Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

tests Performed after workover  
no Pressure on tubing

Signature: <b>Brian O'Neill</b>		OIL CONSERVATION DIVISION	
Printed name: <b>Brian O'Neill</b>			
Title: <b>Sr. manager</b>		Entered into RBDMS	
E-mail Address: <b>brian.o'dell@DelekLogistics.com</b>		Re-test	
Date: <b>8-18-2023</b>	Phone: <b>970-930-5868</b>		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 254490

CONDITIONS

Operator: DKL Field Services, LLC 310 Seven Springs Way Brentwood, TN 37027	OGRID: 372603
	Action Number: 254490
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
mgebremichael	None	8/25/2023