

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

| | |
|---|-----------------------------------|
| Operator Name <i>Apache Corporation</i> | API Number <i>30-015-46526</i> |
| Property Name <i>Palmillo 20 State Com</i> | Well No. <i>243H</i> |

| Surface Location | | | | | | | | |
|----------------------|----------------------|------------------------|---------------------|--------------------------|----------------------|-------------------------|----------------------|-----------------------|
| UL - Lot <i>E</i> | Section <i>21</i> | Township <i>19S</i> | Range <i>28E</i> | Feet from <i>1945</i> | N/S Line <i>N</i> | Feet From <i>370</i> | E/W Line <i>W</i> | County <i>Eddy</i> |

Well Status

| | | | | | | | | | | | | |
|---|-----------|----|-----|---------|----|-----|----------|-----|---|----------|-----|--------------------------|
| <input checked="" type="checkbox"/> YES | TA'D WELL | NO | YES | SHUT-IN | NO | INJ | INJECTOR | SWD | <input checked="" type="checkbox"/> OIL | PRODUCER | GAS | DATE <i>6/15/2023</i> |
|---|-----------|----|-----|---------|----|-----|----------|-----|---|----------|-----|--------------------------|

OBSERVED DATA

| | (A)Surface | (B)Interm(1) | (C)Interm(2) | (D)Prod. Casing | (E)Tubing |
|----------------------|------------|--------------|--------------|-----------------|---------------|
| Pressure | <i>0</i> | <i>N/A</i> | <i>N/A</i> | <i>N/A</i> | <i>N/A</i> |
| Flow Characteristics | | | | | |
| Puff | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | CO2 |
| Steady Flow | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | WTR |
| Surges | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | GAS |
| Down to nothing | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | Type of fluid |
| Gas or Oil | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | Injected for |
| Water | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | <i>Y/N</i> | Waterflood if |
| | | | | | applies |

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

*well not completed, is in T/A status
only surface pipe is present*

| | |
|-----------------|---------------------------|
| Signature: | OIL CONSERVATION DIVISION |
| Printed name: | Entered into RBDMS |
| Title: | Re-test |
| E-mail Address: | |
| Date: | Phone: |
| Witness: | <i>[Signature]</i> |

INSTRUCTIONS ON BACK OF THIS FORM

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 230169

CONDITIONS

| | |
|---|--|
| Operator: APACHE CORPORATION 303 Veterans Airpark Ln Midland, TX 79705 | OGRID: 873 |
| | Action Number: 230169 |
| | Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| kfortner | None | 9/18/2023 |