

Well Name: LINDRITH B	Well Location: T24N / R3W / SEC 11 / SWSW / 36.329525 / -107.131781	County or Parish/State: RIO ARRIBA / NM
Well Number: 96	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMSF078912	Unit or CA Name:	Unit or CA Number:
US Well Number: 3003925723	Well Status: Abandoned	Operator: HILCORP ENERGY COMPANY

Subsequent Report

Sundry ID: 2630543

Type of Submission: Subsequent Report

Date Sundry Submitted: 08/25/2021

Date Operation Actually Began: 08/06/2021

Type of Action: Reclamation

Time Sundry Submitted: 01:31

Actual Procedure: Final reclamation was completed on 8/6/2021 for the subject plugged and abandoned location. A reclamation inspection was conducted on 8/19/2021 with BLM inspector Lucas Vargo and received approval for the reclamation BMPs on the subject well.

SR Attachments

Actual Procedure

Lindrith_B_96_Signed_RCC_Form_20210825133050.pdf

Well Name: LINDRITH B	Well Location: T24N / R3W / SEC 11 / SWSW / 36.329525 / -107.131781	County or Parish/State: RIO ARRIBA / NM
Well Number: 96	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMSF078912	Unit or CA Name:	Unit or CA Number:
US Well Number: 3003925723	Well Status: Abandoned	Operator: HILCORP ENERGY COMPANY

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: KANDIS ROLAND	Signed on: AUG 25, 2021 01:30 PM
Name: HILCORP ENERGY COMPANY	
Title: Operation Regulatory Tech	
Street Address: 382 Road 3100	
City: Farmington	State: NM
Phone: (505) 599-3400	
Email address: kroland@hilcorp.com	

Field Representative

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: DAVE J MANKIEWICZ	BLM POC Title: AFM-Minerals
BLM POC Phone: 5055647761	BLM POC Email Address: DMANKIEW@BLM.GOV
Disposition: Approved	Disposition Date: 09/03/2021
Signature: Dave Mankiewicz	

RCC Reclamation Completion		Location Name: LINDRITH B UNIT 96		Date:		Revision 3 (3/21/17)	
API#: 3003925723		UL-Sec-Twn-Rng: D 11 024N 003W		Lat/Long: 36.329509, -107.13114 NAD 27			
Surface Owner:		Lease#: NMSF078912		County/State: RIO ARriba, NM			
Pipeline Owner: ENT		Twin/Co-Locate Well Name & Operator:					
Onsite:	Agency Inspector:	Contractor:	Seed Mix:	Remediation			
Bryan Hall	Juan Valero	Rosenbaum	Specified by Agency See RTT table				
Interim Reclamation	Final Reclamation	Completed	Incomplete	Completed	Incomplete	Completed	Incomplete
Have pit sample results been approved	3rd party pipeline removed	✓		Facilities stripped			
Has water been removed from pit	Anchors removed	✓		Certificate of waste issued & approved			
Have pit marker photos been taken	Equipment and piping removed	✓		Depth:			
Has certificate of waste been issued & approved	Power poles removed	✓		Width:			
Have all pit contents been removed	Cathodic protection removed	✓		Length:			
Has sample after content removal been taken	Vegetative cages removed	✓		Date of Excavation Start:			
Is location contoured	CMP's removed	✓		Date of Excavation End:			
Is there 4' of cover over pit	Non native gravel buried or removed	✓		Date of Backfill Start:			
Has top soil been spread evenly	Noxious weeds removed or sprayed	✓		Date of Backfill End:			
Has all non-native gravel been buried or removed	Invasive weeds removed or sprayed	✓		Yards Hauled Out:			
Has pit liner been removed	Contouring complete	✓		Impacted Soil Hauled To:			
Has all trash been removed	Top soil spread	✓		Yards Hauled In:			
Have all weeds been removed	Diversion clean and functional	✓		Fresh Soil Hauled In From:			
Teardrop allows vehicle access to all facilities	Silt trap clean and functional	✓		Approval to backfill			
Drainage ditches allow adequate run off	Cattle guard / gates removed	✓		Back fill mechanically compacted			
All non-traffic areas disked properly	Cellar / mouse hole covered	✓		Facilities reset			
All non-traffic areas seeded	Erosion under control	✓		Trash and debris removed			
Seeded areas have been mulched	Location properly ripped	✓		Close Out Completed			
Noxious weeds have been removed or sprayed	Location properly disked	✓		Soil Removal Sundry Ready to be Filed			
Invasive weeds have been removed or sprayed	Location seeded	✓					
Barriers set to deter traffic	Photo transect installed	✓					
Silt traps are functional	Access road properly closed	✓					
Culverts are functional	Public use controlled	✓					
Upper diversion is functional	Barriers in place	✓					
Erosion under control	Grazing controlled	✓					
Photo transect installed	P&A marker installed & legible	✓					
Have wellhead cages and jersey barriers been removed	Well sign removed	✓					
Have reclamation pictures been taken	Growth at least 70%	✓					
Growth at least 70%	Trash and debris removed from location	✓					
Agency Inspection Date:	Final reclamation photos taken	✓					
Sundry is ready to file	Agency Inspection Date: 8-19-21	✓					
	FAN Ready to be filed	✓					
Comments:	Comments:	Final Reclamation complete. Wait on 2-yr growth. Bryan Hall					

Hilcorp Energy

Lindrith B 96

36.329509, -107.13114

API-30-039-25723

JNMSF078912

Final Reclamation Plan

Onsite completed on 4/01/2021

1. Pick up and remove all trash, metal, cable, and any foreign debris within 200' of location.
2. Remove pipe from meter run.
3. Rip Rabbit Brush and push into toe of fill and bury.
4. Re-contour pad to re-create natural terrain. Push material from the three sides towards the middle of location to recreate natural terrain.
5. Build silt trap on the east side of location.
6. Cut diversion ditch between location and road.
7. Rip compacted soil, and leave ripped
8. Re-seed all disturbed areas. Drill where applicable at rate per acre defined by seed mix, broadcast seed where needed at double the rate, all other disturbed areas. Seed mix specified by BLM will be used.



Common name

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 46720

CONDITIONS

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 46720
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclure	ACCEPTED FOR RECORD	9/28/2023