

Well Name: BAMBOOZLED BBX FEDERAL COM	Well Location: T21S / R24E / SEC 3 / SESE /	County or Parish/State: EDDY / NM
Well Number: 2	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM107360	Unit or CA Name: BAMBOOZLED BBX FED COM 2	Unit or CA Number: NMNM114185
US Well Number: 300153288500X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Subsequent Report

Sundry ID: 2739126

Type of Submission: Subsequent Report

Date Sundry Submitted: 07/03/2023

Date Operation Actually Began: 12/20/2021

Type of Action: Reclamation

Time Sundry Submitted: 09:05

Actual Procedure: P&A Reclamation and re-seeding was completed on 12/20/2021. Please see attached Surface Reclamation Complete Report. EOG will conduct annual monitoring beginning in 2024 and will submit a sundry advising of the status of reclamation success. Upon meeting BLM's success criteria, a Final Abandonment Notice will be submitted.

SR Attachments

Actual Procedure

BAMBOOZLED_BBX_FEDERAL_COM_2_CRR_2023_6_29_20230703090420.pdf

Received by OCD: 8/8/2023 3:51:15 PM

Well Name: BAMBOOZLED BBX
FEDERAL COM

Well Location: T21S / R24E / SEC 3 /
SESE /

County or Parish/State: EDDY /
NM

Well Number: 2

Type of Well: CONVENTIONAL GAS
WELL

Allottee or Tribe Name:

Lease Number: NMNM107360

Unit or CA Name: BAMBOOZLED BBX
FED COM 2

Unit or CA Number:
NMNM114185

US Well Number: 300153288500X1

Well Status: Abandoned

Operator: EOG RESOURCES
INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA

Signed on: JUL 03, 2023 09:05 AM

Name: EOG RESOURCES INCORPORATED

Title: Regulatory Specialist

Street Address: 104 SOUTH FOURTH STREET

City: ArtesiaState: NM

Phone: (575) 748-4168

Email address: tina_huerta@eogresources.com

Field

Representative Name:

Street Address:

City:State:Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: JAMES A AMOS

BLM POC Title: Acting Assistant Field Manager

BLM POC Phone: 5752345927

BLM POC Email Address: jamos@blm.gov

Disposition: Accepted

Disposition Date: 08/08/2023

Signature: James A Amos



Surface Reclamation Complete Report

Well Name: BAMBOOZLED BBX FEDERAL COM #002

API: 30-015-32885

Well Location: P-3-21S-24E

Surface Owner: BLM



Date & Time: Thu Jun 22 15:08:54 MDT 2023
Position: +032.50462° / -104.48060°
Altitude: 1208m
Datum: WGS-84
Azimuth/Bearing: 323° N37W 5742mils (True)
Zoom: 1X
C. Peterson



On-Site Regulatory Reclamation Inspection		Date:	6/22/23	
Site Name: <u>BAMBOOZLED BBX FEDERAL COM #002</u>				
API Number: <u>30-0 15 32885</u>		Plug Date: <u>5/1/21</u>		Inspection: <input type="checkbox"/> Initial <input type="checkbox"/> Monitoring <input type="checkbox"/> Active <input type="checkbox"/> Corrective <input type="checkbox"/> Final
<input type="checkbox"/> Facility Site-No associated well on location				
Was this the last remaining or only well on the location?			YES	NO
Are there any abandoned pipelines that are going to remain on the location?				
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?				X
If any production equipment or structure (including 3rd party) is to remain on location, please specify.				
Site Evolution				
Recontoured back to original State/Topsoil Replaced			YES	NO
Have the rat hole and cellar been filled and leveled?			X	
Have the cathodic protection holes been properly abandoned & reclaimed?			X	
Rock or Caliche Surfacing materials have been removed?			X	
Section Comments:				
All Facilities Removed for Final Reclamation				
Have all of the pipelines & production equipment been cleared? (other than the listed above)			X	
Has all of the required junk and trash been cleared from the location?			X	
Have all of the required anchors, dead men, tie downs and risers have been cut off at least two feet below ground level?			X	
Have all of the required metal bolts and other materials have been removed?			X	
Have all the required portable bases been removed?			X	
Section Comments:				
Dry Hole Marker				
Has a steel marker been installed per COA requirements?			YES	NO
Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground			X	
Required DHM Information:				
<input checked="" type="checkbox"/> Operator Name <input type="checkbox"/> UL or Qst/Qtr <input checked="" type="checkbox"/> API Number <input checked="" type="checkbox"/> County <input type="checkbox"/> Federal Lease # (Fed Only)				
<input type="checkbox"/> Lease Name & Number <input checked="" type="checkbox"/> Sec-Two-Ring <input checked="" type="checkbox"/> Footage <input checked="" type="checkbox"/> P&A Date				
Free of Oil or Salt Contaminated Soil				
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?			YES	NO
Have all other environmental concerns been addressed as per OCD rules?			X	
If any environmental concerns remain on the location, please specify.				
Abandoned Pipelines				
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 28.15.35.10 NMAC).			YES	NO
Have all fluids have been removed from any abandoned pipelines?				
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?				
Have all accessible points of abandoned pipelines been permanently capped?				
Section Comments:				
Last Remaining or Only Well on the Location				
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.			YES	NO
Have all electrical service poles and lines been removed from the location?			X	
Is there any electrical utility distribution infrastructure that is remaining on the location?				X
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?			X	
Have all the retrievable pipelines, production equipment been removed from the location?			X	
Has all the junk and trash been removed from the location?			X	
Section Comments:				
Environmental Only- Do not have to be met to pass inspection				
This section corresponds with questions on the Reclamation Inspection Form in Environmental but not related to NMOC forms.				
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)			Met	Not Met
Site Stability? Erosion controls in place (if necessary) & working.			X	
Signs of seeding completion? (Broadcast/Drilled)			X	
Revegetation Success as compared to background? Met >75%.				X
Circle One: 0% <u>25%</u> 50% 75% 100%				
Adequate Reclamation Fence installed?				X
Section Comments:				
Additional Findings or Comments: <u>STEEL RISER ON SOUTHEAST CORNER OF PAD. PIPELINE RISER ALONG ACCESS ROAD.</u>				
Inspector: <u>C. PETERSON</u>				
Picture Checklist: <input checked="" type="checkbox"/> DHM <input checked="" type="checkbox"/> Background <input type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input type="checkbox"/> _____ <input checked="" type="checkbox"/> Site Corners <input checked="" type="checkbox"/> Access Road <input type="checkbox"/> EOG Equipment <input type="checkbox"/> Trash/Junk <input type="checkbox"/> _____				
<input type="checkbox"/> READY FOR FAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW Inspection Result <input checked="" type="radio"/> PASS <input type="radio"/> FAIL				

On-Site_Inspection_Form v1.xlsx

2/13/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 249814

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 249814
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclure	ACCEPTED FOR RECORD	9/29/2023