

Received by OCD: 6/19/2023 10:59:36 AM

Page 2 of 6

Well Name: PAN AM PARDUE	Well Location: T21S / R24E / SEC 27 / SESW /	County or Parish/State: EDDY / NM
Well Number: 1	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM76944	Unit or CA Name:	Unit or CA Number:
US Well Number: 300151072800X1	Well Status: Abandoned	Operator: EOG RESOURCES INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TINA HUERTA	Signed on: MAR 22, 2023 02:57 PM
Name: EOG RESOURCES INCORPORATED	
Title: Regulatory Specialist	
Street Address: 104 SOUTH FOURTH STREET	
City: Artesia	State: NM
Phone: (575) 748-4168	
Email address: tina_huerta@eogresources.com	

Field

Representative Name:		
Street Address:		
City:	State:	Zip:
Phone:		
Email address:		

BLM Point of Contact

BLM POC Name: DEBORAH L MCKINNEY	BLM POC Title: Legal Instruments Examiner
BLM POC Phone: 5752345931	BLM POC Email Address: dmckinne@blm.gov
Disposition: Accepted	Disposition Date: 06/16/2023
Signature: Deborah McKinney	



Surface Reclamation Complete Report & Annual Surface Reclamation Monitoring Report

Well Name: PAN AM PARDUE ALZ FEDERAL COM #001

API: 30-015-10728

Well Location: N-27-21S-24E

Surface Owner: BLM

Reclamation Complete Date: 3/16/22

Reclamation Annual Monitoring Date: 3/10/23

Total Acres reclaimed: 2.75 acres

Seed Mix:

Mix	Species	lb/acre (Drilled)	lb/acre (Broadcast)
BLM #3 (For Shallow Sites)	Plains Bristlegrass (<i>Setaria macrostachya</i>)	2.0	4.0
"	Green Sprangletop (<i>Leptochloa dubia</i>)	4.0	8.0
"	Sideoats Grama (<i>Bouteloua curtipendula</i>)	10.0	20.0

Weights should be as pounds of pure live seed.

Note:

EOG will conduct an annual surface reclamation monitoring field visit in 2023 to determine if successful vegetation regrowth is established.



On-Site Regulatory Reclamation Inspection		Date:	3 / 10 / 2023
Site Name: Pan Am Purdue ALZ Federal Com #001			
API Number: 30-15-10728	Plug Date: 04 / 22 / 2021	Inspection: <input type="checkbox"/> Initial <input type="checkbox"/> Monitoring <input type="checkbox"/> Active <input checked="" type="checkbox"/> Corrective <input type="checkbox"/> Final	
<input type="checkbox"/> Facility Site No associated well on location			
Was this the last remaining or only well on the location?		YES	NO
Are there any abandoned pipelines that are going to remain on the location?		✓	✓
Is there any production equipment or structure (not including steel marker, poured onsite concrete bases, or pipelines) that are going to remain on location?		✓	✓
If any production equipment or structure (including 3rd party) is to remain on location, please specify: _____			
Site Evaluation			
Recontoured back to original State/Topsoil Replaced		YES	NO
Have the rat hole and cellar been filled and leveled?		✓	✓
Have the cathodic protection holes been properly abandoned & reclaimed?		✓	✓
Rock or Caliche Surfacing materials have been removed?		✓	✓
Section Comments: _____			
All Facilities Removed for Final Reclamation			
Have all of the pipelines & production equipment been cleared? (other than the listed above)		✓	✓
Have all of the required junk and trash been cleared from the location?		✓	✓
Have all of the required anchors, dead men, tie downs and rivets have been cut off at least two feet below ground level?		✓	✓
Have all of the required metal bolts and other materials have been removed?		✓	✓
Have all the required portable bases been removed?		✓	✓
Section Comments: _____			
Dry Hole Marker			YES
Has a steel marker been installed per COA requirements?	Check One: <input type="checkbox"/> Buried <input checked="" type="checkbox"/> Above Ground	✓	NO
Required DHM Information:			
<input checked="" type="checkbox"/> Operator Name	<input checked="" type="checkbox"/> U/I or OxyGen	<input checked="" type="checkbox"/> API Number	<input checked="" type="checkbox"/> County
<input checked="" type="checkbox"/> Lease Name & Number	<input checked="" type="checkbox"/> Sec-Town-Range	<input checked="" type="checkbox"/> Footage	<input checked="" type="checkbox"/> F&A Date
<input checked="" type="checkbox"/> Federal Lease # (Fed Only)			
Free of Oil or Salt Contaminated Soil			YES
Have all the required pits been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?		✓	NO
Have all other environmental concerns been addressed as per OCD rules?		✓	✓
If any environmental concerns remain on the location, please specify: _____			
Abandoned Pipelines			
Only need to provide answers in this group, if any pipelines have been abandoned (in accordance with 29.15.35.10 NMAC).			YES
Have all fluids have been removed from any abandoned pipelines?		✓	NO
Have all abandoned pipelines been confirmed to NOT contain additional regulated NORM, other than that which accumulated under normal operation?		✗	✗
Have all accessible points of abandoned pipelines been permanently capped?		✓	✓
Section Comments: _____			
Last Remaining or Only Well on the Location			YES
Please answer all questions that apply in this group, specifically if there is no longer going to be any well or facility remaining at this location.			NO
Have all electrical service poles and lines been removed from the location?		✓	✓
Is there any electrical utility distribution infrastructure that is remaining on the location?		✓	✓
Have all the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan?		✓	✓
Have all the retrievable pipelines, production equipment been removed from the location?		✓	✓
Have all the junk and trash been removed from the location?		✓	✓
Section Comments: _____			
Environmental Only: Do not have to be met to pass inspection			
This section corresponds with questions on the Reclamation Inspection Form in Environmental but not related to NMOC forms.			Met
Free of Noxious or Invasive Weeds? (Note species or treatment in remarks)		✓	Not Met
Site Stability? Erosion controls in place (if necessary) & working.		✓	✓
Signs of seedling completion? (Broadcast/Drilled)		✓	✓
Revegetation Success as compared to background? Met >75%.	Circle One: 0% 25% 50% 75% 100%	✓	✓
Adequate Reclamation Fence Installed?		N	A
Section Comments: _____			
Additional Findings or Comments: _____			
Inspector: Igor Rios			
Picture Checklist: <input type="checkbox"/> DHM <input type="checkbox"/> Background <input type="checkbox"/> 3rd Party Equipment <input type="checkbox"/> Contamination <input checked="" type="checkbox"/> Waddies <input type="checkbox"/> Site Cones <input type="checkbox"/> Access Road <input type="checkbox"/> SOG Equipment <input type="checkbox"/> Trash/Junk		<input type="checkbox"/> READY FOR TAN SUBMITTAL <input type="checkbox"/> NEEDS FURTHER REVIEW Inspection Result: <input checked="" type="radio"/> PASS <input type="radio"/> FAIL	

On-Site_Inspection_Form v1.xlsx

2/13/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 230076

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 230076
	Action Type: [C-103] Sub. General Sundry (C-103Z)

CONDITIONS

Created By	Condition	Condition Date
dmcclure	ACCEPTED FOR RECORD	10/27/2023