

State of New Mexico
Oil Conservation Division
Hobbs District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name NGL Waste	API Number 30-025-49364
Property Name Striker 4 SWD	Well No. #1

Surface Location								
UT - Lat M	Section 24	Township 24S	Range 34E	Foot from 850	N/S Line S	Foot from 124	E/W Line W	County Lea


Well Status										
YES	YES	NO	YES	NO	INJ	SWD	OIL	PRODUCER	GAS	DATE 08/17/23

OBSERVED DATA

	IS (Surface)	(Internal)	(Choke)	At Prod. Casing	At Valve
Pressure	0			0	300
Flow Characteristics					
Full	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surge	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

Remarks - Please check for each string (A,B,C,D,E) pertinent information regarding blow down or continuous build up if applies.

MIT/BHT before Step Rate Test

Signature: 	OIL CONSERVATION DIVISION
Printed name: Gary Fisher	Entered into RDBMS
Title: VP	Re-test
E-mail Address: gfisher@popmidstream.com	
Date: 8/18/2023	
Phone: 720-315-8035	
Website:	

INSTRUCTIONS ON BACK OF THIS FORM



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 318345

CONDITIONS

Operator: NGL Waste Services, LLC 1008 Southview Circle Center, TX 75935	OGRID: 329268
	Action Number: 318345
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	3/4/2024