

South District
Phone: (575) 241-7063

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division South District

BRADENHEAD TEST REPORT

| | |
|---|-----------------------------------|
| Operator Name XTO Permian Operating LLC | API Number 30-015-40126 |
| Property Name Poker Lake Cvx JV PC | Well No. 2012 H |

| 7. Surface Location | | | | | | | | |
|----------------------|----------------------|------------------------|---------------------|------------------------|----------------------|--------------------------|----------------------|-----------------------|
| UL - Lot 0 | Section 16 | Township 24S | Range 30E | Feet from 50 | N/S Line S | Feet From 1980 | E/W Line E | County Edmr |

| TA'D Well | | SHUT-IN | | INJECTOR | | PRODUCER | | DATE |
|---|----|---|----|----------|-----|---|-----|-------------------|
| <input checked="" type="checkbox"/> YES | NO | <input checked="" type="checkbox"/> YES | NO | INJ | SWD | <input checked="" type="checkbox"/> OIL | GAS | 12/12/2023 |

| OBSERVED DATA | | | | | |
|----------------------|---|---|---------------|---|-----------------------|
| | (A) Surf-Interm | (B) Interm(1) | (C) Interm(2) | (D) Prod Csmg | (E) Tubing |
| Pressure | 13 7/8 | 8 5/8 | N/A | 5 1/2 | 2 7/8 235 Intg |
| Flow Characteristics | | | | | |
| Puff | Y / <input checked="" type="checkbox"/> N | Y / <input checked="" type="checkbox"/> N | Y / N | Y / <input checked="" type="checkbox"/> N | CO2 _____ |
| Steady Flow | Y / <input checked="" type="checkbox"/> N | Y / <input checked="" type="checkbox"/> N | Y / N | Y / <input checked="" type="checkbox"/> N | WTR _____ |
| Surges | Y / <input checked="" type="checkbox"/> N | Y / <input checked="" type="checkbox"/> N | Y / N | Y / <input checked="" type="checkbox"/> N | GAS _____ |
| Down to nothing | <input checked="" type="checkbox"/> Y / N | <input checked="" type="checkbox"/> Y / N | Y / N | <input checked="" type="checkbox"/> Y / N | If applicable type |
| Gas or Oil | Y / <input checked="" type="checkbox"/> N | Y / <input checked="" type="checkbox"/> N | Y / N | Y / <input checked="" type="checkbox"/> N | fluid injected for |
| Water | Y / <input checked="" type="checkbox"/> N | Y / <input checked="" type="checkbox"/> N | Y / N | Y / <input checked="" type="checkbox"/> N | Waterflood |

If bradenhead flowed water, check all of the descriptions that apply:

| | | | | |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Initial TA Status
 Surf **13 7/8** zero
 Inter **8 5/8** zero
 Prod **5 1/2** zero
 Tbg. **2 7/8** zero

| | |
|---|----------------------------|
| Signature: Rodolfo Rodriguez | OIL CONSERVATION DIVISION |
| Printed name: Rodolfo Rodriguez | Entered into RBDMS |
| Title: Foreman | Re-test |
| E-mail Address: Rodolfo.Rodriguez@exxamobile.com | |
| Date: 12/12/2023 | Phone: 505-670-8715 |
| Witness: David A. [Signature] | |

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 296820

CONDITIONS

| | |
|---|--|
| Operator: XTO ENERGY, INC 6401 Holiday Hill Road Midland, TX 79707 | OGRID: 5380 |
| | Action Number: 296820 |
| | Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

| | | |
|------------|-----------|----------------|
| Created By | Condition | Condition Date |
| kfortner | None | 7/18/2024 |