

Well Name: BW FEDERAL 29-29-8	Well Location: T29N / R8W / SEC 29 / NWNW / 36.702574 / -107.706084	County or Parish/State: SAN JUAN / NM
Well Number: 201	Type of Well: OTHER	Allottee or Tribe Name:
Lease Number: NMSF078046	Unit or CA Name:	Unit or CA Number:
US Well Number: 3004531181	Operator: HILCORP ENERGY COMPANY	

Subsequent Report

Sundry ID: 2803453

Type of Submission: Subsequent Report

Type of Action: Mechanical Integrity Test

Date Sundry Submitted: 07/29/2024

Time Sundry Submitted: 07:59

Date Operation Actually Began: 07/26/2024

Actual Procedure: MIT test performed on the subject well on 07/26/2024. PT to 565# for 30min, test good. Witnessed by Eileen Medrano with NMOCD. Please see attached chart. Hilcorp requests NMOCD's permission to extend the Temporarily abandoned status to review for future potential.

SR Attachments

Actual Procedure

BW_Federal_29_29_8_201___WBD_20240729075856.pdf

BHTest_07.26.2024_20240729075547.pdf

MITTest_07.26.2024_20240729075539.pdf

MITChart_07.26.2024_20240729075530.pdf

Well Name: BW FEDERAL 29-29-8

Well Location: T29N / R8W / SEC 29 / NWNW / 36.702574 / -107.706084

County or Parish/State: SAN JUAN / NM

Well Number: 201

Type of Well: OTHER

Allottee or Tribe Name:

Lease Number: NMSF078046

Unit or CA Name:

Unit or CA Number:

US Well Number: 3004531181

Operator: HILCORP ENERGY COMPANY

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TAMMY JONES

Signed on: JUL 29, 2024 07:59 AM

Name: HILCORP ENERGY COMPANY

Title: Regulatory Compliance Specialist

Street Address: 382 ROAD 3100

City: AZTEC

State: NM

Phone: (505) 324-5185

Email address: TAJONES@HILCORP.COM

Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK

BLM POC Title: Petroleum Engineer

BLM POC Phone: 5055647742

BLM POC Email Address: krennick@blm.gov

Disposition: Accepted

Disposition Date: 08/06/2024

Signature: Kenneth Rennick



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT (TA OR UIC)

Date of Test July 26, 2024 Operator Hilcorp Energy Company API # 30-0 45-31181
Property Name BW Federal 2929 8 Well # 201 Location: Unit D Sec 29 Twn 29 Rge 08W

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): Y TA Expires: _____


Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 0
Int. Casing Pres. 0

Pressured annulus up to 565 psi. for 30 mins. Test passed/failed

REMARKS: CIBP 2830' 1,000# Spring, Last Calibration date 6/27/2024
Pressured up to 565psi held entire duration of test. 565 psi end pressure

By Jose Morales (Operator Representative) Witness [Signature] (NMOCD)
Wellsite Supervisor (Position)

Revised 02-11-02





NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnr.state.nm.us/ocd/District III3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test July 26, 2024 Operator Hilcorp Energy Company API #30-0 45- 31181

Property Name BW Federal 2929 Well No. 201 Location: Unit D Section 29 Township 29N Range 08W

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Table with columns for PRESSURE (Bradenhead, INTERM) and FLOW CHARACTERISTICS (BRADENHEAD, INTERMEDIATE) across various testing times (5 min to 30 min).

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK


5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: Opsi - Nothing when opened, Opsi-5min, Opsi-10min, Opsi-15min

By Jose Manera Wellsite Supervisor (Position)

Witness

E-mail address



District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 370942

CONDITIONS

Operator: HILCORP ENERGY COMPANY 1111 Travis Street Houston, TX 77002	OGRID: 372171
	Action Number: 370942
	Action Type: [C-103] Sub. Temporary Abandonment (C-103U)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	Formation tops not on schematic - MIT required on or before 7/26/2029	8/6/2024