

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name S B K F LLC	API Number 30-015-10782
Property Name State 647 AC 721	Well No. 30-015-207

Surface Location

UL - Lot I	Section 33	Township 18	Range 20	Feet from 1980	N/S Line S	Feet from 990	E/W Line E	County Eddy
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	-----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 7-12-22
------------------	-------------------------------------	----------------	-------------------------------------	--------------------------------------	----------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure					300
Flow Characteristics					
Puff	☒ Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Isjected for
Water	Y / N	Y / N	Y / N	Y / N	Waterhead if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

some clear fluid small amount
Test good

Signature: Dan Smolik	OIL CONSERVATION DIVISION
Printed name: Dan Smolik	Entered into RBDMS
Title: Compliance Officer	Re-test
E-mail Address:	
Date: 7-12-22	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name SBE LLC	API Number 30-015-02054
Property Name State 647 AC 711	Well No. 100

1. Surface Location

UL - Lot A	Section 27	Township 18	Range 28	Feet from 330	NS Line N	Feet from 990	E/W Line E	County Fddy
----------------------	----------------------	-----------------------	--------------------	-------------------------	---------------------	-------------------------	----------------------	-----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER	GAS	DATE 7-12-22
--	--	--	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure					375
Flow Characteristics	NO Pressure				
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Test 6 Good

Signature: Dan Snolik	OIL CONSERVATION DIVISION
Printed name: Dan Snolik	Entered into RBDMS
Title: Compliance Officer	Re-test
E-mail Address:	
Date: 7-12-22	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name SBK# LLC		API Number 30-015-02053	
Property Name State 647 AC 711		Well No. 93	

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet from	E/W Line	County
				330	N	3430	E	Eddy

Well Status

TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
												7-12-22

OBSERVED DATA

	(A) Surface	(B) Interim(1)	(C) Interim(2)	(D) Prod Casing	(E) Tubing
Pressure					400
Flow Characteristics	NO Pressure				
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Isjected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Dan Sordik		OIL CONSERVATION DIVISION	
Printed name: Dan Sordik		Entered into RBDMS	
Title: Compliance officer		Re-test	
E-mail Address:			
Date: 7-12-22	Phone:		
	Witness:		

INSTRUCTIONS ON BACK OF THIS FORM

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name SIB KF LLC		API Number 30-015-06109	
Property Name Stela 647 AC 711		Well No. 84	

Surface Location

UL - Lot L	Section 27	Township 18	Range 28	Feet from 2310	N/S Line S	Feet From 330	E/W Line W	County Eddy
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	-----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER	GAS	DATE 7-12-22
--	--	--	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					350
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood %

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Test Good

Signature: Dan Smolik	OIL CONSERVATION DIVISION
Printed name: Dan Smolik	Entered into RBDMS
Title: Compliance Officer	Re-test
E-mail Address:	
Date: 7-12-22	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name S B K F LLC	API Number 30-015-02055
Property Name State 647 AC 711	Well No. 89

2. Surface Location

UL - Lot 4	Section 27	Township 18	Range 28	Feet from 2310	N/S Line S	Feet From 1650	E/W Line W	County Eddy
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	--------------------------	----------------------	-----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 7-12-22
------------------	-------------------------------------	----------------	-------------------------------------	--------------------------------------	----------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	N/A				250
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	☒ N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Test Good

Signature: Dan Smolik	OIL CONSERVATION DIVISION
Printed name: Dan Smolik	Entered into RBDMS
Title: Compliance Officer	Re-test
E-mail Address:	
Date: 7-12-22	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name SBKF LLC	API Number 30-015-02052
Property Name State 647 AC 711	Well No. 92

1. Surface Location

UL - Lot N	Section 27	Township 18	Range 28	Feet from 990	N/S Line 5	Feet From 1650	E/W Line W	County El Paso
----------------------	----------------------	-----------------------	--------------------	-------------------------	----------------------	--------------------------	----------------------	--------------------------

Well Status

TA'D WELL YES	☒ NO	YES	SHUT-IN ☒ NO	☒ INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 7-12-22
------------------	-------------------------------------	-----	--	--------------------------------------	----------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure					350
Flow Characteristics				NO Pressure	
Puff	☒ Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Isjected for
Water	Y / N	Y / N	Y / N	Y / N	Waterhead if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Test Good

Signature: Dan Smolch	OIL CONSERVATION DIVISION
Printed name: Dan Smolch	Entered into RBDMS
Title: Compliance Officer	Re-test
E-mail Address:	
Date: 7-12-22	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name S B K F	API Number 30-015-02062
Property Name Twin lakes	Well No. 7

1. Surface Location

UL - Lot m	Section 28	Township 18	Range 28	Feet from 1316	N/S Line S	Feet From 270	E/W Line W	County Eddy
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	-----------------------

Well Status

TA'D WELL YES	☒ NO	YES	SHUT-IN NO	☒ INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 7-12-22
------------------	-------------------------------------	-----	---------------	--------------------------------------	----------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					650
Flow Characteristics	OK				
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterfound if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Test good

Signature: Dmk	OIL CONSERVATION DIVISION
Printed name: Dan Smolik	Entered into RBDMS
Title: Compl. area officer	Re-test
E-mail Address:	
Date: 7-12-22	Phone:
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name S B K F LLC	API Number 36-015-02005
Property Name Mershon State	Well No. 3

1. Surface Location

UL - Lot E	Section 21	Township 18	Range 28	Feet from 2310	N/S Line N	Feet from 330	E/W Line W	County Eddy
----------------------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	-----------------------

Well Status

TA'D WELL YES ☒ NO ☒	SHUT-IN YES ☒ NO ☒	INJECTOR ☒	SWD	OIL	PRODUCER	GAS	DATE 7-12-22
---	---	--	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure					
Flow Characteristics	NO Pressure				
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Isjected for
Water	Y / N	Y / N	Y / N	Y / N	Waterfound if
					any other

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Test good

Signature: Dan Smelik	OIL CONSERVATION DIVISION
Printed name: Compliance Officer	Entered into RBDMS
Title: Dan Smelik	Re-test
E-mail Address:	
Date: 7-12-22	Phone:
	Witness:

INSTRUCTIONS ON BACK OF THIS FORM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 145344

CONDITIONS

Operator: SBKF, LLC P.O. Box 1569 Artesia, NM 88211	OGRID:
	225437
	Action Number:
	145344
Action Type:	
[UF-BHT] Bradenhead Test (BRADENHEAD TEST)	

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	9/6/2024