

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name RING ENERGY		API Number 30-025-05122	
Property Name Buckley		Well No. A-4	

7. Surface Location									
UL - Lot N	Section 25	Township 14S	Range 37E	Feet from 330'	N/S Line S	Feet From 1650'	E/W Line W	County LEA	

Well Status									
TA'D WELL ☒ YES ☐ NO		SHUT-IN ☒ YES ☐ NO		INJECTOR ☐ INJ ☐ SWD		PRODUCER ☒ OIL ☐ GAS		DATE 4-19-23	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	NR	NR	0	TA
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ☐
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☐
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	


Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

TA Status test

**ACD
ser 8149
cal 2-2-23**

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test X	
E-mail Address:			
Date:	Phone:		
Witness: Key Mte - ocd			

INSTRUCTIONS ON BACK OF THIS FORM



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 212192

CONDITIONS

Operator: Ring Energy, Inc P.O. Box 11350 Midland, TX 79702	OGRID: 328599
	Action Number: 212192
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	9/20/2024