

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name LEGACY RESERVES OPERATING LP		API Number 30-025-10381
Property Name LANGLIE MATTIX PENROSE SAND UNIT		Well No. 82

Surface Location									
UL - Lot C	Section 21	Township 22S	Range 37E		Feet from 660	N/S Line N	Feet From 1980	E/W Line W	County LEA

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 2/19/2023	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø			40	50
Flow Characteristics					
Puff	Y / Ø	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / Ø	Y / N	Y / N	Y / N	WTR ___
Surges	Y / Ø	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / Ø	Y / N	Y / N	Y / N	Injected for
Water	Y / Ø	Y / N	Y / N	Y / N	Waterflood if applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION
Printed name: I Marlon Nuñez		Entered into RBDMS
Title: PRODUCTION TECH		Re-test
E-mail Address:		
Date:	Phone:	
Witness:		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 221188

CONDITIONS

Operator: LEGACY RESERVES OPERATING, LP 1400 16th Street, Suite 510 Denver, CO 80202	OGRID: 240974
	Action Number: 221188
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	9/20/2024