

Oil and Gas Division
Oil Conservation Division
Public Display Office

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Public Display Office

BRADENHEAD TEST REPORT

Operator Name

API Number

Benton Crude Oil LLC
Langlie Mattix Queen

30-025-11 ~~000~~ 601
019

Surface Location

U/L Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
J	15	25 S	37 E	1980	S	1980	E	LEA

Well Status

YARD WELL	YES	NO	SHUT-IN	YES	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
YES		☒	YES		☒	☒						9/18/24

OBSERVED DATA

	(A) Surface	(B) Interval(1)	(C) Interval(2)	(D) Prod. Casing	(E) Tubing
Pressure	0			0	190
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	W.H. ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Disposed by
Water	Y/N	Y/N	Y/N	Y/N	Weighted by

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature

Printed name

Title

Email Address

Date

Phone


Work Email

Lang Polman

OIL CONSERVATION DIVISION

Entered into PBOMS

Re-test



OIL CONSERVATION DIVISION

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 385989

CONDITIONS

Operator: Benton Crude Oil LLC 2201 Menaul Blvd NE Ste A Albuquerque, NM 87107	OGRID: 331974
	Action Number: 385989
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
plmartinez	None	9/26/2024