

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

OKL Field	Operator Name	APL Number
Services	KLC	30-025-41703
Brady BC	Property Name	Well No. 2

Surface Location					
U.L. Loc	Section	Township	Range	East from	NS Line
I	35	20S	33E	1620	S
				Feet from	
				304	
				EAV Line	
				E	
				County	
				Lea	

Well Status					
YES	T&D WELL	NO	YES	SHUT-IN	NO
				INJ	INSPECTOR
				SWD	OIL
				PRODUCER	GAS
				DATE	
				6-13-23	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Comp	(E)Tubing
Pressure	20	0			25
Flow Characteristics					1200
Puff	Y/N	Y/N		Y/N	CO2
Steady Flow	Y/N	Y/N		Y/N	WTR
Surges	Y/N	Y/N		Y/N	GAS
Down to nothing	Y/N	Y/N		Y/N	Type of fluid
Gas or Oil	Y/N	Y/N		Y/N	Indicated for
Water	Y/N	Y/N		Y/N	Worked for
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	Key Mary	OIL CONSERVATION DIVISION
Printed name:	Key Mary	Entered into RBDMS
Title		Re-test
E-mail Address:	Key, Mackay@nmlklogistics	
Date:	6-13-23	
Phone:	575-631-8198	
Witness:		

INSTRUCTIONS ON BACK OF THIS FORM GR

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 228718

CONDITIONS

Operator: DKL Field Services, LLC 310 Seven Springs Way Brentwood, TN 37027	OGRID: 372603
	Action Number: 228718
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	9/27/2024