Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103	
Office District I – (575) 393-6161	Energy, Minerals and Natural F		Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	znoigj, minorais and matarai resources		API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIV	VISION 5 1 1	30-005-21164	
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		STATE FEE e Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		o. state	e on & das Lease No.	
	CES AND REPORTS ON WELLS	7. Leas	se Name or Unit Agreement Name	
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH		Cato San Andres Unit	
1. Type of Well: Oil Well	Gas Well Other	8. Wel	l Number 328	
2. Name of Operator Cano Petro of New Mexico, Inc.		9. OGF 2488	RID Number	
3. Address of Operator			ol name or Wildcat	
801 Cherry Street Suite 3200 Unit	25 Fort Worth, TX 76102	C-080000 20000000	Cato; San Andres	
4. Well Location				
Unit Letter M	1298 feet from the S		6_feet from theW line	
Section 9	•		MPM County Chaves	
	11. Elevation (Show whether DR, RKE 4058	, RT, GR, etc.)		
TEMPORARILY ABANDON	CHANGE PLANS COI MULTIPLE COMPL OTHe eted operations. (Clearly state all pertin k). SEE RULE 19.15.7.14 NMAC. Fo	MEDIAL WORK MMENCE DRILLING OF SING/CEMENT JOB HER: ent details, and give per r Multiple Completions:	tinent dates, including estimated date	
Spud Date:	Rig Release Date:			
I hereby certify that the information al	bove is true and complete to the best of	my knowledge and belie	ef.	
SIGNATURE: Ethan Wakefield	TITLE: Authorized	1 Representative	DATE 9/16/24	
Type or print name:Ethan Wak	efield E-mail address: e.wake	efield@dwsrigs.com	PHONE: 405-343-7736	
For State Use Only				
APPROVED BY:	TITLE		DATE	

Cano Petro Inc./NMOCD OWP

Plug And Abandonment End Of Well Report

Cato San Andres Unit #328

1298' FSL & 1306' FWL, Section 9, T8S, R30E Chaves County, NM / API 30-005-21164

Work Summary:

- 12/13/21 Made NMOCD P&A operations notifications at 9:00 AM MST.
- MOL and R/U P&A rig. Prepped location with backhoe. Checked well pressures: Tubing: 0 psi, Casing: 320 psi, Bradenhead: 0 psi. Bled down well. Removed horse's head in preparation to pull rods. Worked stuck sucker rod pump free. L/D polish rod, 128- ¾" sucker rods, and sucker rod pump. N/D wellhead, N/U BOP and function tested. Worked stuck tubing. L/D 2 8' 2-3/8" subs, 105 joints of 2-3/8" tubing, seating nipple, 4' perforated pup joint, and 1 joint of 2-3/8" tubing with bull plug. P/U casing scraper and work string and tallied in the wellbore above top perforation to a depth of 3,160'. Secured and shut-in well for the day.
- 12/15/21 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. P/U CR, TIH and set at 3,161'. Stung out of CR. R/U cementing services. Attempted to circulate wellbore with 80 bbls of fresh water but was unsuccessful. Pumped plug #1 from 3,161'-2,954' to cover the San Andres perforations and formation top. TOOH with tubing. WOC 4 hours. TIH and tagged plug #1 top at 3,155'. Tag depth was below minimum tag depth for plug #1. R/U cementing services. Re-pumped plug #1 from 3,155'-2,954' to cover the San Andres perforations and formation top. TOOH with tubing. WOC overnight. Secured and shut-in well for the day.
- 12/16/21 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. TIH and tagged plug #1 top at 3,130'. R/U cementing services. Circulated wellbore with 40 bbls of fresh water.

Attempted to pressure test production casing to 500 psi in which it failed to hold pressure. Re-pumped plug #1 from 3,130'-2,864' to cover the San Andres perforations and formation top. TOOH. WOC 4 hours. R/U wireline services. Ran CBL from top of plug #1 at approximately 2,864' to surface. CBL results were sent to NMOCD office for review. Pressure tested production casing to 500 psi in which it successfully held pressure. RIH and perforated squeeze holes at 1,490'. Attempted to establish injection rate into perforations at 1,490' but was unsuccessful. RIH and perforated squeeze holes at 1,400'. Attempted to establish injection rate into perforations at 1,400' but was unsuccessful. RIH and perforated squeeze holes at 1,000'. Attempted to establish injection rate into perforations at 1,000' but was unsuccessful. TIH and tagged plug #1 top at 2,829'. Pumped 9.5 ppg mud spacer from 2,829'-1,595'. L/D tubing up to next plug depth. TOOH with remaining tubing. Secured and shut-in well for the day.

- Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 12/17/21 psi. Bled down well. TIH with work string to 1,580'. R/U cementing services. Pumped plug #2 from 1,580'-872' to cover the Yates and Rustler formation tops. WOC 4 hours. L/D tubing up to next plug depth. TOOH with remaining tubing. TIH and tagged plug #2 top at 1,198'. R/U cementing services. Re-pumped plug #2 from 1,198'-800' to cover the Yates and Rustler formation tops. WOC 4 hours. TOOH with tubing. TIH and tagged plug #2 top at 878'. Pumped 9.5 ppg mud spacer from 878'-583'. L/D tubing to surface. R/U wireline services. RIH and perforated squeeze holes at 583'. R/U cementing services. Successfully established circulation down 5 1/2" production casing through perforations at 583' and back around and out Bradenhead valve at surface. Successfully circulated cement down 5 1/2" production casing through perforations at 583' and back around and out Bradenhead valve at surface. N/D BOP, N/U wellhead. WOC overnight. Secured and shut-in well for the day.
- 12/21/21 Checked well pressures: Tubing: 0 psi, Casing: 0 psi, Bradenhead: 0 psi. Bled down well. Dug out wellhead with backhoe. Performed wellhead cut-off. Cement was at surface in both 8-5/8" surface casing annulus and 5 ½" production casing. Installed subsurface P&A marker per NMOCD regulations. Photographed the P&A marker in place and recorded its location via GPS coordinates. Back filled P&A marker. R/D and MOL.

Plug Summary:

Plug #1:(San Andres Perforations and Formation Top 3,161'-2,829', 75 Sacks Type III Cement(Re-pumped 50 sx))

Mixed 75 sx Type III cement and spotted a balanced plug to cover the San Andres perforations and formation top.

Plug #2:(Yates and Rustler Formation Tops 1,580'-878', 110 Sacks Type III Cement(Re-pumped 40 sx))

RIH and perforated squeeze holes at 1,490'. Attempted to establish injection rate into perforations at 1,490' but was unsuccessful. RIH and perforated squeeze holes at 1,400'. Attempted to establish injection rate into perforations at 1,400' but was unsuccessful. RIH and perforated squeeze holes at 1,000'. Attempted to establish injection rate into perforations at 1,000' but was unsuccessful. TIH and tagged plug #1 top at 2,829'. Pumped 9.5 ppg mud spacer from 2,829'-1,595'. L/D tubing up to next plug depth. TOOH with remaining tubing. TIH with work string to 1,580'. R/U cementing services. Pumped plug #2 from 1,580'-872' to cover the Yates and Rustler formation tops. WOC 4 hours. L/D tubing up to next plug depth. TOOH with remaining tubing. TIH and tagged plug #2 from 1,198'-800' to cover the Yates and Rustler formation tops. WOC 4 hours. TOOH with tubing. TIH and tagged plug #2 top at 878'.

Plug #3: (Surface Casing Shoe 583'-Surface, 186 Sacks Type III Cement)

RIH and perforated squeeze holes at 583'. R/U cementing services. Successfully established circulation down 5 ½" production casing through perforations at 583' and back around and out Bradenhead valve at surface. Successfully circulated cement down 5 ½" production casing through perforations at 583' and back around and out Bradenhead valve at surface. N/D BOP, N/U wellhead. WOC overnight. Dug out wellhead with backhoe. Performed wellhead cutoff. Cement was at surface in both 8-5/8" surface casing annulus and 5 ½" production casing. Installed subsurface P&A marker per NMOCD regulations. Photographed the P&A marker in place and recorded its location via GPS coordinates. Back filled P&A marker. R/D and MOL.

Wellbore Diagram

Cato San Andres Unit #328 API #: 30-005-21164 Chaves County, New Mexico

Plug 3

583 feet - Surface 583 feet plug 186 sacks of Type III Cement

Plug 2

1580 feet - 878 feet 702 feet plug 110 sacks of Type III Cement 40 sacks re-pumped

Plug 1


3161 feet - 2829 feet 332 feet plug 75 sacks of Type III Cement 50 sacks re-pumped

> Perforations 3224 ft - 3250 ft


Surface Casing

8.625" 24# @ 533 ft


Formation San Andres - 2474 ft



Production Casing 5.5" 15.5# @ 3444 ft







District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 383882

CONDITIONS

Operator:		OGRID:
	CANO PETRO OF NEW MEXICO, INC.	248802
	801 Cherry Street	Action Number:
	Fort Worth, TX 76102	383882
		Action Type:
		[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By		Condition Date
samuel.romero	Operator must submit a C-103Q within one year from plugging date in order for OCD to perform a site inspection.	10/2/2024