



BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/6/23 Operator Maralex Resources API #30-045- 28524
Property Name GASS Well No. #3 Location: Unit H Section 08 Township 27N Range 15W
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate - Casing 34 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	0		34		
10 min	0		34		
15 min	0		34		
20 min	0		34		
25 min	0		34		
30 min	0		34		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH ✓ SALTY ✓ SULFUR ✓ BLACK ✓

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE ✓

REMARKS:

Puff when BH opened

By J. M. Ortega

Witness _____

Mechanic (Pumper)
(Position)

E-mail address amo@maralexinc.com

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 381622

CONDITIONS

Operator: MARALEX RESOURCES INC P.O. Box 338 Ignacio, CO 81137	OGRID: 13998
	Action Number: 381622
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	None	10/3/2024