

**State Of New Mexico**  
**Energy, Minerals and Natural Resources Department**

31-Oct-24

**HUNT CIMARRON LIMITED PARTNERSHIP**

**Pre Enforcement Notification**

P.O. Box 1592  
Roswell, NM 882021592

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

*INSPECTION DETAIL SECTION*

[30-005-00433] ANCHOR DEEP UNIT #001

OGRID: 164726

K-09-14S-29E 1974 FSL 1988 FWL

Inspection Date	Type Inspection	Inspector	Inspection No.
10/31/2024	Routine Inspection	[RZH] Ronald Heuer	iRZH2430531850
Violation	Title		Corrective Action Due
cRZH2430558237	19.15.16.8 Sign on Wells Inaccurate Information <i>(Current owner information and API are missing from the well sign. Well name is incomplete on the well sign.)</i>		1/29/2025
cRZH2430558238	19.15.10.8 Safety Procedures for Drilling and Production Substandard Equipment and/or Needs Repair <i>(Chemical tank secondary containments need coverings. Two of the containments have either liquid or sludge in them.)</i>		1/29/2025
cRZH2430558239	19.15.18.16 Tanks, Oil Tanks, Fire Walls and Tank Identification Noncompliance with Requirements (Construction, Operations or Closure) <i>(Tank battery pit liner needs repairs.)</i>		1/29/2025
cRZH2430558240	19.15.10.8 Safety Procedures for Drilling and Production General Housekeeping Required <i>(Contaminated soil mound on location needs to be cleaned up per rule.)</i>		1/29/2025
cRZH2430558241	19.15.18.16 Tanks, Oil Tanks, Fire Walls and Tank Identification Tank identification missing or needs repaired <i>(Tank battery is missing its identification sign.)</i>		1/29/2025

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division \* 506 W. Texas Ave. \* Artesia, NM 88210  
Phone: 505-476-3441 \* Fax: 575-748-9720 \* [www.emnrd.nm.gov](http://www.emnrd.nm.gov)