
eceined by OCD: 8/9/2023 10:45:12	State of New Mexico	Form C-103 <sup>1</sup> of		
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240	-	WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-32324		
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease  STATE ☐ FEE ☒		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM				
87505 SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLI	Artesia Gas Plant Duke AGI			
·	PROPOSALS.)  1. Type of Well: Oil Well ☐ Gas Well ☐ Other: Acid Gas Injection ☒			
2. Name of Operator	out with a control out injection	9. OGRID Number 36785		
DCI	P Midstream LP			
3. Address of Operator	. The Co.	10. Pool name or Wildcat		
	17 <sup>th</sup> Street, Suite 2500, Denver, CO 80202	AGI - Devonian		
4. Well Location				
Unit Letter <u>K</u> : <u>1232</u>	feet from the South line and 1927 feet from the			
Section 7	Township 18S Range 28E NMPN			
	11. Elevation (Show whether DR, RKB, RT, GR, et	tc.): 3736 GR		
12. Check	Appropriate Box to Indicate Nature of Notice	e, Report or Other Data		
NOTICE OF IN	ITENTION TO:	DOEOLIENT DEDORT OF		
NOTICE OF IN PERFORM REMEDIAL WORK ☐	NTENTION TO: SU  PLUG AND ABANDON □ REMEDIAL WO	BSEQUENT REPORT OF:  ORK ALTERING CASING		
TEMPORARILY ABANDON		RILLING OPNS. P AND A		
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	<del>_</del>		
DOWNHOLE COMMINGLE	MOLTIFLE COMFL CASING/CLIME	.N1 30B		
CLOSED-LOOP SYSTEM				
OTHER:	OTHER: (Mech	anical Integrity Test)		
	pleted operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date		
	ork). SEE RULE 19.15.7.14 NMAC. For Multiple C			
proposed completion or rec	completion.			
The mechanical integrity test (M	(IT) was conducted on Wednesday, April 26, 202	23. Barbara Lydick (NMOCD) was on-site		
	and bradenhead test (BHT). Below is a step-by-			
**	• •	•		
	ure between the production casing and tubing wa			
	gas (TAG) was being injected at 774 MCF, with			
	mp truck and a calibrated chart recorder were att			
	ges. The annular pressure valve was opened and slowly added from the pump truck to achieve the			
	ed from the truck and the MIT began at 12:07 pm			
	nnular pressure until 12:47 pm (40 minutes). Die			
	ecorder. An operating pressure of 290 psi was le			
	ilus pressure dropped from 610 to 580 psi; a decr			
final 20 minutes.	ius pressure dropped from 010 to 300 psi, a deer	ease of 30 psi (4.5%) and was stable for the		
The intermediate and surface case	sing remained at 191 and 5 psi respectively throu	ghout the MIT.		
The approved MIT pressure char	t, BHT results, and chart recorder calibration she	eet are attached.		
I hereby certify that the information	above is true and complete to the best of my knowled	dge and belief.		
SIGNATURE Dale T Lim	Ench. TITLE Consultant to DCI	D.M. detroom DATE 4/06/0002		
Type or print name <u>Dale T Littlej</u>	tiol. TITLE Consultant to DCI ohn E-mail address: dale@geole			
For State Use Only	D-man address, date & geore	1 HONE. (303) 042-0000 .		
<del></del>				
APPROVED BY:	TITLE	DATE		
Conditions of Approval (if any):				



### State of New Mexico

## Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

		BRADENHEAD TE		ice		
	Operator	200001		200	APINum	202011
		roperty Name		20.0	115	Vell No.
Dule HGI					- North and Control	)
<sup>1</sup> Surface Location						
UL-Lot Section To	Range Range	Feet from 1232	N/S Line	Feet From	E/W Line	- Gounty
Well Status						
YES TA'D WELL NO	YES SHUT-IN	NO INJ INJECTOR	OIL PRO	DUCER GAS	1 , ,	DATE
hundan hand	A D	GI Well OBSERVED D	1	eorlace just	ter stor	126/2025
	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod C	sng	(E)Tubing
Pressure	5	191		10		1781
Flow Characteristics	monitored	And the second second		10		1/01
Puff	YIN	Monitored	Y/N/	Y	(N)	CO2
Steady Flow	Y/N	Y/N	YIN		/(N)	WTR_
Surges	Y/N	Y/N	YIN		N	GAS ACI
Down to nothing	Y/N	Y/N	Y/N	0	/ N	Tajected for
Gas or Oil	Y/N	Y/N	YIN	Y	1 (N)	Waterflood 9' applies
Water	Y/N	Y/N	Y/N	Y	/(N)	
Remarks-Please state for each PCP AGI B				sunt ive open lo se or findes		
Signature:		is this last holiand				ON DIVISION
Printed name:		THE RESIDENCE PROPERTY.	Entered into RBDMS			
Title:			Re-te	est		
E-mail Address:	Dhan					
Date:	Phone:	20 III				- CAMPON NAMED AND ADDRESS OF THE PARTY OF T
	Witness:	DAVE John!			A	

INSTRUCTIONS ON BACK OF THIS FORM

## MACLASKEY FIELD SERVICES

5900 WEST LOVINGTON HWY. HOBBS, N.M. 88240 565-393-1016

THIS IS TO CERTIFY THAT	DATE 3-14-23
LABORROUS METER TE SERVICES, INC. HAS CHECKED TO INSTRUMENT.	ECHNICAN FOR MACLASKEY OILFIELD  E CALIBRATION ON THE FOLLOWING  /DO PRESSURE RECORDER
	SERIAL NUMBER 500 9150 16
TESTED AT THESE POINT  PRESSURE SOO  TEST AS FOUND CORRECTED  O (00 )  (	S.  PRESSURE /000  TEST AS FOUND CORRECT  S00 600  200 900  \$00 /
REMARKS:	

SIGNED: Acut Leducy

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 250056

#### **CONDITIONS**

Operator:	OGRID:
DCP OPERATING COMPANY, LP	36785
2331 Citywest Blvd	Action Number:
Houston, TX 77042	250056
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

### CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/26/2024